

Client:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

VERINA CONSULTING GROUP, LLC Date Collected: 11/07/24

Project: Rotor Clip - PO# 5183.0001 Date Received: 11/07/24

Client Sample ID: Water Treatment Discharge SDG No.: P4763

Lab Sample ID: P4763-01 Matrix: Water

Level (low/med): low % Solid: 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-47-3	Chromium	47.6		1	0.66	5.00	ug/L	11/08/24 12:30	11/11/24 16:30	SW6010	SW3010
7440-50-8	Copper	14.7		1	7.07	10.0	ug/L	11/08/24 12:30	11/11/24 16:30	SW6010	SW3010
7440-02-0	Nickel	18.4	J	1	0.85	20.0	ug/L	11/08/24 12:30	11/11/24 16:30	SW6010	SW3010
7440-66-6	Zinc	88.2	N	1	1.75	20.0	ug/L	11/08/24 12:30	11/11/24 16:30	SW6010	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group4

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference. OR = Over Range

N =Spiked sample recovery not within control limits