

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: VERINA CONSULTING GROUP, LLC Date Collected: 12/05/24 Project: Rotor Clip - PO# 5183.0001 Date Received: 12/05/24 Client Sample ID: WATER TREATMENT DISCHARGE SDG No.: P5141 P5141-01 Lab Sample ID: Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-43-9	Cadmium	0.094	U	1	0.094	3.00	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010
7440-47-3	Chromium	359		1	0.66	5.00	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010
7440-50-8	Copper	10.3		1	7.07	10.0	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010
7439-92-1	Lead	3.51	U	1	3.51	6.00	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010
7440-02-0	Nickel	55.8		1	0.85	20.0	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010
7440-22-4	Silver	0.58	U	1	0.58	5.00	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010
7440-66-6	Zinc	573		1	1.75	20.0	ug/L	12/09/24 09:10	12/10/24 12:57	SW6010	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group5

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits