284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QCBatch ID # VX060625

Review By	Mahesh Dadoda	Review On	6/9/2025 1:15:21 PM		
Supervise By	Semsettin Yesilyurt	Supervise On	6/9/2025 1:19:58 PM		
SubDirectory	VX060625	HP Acquire Method		HP Processing Method	82X060625W.M

STD. NAME	STD REF.#
Tune/Reschk	VP134153
Initial Calibration Stds	VP134235,VP134236,VP134237,VP134238,VP134239,VP134240
CCC	VP134154
Internal Standard/PEM	
ICV/I.BLK	VP134241
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

Sr#	SampleId	Data File Name	Date-Time	Operator	Status
1	BFB	VX046516.D	06 Jun 2025 08:47	JC/MD	Ok
2	VSTDICC001	VX046517.D	06 Jun 2025 09:13	JC/MD	Not Ok
3	VSTDICC005	VX046518.D	06 Jun 2025 09:42	JC/MD	Ok,M
4	VSTDICC020	VX046519.D	06 Jun 2025 10:18	JC/MD	Ok,M
5	VSTDICCC050	VX046520.D	06 Jun 2025 10:40	JC/MD	Ok,M
6	VSTDICC100	VX046521.D	06 Jun 2025 11:02	JC/MD	Ok,M
7	VSTDICC150	VX046522.D	06 Jun 2025 11:25	JC/MD	Ok,M
8	IBLK	VX046523.D	06 Jun 2025 11:47	JC/MD	Ok
9	VSTDICC001	VX046524.D	06 Jun 2025 12:57	JC/MD	Ok,M
10	VSTDICV050	VX046525.D	06 Jun 2025 14:11	JC/MD	Ok,M
11	VX0606MBL01	VX046526.D	06 Jun 2025 14:39	JC/MD	Ok
12	VX0606WBL01	VX046527.D	06 Jun 2025 15:02	JC/MD	Ok
13	VX0606WBS01	VX046528.D	06 Jun 2025 15:25	JC/MD	Ok,M
14	VX0606MBS01	VX046529.D	06 Jun 2025 15:51	JC/MD	Ok,M
15	Q2168-11MEDL	VX046530.D	06 Jun 2025 16:13	JC/MD	Ok
16	VX0606WBSD01	VX046531.D	06 Jun 2025 16:36	JC/MD	Ok,M
17	Q2194-02	VX046532.D	06 Jun 2025 16:58	JC/MD	Ok
18	Q2194-04	VX046533.D	06 Jun 2025 17:21	JC/MD	Ok
19	Q2207-09	VX046534.D	06 Jun 2025 17:43	JC/MD	Ok,M
20	Q2207-18	VX046535.D	06 Jun 2025 18:06	JC/MD	Ok,M
21	Q2207-27	VX046536.D	06 Jun 2025 18:28	JC/MD	Ok,M

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QCBatch ID # VX060625

Review By	Mahesh Dadoda	Review On	6/9/2025 1:15:21 PM		
Supervise By	Semsettin Yesilyurt	Supervise On	6/9/2025 1:19:58 PM		
SubDirectory	VX060625	HP Acquire Method		HP Processing Method	82X060625W.M

STD. NAME	STD REF.#
Tune/Reschk	VP134153
Initial Calibration Stds	VP134235,VP134236,VP134237,VP134238,VP134239,VP134240
CCC	VP134154
Internal Standard/PEM	
ICV/I.BLK	VP134241
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

22	Q2207-36	VX046537.D	06 Jun 2025 18:51	JC/MD	Ok,M
23	Q2207-45	VX046538.D	06 Jun 2025 19:13	JC/MD	Ok,M
24	Q2208-09	VX046539.D	06 Jun 2025 19:35	JC/MD	Ok,M
25	Q2208-18	VX046540.D	06 Jun 2025 19:58	JC/MD	Ok,M
26	Q2208-27	VX046541.D	06 Jun 2025 20:20	JC/MD	Ok,M
27	Q2208-36	VX046542.D	06 Jun 2025 20:42	JC/MD	Ok,M
28	Q2236-01	VX046543.D	06 Jun 2025 21:04	JC/MD	Not Ok
29	VSTDCCC050	VX046544.D	06 Jun 2025 21:26	JC/MD	Not Ok
30	BFB	VX046545.D	06 Jun 2025 23:59	JC/MD	Ok
31	VSTDCCC050	VX046546.D	07 Jun 2025 00:34	JC/MD	Ok,M
32	VX0606WBL02	VX046547.D	07 Jun 2025 01:17	JC/MD	Ok
33	VX0606WBS02	VX046548.D	07 Jun 2025 02:00	JC/MD	Ok,M
34	VX0606WBSD02	VX046549.D	07 Jun 2025 02:22	JC/MD	Ok,M
35	PB168312TB	VX046550.D	07 Jun 2025 02:43	JC/MD	Ok,M
36	PB168272TB	VX046551.D	07 Jun 2025 03:05	JC/MD	Ok,M
37	Q2236-05	VX046552.D	07 Jun 2025 03:26	JC/MD	ReRun
38	Q2236-09	VX046553.D	07 Jun 2025 03:48	JC/MD	ReRun
39	Q2236-13	VX046554.D	07 Jun 2025 04:09	JC/MD	Ok
40	Q2236-17	VX046555.D	07 Jun 2025 04:31	JC/MD	ReRun
41	Q2227-04	VX046556.D	07 Jun 2025 04:52	JC/MD	Ok,M
42	Q2228-04	VX046557.D	07 Jun 2025 05:14	JC/MD	ReRun
43	Q2235-01	VX046558.D	07 Jun 2025 05:36	JC/MD	ReRun
44	Q2240-04	VX046559.D	07 Jun 2025 05:57	JC/MD	ReRun

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QCBatch ID # VX060625

Review By	Mahesh Dadoda	Review On	6/9/2025 1:15:21 PM		
Supervise By	Semsettin Yesilyurt	Supervise On	6/9/2025 1:19:58 PM		
SubDirectory	VX060625	HP Acquire Method		HP Processing Method	82X060625W.M

STD. NAME	STD REF.#
Tune/Reschk	VP134153
Initial Calibration Stds	VP134235,VP134236,VP134237,VP134238,VP134239,VP134240
CCC	VP134154
Internal Standard/PEM	
ICV/I.BLK	VP134241
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

45	Q2240-08	VX046560.D	07 Jun 2025 06:18	JC/MD	ReRun
46	Q2240-12	VX046561.D	07 Jun 2025 06:40	JC/MD	ReRun
47	Q2241-04	VX046562.D	07 Jun 2025 07:01	JC/MD	ReRun
48	Q2241-08	VX046563.D	07 Jun 2025 07:23	JC/MD	ReRun
49	Q2226-04	VX046564.D	07 Jun 2025 07:44	JC/MD	ReRun
50	VSTDCCC050	VX046565.D	07 Jun 2025 08:06	JC/MD	Ok,M

M : Manual Integration

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QCBatch ID # VX061025

Review By	John Carlone	Review On	6/11/2025 10:17:47 AM		
Supervise By	Mahesh Dadoda	Supervise On	6/11/2025 11:14:33 AM		
SubDirectory	VX061025	HP Acquire Method		HP Processing Method	82X060625W.M

STD. NAME	STD REF.#
Tune/Reschk	VP134200
Initial Calibration Stds	
CCC	VP134201,VP134202
Internal Standard/PEM	
ICV/I.BLK	
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

Sr#	SampleId	Data File Name	Date-Time	Operator	Status
1	BFB	VX046585.D	10 Jun 2025 08:36	JC/MD	Ok
2	VSTDCCC050	VX046586.D	10 Jun 2025 09:07	JC/MD	Ok,M
3	VX0610MBL01	VX046587.D	10 Jun 2025 09:36	JC/MD	Ok
4	VX0610WBL01	VX046588.D	10 Jun 2025 09:57	JC/MD	Ok
5	VX0610WBS01	VX046589.D	10 Jun 2025 10:18	JC/MD	Ok,M
6	VX0610WBSD01	VX046590.D	10 Jun 2025 10:44	JC/MD	Ok,M
7	Q2262-02	VX046591.D	10 Jun 2025 11:05	JC/MD	Ok
8	Q2262-04	VX046592.D	10 Jun 2025 11:27	JC/MD	Ok
9	IBLK	VX046593.D	10 Jun 2025 11:48	JC/MD	Ok
10	Q2230-01	VX046594.D	10 Jun 2025 12:09	JC/MD	Ok
11	Q2230-06	VX046595.D	10 Jun 2025 12:30	JC/MD	Ok
12	Q2233-01DL	VX046596.D	10 Jun 2025 12:51	JC/MD	Ok
13	Q2233-03DL	VX046597.D	10 Jun 2025 13:13	JC/MD	Ok
14	Q2233-04DL	VX046598.D	10 Jun 2025 13:34	JC/MD	Ok
15	Q2234-01DL	VX046599.D	10 Jun 2025 13:55	JC/MD	Ok
16	IBLK	VX046600.D	10 Jun 2025 14:16	JC/MD	Ok
17	Q2230-05	VX046601.D	10 Jun 2025 14:38	JC/MD	Ok,M
18	Q2230-02	VX046602.D	10 Jun 2025 14:59	JC/MD	Ok,M
19	Q2230-03MS	VX046603.D	10 Jun 2025 15:20	JC/MD	Not Ok
20	Q2230-04MSD	VX046604.D	10 Jun 2025 15:42	JC/MD	Not Ok
21	IBLK	VX046605.D	10 Jun 2025 16:03	JC/MD	Ok

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QCBatch ID # VX061025

Review By	John Carlone	Review On	6/11/2025 10:17:47 AM		
Supervise By	Mahesh Dadoda	Supervise On	6/11/2025 11:14:33 AM		
SubDirectory	VX061025	HP Acquire Method		HP Processing Method	82X060625W.M

STD. NAME	STD REF.#
Tune/Reschk	VP134200
Initial Calibration Stds	
CCC	VP134201,VP134202
Internal Standard/PEM	
ICV/I.BLK	
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

22	Q2249-01	VX046606.D	10 Jun 2025 16:24	JC/MD	Not Ok
23	IBLK	VX046607.D	10 Jun 2025 16:46	JC/MD	Ok
24	Q2233-01	VX046608.D	10 Jun 2025 17:07	JC/MD	Dilution
25	Q2233-03	VX046609.D	10 Jun 2025 17:28	JC/MD	Dilution
26	Q2233-04	VX046610.D	10 Jun 2025 17:50	JC/MD	Dilution
27	Q2234-01	VX046611.D	10 Jun 2025 18:11	JC/MD	Dilution
28	VSTDCCC050	VX046612.D	10 Jun 2025 18:53	JC/MD	Ok,M
29	BFB	VX046613.D	10 Jun 2025 19:57	JC/MD	Ok
30	VSTDICC005	VX046614.D	10 Jun 2025 20:19	JC/MD	Ok,M
31	VSTDICCC020	VX046615.D	10 Jun 2025 20:40	JC/MD	Ok,M
32	VSTDICC050	VX046616.D	10 Jun 2025 21:01	JC/MD	Ok,M
33	VSTDICC100	VX046617.D	10 Jun 2025 21:22	JC/MD	Ok,M
34	VSTDICC150	VX046618.D	10 Jun 2025 21:44	JC/MD	Ok,M
35	IBLK	VX046619.D	10 Jun 2025 22:05	JC/MD	Ok
36	VSTDICV020	VX046620.D	10 Jun 2025 22:26	JC/MD	Ok,M
37	VX0610WBS02	VX046621.D	10 Jun 2025 23:09	JC/MD	Ok,M
38	VX0610WBSD02	VX046622.D	10 Jun 2025 23:30	JC/MD	Ok,M
39	VX0610WBL02	VX046623.D	11 Jun 2025 00:12	JC/MD	Ok
40	Q2203-01	VX046624.D	11 Jun 2025 00:33	JC/MD	Dilution
41	Q2203-04	VX046625.D	11 Jun 2025 00:54	JC/MD	Dilution
42	VSTDCCC020	VX046626.D	11 Jun 2025 01:16	JC/MD	Ok,M

M : Manual Integration