



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

pl031424

Instrument

ECD_I

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
PEM	PL088550.D	4,4"-DDD	Abdul	3/14/2024 10:06:21 AM	Ankita	3/14/2024 10:50:46	Peak Integrated by Software incorrectly
PEM	PL088550.D	4,4"-DDD #2	Abdul	3/14/2024 10:06:21 AM	Ankita	3/14/2024 10:50:46	Peak Integrated by Software incorrectly
PSTDICC005	PL088556.D	delta-BHC	Abdul	3/14/2024 10:06:25 AM	Ankita	3/14/2024 10:50:48	Peak Integrated by Software incorrectly
PSTDICC005	PL088556.D	Endosulfan II	Abdul	3/14/2024 10:06:25 AM	Ankita	3/14/2024 10:50:48	Peak Integrated by Software incorrectly
PSTDICC005	PL088556.D	Endrin	Abdul	3/14/2024 10:06:25 AM	Ankita	3/14/2024 10:50:48	Peak Integrated by Software incorrectly
PSTDICC005	PL088556.D	Heptachlor epoxide	Abdul	3/14/2024 10:06:25 AM	Ankita	3/14/2024 10:50:48	Peak Integrated by Software incorrectly
PSTDICC005	PL088556.D	Mirex #2	Abdul	3/14/2024 10:06:25 AM	Ankita	3/14/2024 10:50:48	Peak Integrated by Software incorrectly
PEM	PL088571.D	4,4"-DDD	Abdul	3/14/2024 10:03:57 AM	Ankita	3/14/2024 10:50:50	Peak Integrated by Software incorrectly
PEM	PL088571.D	alpha-BHC #2	Abdul	3/14/2024 10:03:57 AM	Ankita	3/14/2024 10:50:50	Peak Integrated by Software incorrectly
PEM	PL088571.D	gamma-BHC (Lindane)	Abdul	3/14/2024 10:03:57 AM	Ankita	3/14/2024 10:50:50	Peak Integrated by Software incorrectly
PEM	PL088571.D	Tetrachloro-m-xylene	Abdul	3/14/2024 10:03:57 AM	Ankita	3/14/2024 10:50:50	Peak Integrated by Software incorrectly
PEM	PL088571.D	Tetrachloro-m-xylene #2	Abdul	3/14/2024 10:03:57 AM	Ankita	3/14/2024 10:50:50	Peak Integrated by Software incorrectly
PSTDCCC050	PL088572.D	Endrin aldehyde	Abdul	3/14/2024 10:04:02 AM	Ankita	3/14/2024 10:50:51	Peak Integrated by Software incorrectly



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

pl031424

Instrument

ECD_I

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
PSTDCCC050	PL088572.D	gamma-BHC (Lindane)	Abdul	3/14/2024 10:04:02 AM	Ankita	3/14/2024 10:50:51	Peak Integrated by Software incorrectly
PEM	PL088581.D	4,4"-DDD	Abdul	3/14/2024 10:04:55 AM	Ankita	3/14/2024 10:51:04	Peak Integrated by Software incorrectly
PEM	PL088581.D	4,4"-DDD #2	Abdul	3/14/2024 10:04:55 AM	Ankita	3/14/2024 10:51:04	Peak Integrated by Software incorrectly
PEM	PL088581.D	4,4"-DDT	Abdul	3/14/2024 10:04:55 AM	Ankita	3/14/2024 10:51:04	Peak Integrated by Software incorrectly
PEM	PL088581.D	alpha-BHC #2	Abdul	3/14/2024 10:04:55 AM	Ankita	3/14/2024 10:51:04	Peak Integrated by Software incorrectly
PEM	PL088581.D	Tetrachloro-m-xylene #2	Abdul	3/14/2024 10:04:55 AM	Ankita	3/14/2024 10:51:04	Peak Integrated by Software incorrectly
PSTDCCC050	PL088582.D	alpha-BHC #2	Abdul	3/14/2024 10:04:58 AM	Ankita	3/14/2024 10:51:05	Peak Integrated by Software incorrectly
PSTDCCC050	PL088582.D	Endrin aldehyde	Abdul	3/14/2024 10:04:58 AM	Ankita	3/14/2024 10:51:05	Peak Integrated by Software incorrectly
PSTDCCC050	PL088582.D	gamma-Chlordane	Abdul	3/14/2024 10:04:58 AM	Ankita	3/14/2024 10:51:05	Peak Integrated by Software incorrectly
PSTDCCC050	PL088582.D	Tetrachloro-m-xylene	Abdul	3/14/2024 10:04:58 AM	Ankita	3/14/2024 10:51:05	Peak Integrated by Software incorrectly
PSTDCCC050	PL088588.D	Endrin aldehyde	Abdul	3/14/2024 10:06:01 AM	Ankita	3/14/2024 10:51:14	Peak Integrated by Software incorrectly



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

PL031524

Instrument

ECD_I

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
PEM	PL088591.D	4,4"-DDD	Abdul	3/15/2024 2:29:03 PM	Ankita	3/15/2024 2:40:19	Peak Integrated by Software incorrectly
PEM	PL088591.D	4,4"-DDE	Abdul	3/15/2024 2:29:03 PM	Ankita	3/15/2024 2:40:19	Peak Integrated by Software incorrectly
PEM	PL088591.D	4,4"-DDE #2	Abdul	3/15/2024 2:29:03 PM	Ankita	3/15/2024 2:40:19	Peak Integrated by Software incorrectly
PEM	PL088591.D	Endrin	Abdul	3/15/2024 2:29:03 PM	Ankita	3/15/2024 2:40:19	Peak Integrated by Software incorrectly
PSTDCCC050	PL088592.D	Endrin aldehyde	Abdul	3/15/2024 11:13:38 AM	Ankita	3/15/2024 11:19:57	Peak Integrated by Software incorrectly
PEM	PL088607.D	4,4"-DDD	Abdul	3/15/2024 2:28:46 PM	Ankita	3/15/2024 2:40:24	Peak Integrated by Software incorrectly
PEM	PL088607.D	4,4"-DDE	Abdul	3/15/2024 2:28:46 PM	Ankita	3/15/2024 2:40:24	Peak Integrated by Software incorrectly
PEM	PL088607.D	4,4"-DDE #2	Abdul	3/15/2024 2:28:46 PM	Ankita	3/15/2024 2:40:24	Peak Integrated by Software incorrectly
PEM	PL088607.D	Endrin	Abdul	3/15/2024 2:28:46 PM	Ankita	3/15/2024 2:40:24	Peak Integrated by Software incorrectly
PSTDCCC050	PL088608.D	4,4"-DDD	Abdul	3/15/2024 11:14:28 AM	Ankita	3/15/2024 11:20:23	Peak Integrated by Software incorrectly
PSTDCCC050	PL088608.D	Endrin aldehyde	Abdul	3/15/2024 11:14:28 AM	Ankita	3/15/2024 11:20:23	Peak Integrated by Software incorrectly
PSTDCCC050	PL088608.D	gamma-Chlordane	Abdul	3/15/2024 11:14:28 AM	Ankita	3/15/2024 11:20:23	Peak Integrated by Software incorrectly
PSTDCCC050	PL088608.D	Mirex #2	Abdul	3/15/2024 11:14:28 AM	Ankita	3/15/2024 11:20:23	Peak Integrated by Software incorrectly



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

PL031524

Instrument

ECD_I

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
PB159588BS	PL088616.D	Endrin	Abdul	3/15/2024 11:14:57 AM	Ankita	3/15/2024 11:20:36	Peak Integrated by Software incorrectly
PB159588BS	PL088616.D	Endrin aldehyde	Abdul	3/15/2024 11:14:57 AM	Ankita	3/15/2024 11:20:36	Peak Integrated by Software incorrectly
PB159588BSD	PL088617.D	Endrin	Abdul	3/15/2024 11:15:01 AM	Ankita	3/15/2024 11:20:38	Peak Integrated by Software incorrectly
PB159588BSD	PL088617.D	Endrin aldehyde	Abdul	3/15/2024 11:15:01 AM	Ankita	3/15/2024 11:20:38	Peak Integrated by Software incorrectly
P1747-01	PL088618.D	Tetrachloro-m-xylene #2	Abdul	3/15/2024 11:15:06 AM	Ankita	3/15/2024 11:20:39	Peak Integrated by Software incorrectly
P1747-02	PL088619.D	Tetrachloro-m-xylene #2	Abdul	3/15/2024 11:15:26 AM	Ankita	3/15/2024 11:20:41	Peak Integrated by Software incorrectly
PSTDCCC050	PL088623.D	Endrin aldehyde	Abdul	3/15/2024 11:15:30 AM	Ankita	3/15/2024 11:20:42	Peak Integrated by Software incorrectly
PSTDCCC050	PL088623.D	gamma-Chlordane	Abdul	3/15/2024 11:15:30 AM	Ankita	3/15/2024 11:20:42	Peak Integrated by Software incorrectly
PSTDCCC050	PL088623.D	Mirex #2	Abdul	3/15/2024 11:15:30 AM	Ankita	3/15/2024 11:20:42	Peak Integrated by Software incorrectly