

10:11
BSH

WORKLIST(Hardcopy Internal Chain)

WorkList Name : p4647p

WorkList ID : 185020

Department : Extraction

Date : 11-01-2024 11:01:07

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P4647-01	01A-01B-01C	Solid	PCB Group1	Cool 4 deg C	BSIG01	K61	10/31/2024	8082A

Date/Time 11/01/24 11:01
Raw Sample Received by: RS (Cer 143)
Raw Sample Relinquished by: RM SM

Date/Time 11/01/24 11:10
Raw Sample Received by: RM SM
Raw Sample Relinquished by: RS

WORKLIST(Hardcopy Internal Chain)

WorkList Name : P4647

WorkList ID : 185003

Department : Extraction

Date : 11-01-2024 08:31:00

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P4606-01	1	Solid	PCB Group1	Cool 4 deg C	ATCE02	K63	10/26/2024	8082A
P4645-01	Z-02-WC	Solid	PCB	Cool 4 deg C	PSEG03	K63	10/31/2024	8082A
P4659-01	MH-2	Solid	PCB	Cool 4 deg C	PSEG03	K61	10/31/2024	8082A

Date/Time 11/01/24 9:05
Raw Sample Received by: RJ (Set 1st)
Raw Sample Relinquished by: JD (SM)

Date/Time 11/01/24 9:20
Raw Sample Received by: JD (SM)
Raw Sample Relinquished by: RJ (Set 1st)