

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tully Construction Co., Inc. Date Collected: 11/27/24 10:42

Project: Hamilton Date Received: 11/27/24

Client Sample ID: SOIL-1-HAM SDG No.: P5026

Lab Sample ID: P5026-02 Matrix: SOIL

% Solid: 100

Parameter DF MDL LOQ / CRQL Units **Prep Date** Ana Met. Conc. Qua. Date Ana. Corrosivity 11.4 рΗ 11/27/24 15:27 9045D Ignitability NO 1 0 0 oC 12/03/24 12:37 1030 Reactive Cyanide 0.0087 U 0.050 mg/Kg9012B 1 0.0087 12/02/24 10:00 12/02/24 12:28 Reactive Sulfide J 1.60 0.19 10.0 mg/Kg 12/02/24 12:00 12/02/24 15:09 9034

Comments: pH result reported at temperature 23.2 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits