

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Tully Construction Co., Inc. Date Collected: 11/27/24 11:10 Project: Hamilton Date Received: 11/27/24 Client Sample ID: SOIL-2-HAM SDG No.: P5026 Lab Sample ID: P5026-06 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	10.0	Н	1	0	0	pН		11/27/24 15:35	9045D
Ignitability	NO		1	0	0	oC		12/03/24 12:45	1030
Reactive Cyanide	0.0087	U	1	0.0087	0.050	mg/Kg	12/02/24 10:00	12/02/24 12:28	9012B
Reactive Sulfide	4.76	J	1	0.19	10.0	mg/Kg	12/02/24 12:00	12/02/24 15:12	9034

Comments: pH result reported at temperature 22.9 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits