

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Cover Page

Uploaded	Method	Case	Contract	SDG	File Name	MA
01-06-2025 11:34:39	Volatile Organics	51933	68HERH20D0011	E2AR0	51933_E2AR0_68HERH20D0011_1_SEDD_5-2_GENERAL_3_3_VOA_LOW_MED.xml	

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Sample Summary and Lab Receipt Date		
Sample Number	Volatile Organics	Automated
E2AN7	12-18-2024 10:25:00	X
E2AP8	12-18-2024 10:25:00	X
E2AP9	12-18-2024 10:25:00	X
E2AQ0	12-18-2024 10:25:00	X
E2AQ2	12-18-2024 10:25:00	X
E2AR0	12-17-2024 09:50:00	X
E2AR1	12-17-2024 09:50:00	X
E2AR6	12-17-2024 09:50:00	X
E2AR6MS	12-17-2024 09:50:00	
E2AR6MSD	12-17-2024 09:50:00	
E2AR7	12-17-2024 09:50:00	X
E2AR8	12-17-2024 09:50:00	X
E2AR9	12-17-2024 09:50:00	X
E2AR9ME	12-17-2024 09:50:00	X
E2AS0	12-17-2024 09:50:00	X
E2AS1	12-17-2024 09:50:00	X
Totals	16	

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Grace Period Notification

<i>Some defects have been modified/enhanced in the Method Compliance automated screening system. CLP laboratories are allowed a grace period to make necessary changes for future submissions. Only those defects for which an active grace period currently exists for the methods associated to this submission are listed in the table below. Please refer to the grace period expiration date as displayed below for each listed defect. If any of these active grace period defects are applicable to this SDG, they will be listed in the Grace Period Defect Detail section of this report and disincentives will not be applied for those defects that are assessed during the active grace period. Disincentives will be applied to those defects that are assessed after the grace period has expired.</i>			
Method	Test Name	Defect Message	Expiration Date

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Initial Assessment (IA) Defect Summary				
Method	Category	Test Name	Defect Message	Samples with Defect
Volatile Organics		IAT-04	Required method is missing.	0

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Full Assessment (FA) Defect Summary				
Method	Category	Test Name	Defect Message	Samples with Defect
Volatile Organics		EXES-445	The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable.	14

Method Compliance Results Report

SDG: E2AR0		Case: 51933		Client: EPA Region 5		Submission Event ID: 3972184		Version: 2.00		Submission Type: Self Inspection		SOW: SFAM01.1			
Contract: 68HERH20D0011		Lab Name: Alliance Technical Group, LLC		DRD:		LRD: 12-18-2024		Mailed:		Screening Type: Automated		Sub Group ID: 34491340			

File Skeleton

Volatile Organics																
#	QC	Sample	Type	Date	M	L	DF	File ID	Inst	Col	Run	AB	ABE	PREP	Clean	Store
1	Tune	BFB412	Initial	12-13-2024 08:43:00			1.0	VW031225.D	MSVOA_W	RXI-624	VW031226.D					
2	ICAL	VSTD2.5446	RRF2.5	12-13-2024 09:28:00			1.0	VW031226.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
3	ICAL	VSTD2.5446	RRF005	12-13-2024 09:51:00			1.0	VW031227.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
4	ICAL	VSTD2.5446	RRF025	12-13-2024 10:15:00			1.0	VW031228.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
5	ICAL	VSTD2.5446	RRF050	12-13-2024 10:39:00			1.0	VW031229.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
6	ICAL	VSTD2.5446	RRF100	12-13-2024 11:03:00			1.0	VW031230.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
7	ICV	VICV451	RRF025	12-13-2024 12:00:00			1.0	VW031232.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D	VW031232.D			
8	Tune	BFB415	Initial	12-18-2024 08:09:00			1.0	VW031328.D	MSVOA_W	RXI-624	VW031226.D					
9	CCV	VSTD025594	RRF025	12-18-2024 09:25:00			1.0	VW031329.D	MSVOA_W	RXI-624	VW031226.D	VW031329.D	VW031329.D			
10	CCV	VSTD025595	RRF025	12-18-2024 19:40:00			1.0	VW031350.D	MSVOA_W	RXI-624	VW031226.D	VW031350.D	VW031350.D			
11	MB	VBLK410	Initial	12-18-2024 20:04:00	S	L	1.0	VW031351.D	MSVOA_W	RXI-624	VW031226.D	VW031350.D	VW031368.D	VW031351.D		VW031545.D
12	FS	E2AR0	Initial	12-18-2024 20:52:00	S	L	1.0	VW031352.D	MSVOA_W	RXI-624	VW031226.D	VW031350.D	VW031368.D	VW031351.D		VW031545.D
13	FS	E2AR1	Initial	12-18-2024 21:16:00	S	L	1.0	VW031353.D	MSVOA_W	RXI-624	VW031226.D	VW031350.D	VW031368.D	VW031351.D		VW031545.D
14	FS	E2AS0	Initial	12-18-2024 23:17:00	S	L	1.0	VW031358.D	MSVOA_W	RXI-624	VW031226.D	VW031350.D	VW031368.D	VW031351.D		VW031545.D
15	FS	E2AR9	Initial	12-19-2024 00:06:00	S	L	1.0	VW031360.D	MSVOA_W	RXI-624	VW031226.D	VW031350.D	VW031368.D	VW031351.D		VW031545.D
16	CCV	VSTD025596	RRF025	12-19-2024 03:19:00			1.0	VW031368.D	MSVOA_W	RXI-624	VW031226.D	VW031368.D	VW031368.D			
17	Tune	BFB416	Initial	12-19-2024 07:44:00			1.0	VW031369.D	MSVOA_W	RXI-624	VW031226.D					
18	CCV	VSTD025597	RRF025	12-19-2024 08:38:00			1.0	VW031370.D	MSVOA_W	RXI-624	VW031226.D	VW031370.D	VW031370.D			
19	MB	VBLK411	Initial	12-19-2024 09:34:00	S	L	1.0	VW031371.D	MSVOA_W	RXI-624	VW031226.D	VW031370.D	VW031394.D	VW031371.D		VW031545.D
20	FS	E2AR6	Initial	12-19-2024 18:08:00	S	L	1.0	VW031392.D	MSVOA_W	RXI-624	VW031226.D	VW031370.D	VW031394.D	VW031371.D		VW031545.D
21	FS	E2AR7	Initial	12-19-2024 18:32:00	S	L	1.0	VW031393.D	MSVOA_W	RXI-624	VW031226.D	VW031370.D	VW031394.D	VW031371.D		VW031545.D

Method Compliance Results Report

SDG: E2AR0		Case: 51933		Client: EPA Region 5		Submission Event ID: 3972184		Version: 2.00		Submission Type: Self Inspection		SOW: SFAM01.1			
Contract: 68HERH20D0011		Lab Name: Alliance Technical Group, LLC		DRD:		LRD: 12-18-2024		Mailed:		Screening Type: Automated		Sub Group ID: 34491340			

File Skeleton

Volatile Organics																
#	QC	Sample	Type	Date	M	L	DF	File ID	Inst	Col	Run	AB	ABE	PREP	Clean	Store
22	CCV	VSTD025598	RRF025	12-19-2024 18:56:00			1.0	VW031394.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031394.D			
23	MB	VBLK412	Initial	12-19-2024 19:44:00	S	L	1.0	VW031395.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031412.D	VW031395.D		VW031545.D
24	FS	E2AR8	Initial	12-19-2024 20:56:00	S	L	1.0	VW031396.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031412.D	VW031395.D		VW031545.D
25	FS	E2AR9	Reinjecti on-01	12-19-2024 21:20:00	S	L	1.0	VW031397.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031412.D	VW031395.D		VW031545.D
26	FS	E2AS1	Initial	12-19-2024 21:44:00	S	L	1.0	VW031398.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031412.D	VW031395.D		VW031545.D
27	MS	E2AR6MS	Initial	12-20-2024 02:08:00	S	L	1.0	VW031409.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031412.D	VW031395.D		VW031545.D
28	MSD	E2AR6MSD	Initial	12-20-2024 02:32:00	S	L	1.0	VW031410.D	MSVOA_W	RXI-624	VW031226.D	VW031394.D	VW031412.D	VW031395.D		VW031545.D
29	CCV	VSTD025599	RRF025	12-20-2024 03:19:00			1.0	VW031412.D	MSVOA_W	RXI-624	VW031226.D	VW031412.D	VW031412.D			
30	Tune	BFB417	Initial	12-20-2024 07:46:00			1.0	VW031413.D	MSVOA_W	RXI-624	VW031226.D					
31	CCV	VSTD025600	RRF025	12-20-2024 09:08:00			1.0	VW031414.D	MSVOA_W	RXI-624	VW031226.D	VW031414.D	VW031414.D			
32	CCV	VSTD025601	RRF025	12-20-2024 19:27:00			1.0	VW031437.D	MSVOA_W	RXI-624	VW031226.D	VW031437.D	VW031437.D			
33	MB	VBLK414	Initial	12-20-2024 19:51:00	S	L	1.0	VW031438.D	MSVOA_W	RXI-624	VW031226.D	VW031437.D	VW031458.D	VW031438.D		VW031545.D
34	FS	E2AN7	Initial	12-20-2024 22:15:00	S	L	1.0	VW031443.D	MSVOA_W	RXI-624	VW031226.D	VW031437.D	VW031458.D	VW031438.D		VW031545.D
35	CCV	VSTD025602	RRF025	12-21-2024 04:15:00			1.0	VW031458.D	MSVOA_W	RXI-624	VW031226.D	VW031458.D	VW031458.D			
36	Tune	BFB418	Initial	12-21-2024 13:44:00			1.0	VW031460.D	MSVOA_W	RXI-624	VW031226.D					
37	CCV	VSTD025603	RRF025	12-21-2024 15:08:00			1.0	VW031461.D	MSVOA_W	RXI-624	VW031226.D	VW031461.D	VW031461.D			
38	MB	VBLK415	Initial	12-21-2024 16:00:00	S	L	1.0	VW031462.D	MSVOA_W	RXI-624	VW031226.D	VW031461.D	VW031482.D	VW031462.D		VW031545.D
39	FS	E2AP8	Initial	12-21-2024 16:33:00	S	L	1.0	VW031463.D	MSVOA_W	RXI-624	VW031226.D	VW031461.D	VW031482.D	VW031462.D		VW031545.D
40	FS	E2AP9	Initial	12-21-2024 16:57:00	S	L	1.0	VW031464.D	MSVOA_W	RXI-624	VW031226.D	VW031461.D	VW031482.D	VW031462.D		VW031545.D
41	FS	E2AQ0	Initial	12-21-2024 17:20:00	S	L	1.0	VW031465.D	MSVOA_W	RXI-624	VW031226.D	VW031461.D	VW031482.D	VW031462.D		VW031545.D
42	FS	E2AQ2	Initial	12-21-2024 17:44:00	S	L	1.0	VW031466.D	MSVOA_W	RXI-624	VW031226.D	VW031461.D	VW031482.D	VW031462.D		VW031545.D

Method Compliance Results Report

SDG: E2AR0		Case: 51933		Client: EPA Region 5		Submission Event ID: 3972184		Version: 2.00		Submission Type: Self Inspection		SOW: SFAM01.1			
Contract: 68HERH20D0011		Lab Name: Alliance Technical Group, LLC		DRD:		LRD: 12-18-2024		Mailed:		Screening Type: Automated		Sub Group ID: 34491340			

File Skeleton

Volatile Organics																
#	QC	Sample	Type	Date	M	L	DF	File ID	Inst	Col	Run	AB	ABE	PREP	Clean	Store
43	CCV	VSTD025604	RRF025	12-22-2024 00:06:00			1.0	VW031482.D	MSVOA_W	RXI-624	VW031226.D	VW031482.D	VW031482.D			
44	Tune	BFB421	Initial	12-27-2024 08:24:00			1.0	VW031540.D	MSVOA_W	RXI-624	VW031226.D					
45	CCV	VSTD025483	RRF025	12-27-2024 09:51:00			1.0	VW031541.D	MSVOA_W	RXI-624	VW031226.D	VW031541.D	VW031541.D			
46	MB	VBLK421	Initial	12-27-2024 11:11:00	S	L	1.0	VW031542.D	MSVOA_W	RXI-624	VW031226.D	VW031541.D	VW031552.D	VW031542.D		VW031545.D
47	SB	VHBLK001	Initial	12-27-2024 12:31:00	S	L	1.0	VW031545.D	MSVOA_W	RXI-624	VW031226.D	VW031541.D	VW031552.D	VW031542.D		VW031545.D
48	CCV	VSTD025484	RRF025	12-27-2024 15:36:00			1.0	VW031552.D	MSVOA_W	RXI-624	VW031226.D	VW031552.D	VW031552.D			
49	Tune	BFB703	Initial	12-05-2024 08:43:00			1.0	VX044135.D	MSVOA_X	DB-624UI	VX044143.D					
50	ICAL	VSTD005653	RRF010	12-05-2024 10:38:00			1.0	VX044138.D	MSVOA_X	DB-624UI	VX044143.D	VX044139.D				
51	ICAL	VSTD005653	RRF050	12-05-2024 11:01:00			1.0	VX044139.D	MSVOA_X	DB-624UI	VX044143.D	VX044139.D				
52	ICAL	VSTD005653	RRF100	12-05-2024 11:24:00			1.0	VX044140.D	MSVOA_X	DB-624UI	VX044143.D	VX044139.D				
53	ICAL	VSTD005653	RRF200	12-05-2024 11:47:00			1.0	VX044141.D	MSVOA_X	DB-624UI	VX044143.D	VX044139.D				
54	ICAL	VSTD005653	RRF005	12-05-2024 12:33:00			1.0	VX044143.D	MSVOA_X	DB-624UI	VX044143.D	VX044139.D				
55	ICV	VICV654	RRF050	12-05-2024 13:48:00			1.0	VX044144.D	MSVOA_X	DB-624UI	VX044143.D	VX044139.D	VX044144.D			
56	Tune	BFB708	Initial	12-26-2024 07:47:00			1.0	VX044493.D	MSVOA_X	DB-624UI	VX044143.D					
57	CCV	VSTD050807	RRF050	12-26-2024 08:16:00			1.0	VX044494.D	MSVOA_X	DB-624UI	VX044143.D	VX044494.D	VX044494.D			
58	MB	VBLK744	Initial	12-26-2024 09:21:00	S	M	1.0	VX044495.D	MSVOA_X	DB-624UI	VX044143.D	VX044494.D	VX044507.D	VX044495.D		VW031545.D
59	FS	E2AR9ME	Initial	12-26-2024 10:21:00	S	M	1.0	VX044497.D	MSVOA_X	DB-624UI	VX044143.D	VX044494.D	VX044507.D	VX044495.D		VW031545.D
60	CCV	VSTD050808	RRF050	12-26-2024 16:07:00			1.0	VX044507.D	MSVOA_X	DB-624UI	VX044143.D	VX044507.D	VX044507.D			

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Automated Initial Assessment (IA) Defect Detail - Volatile Organics

Test Name: IAT-04 Defect Message: Required method is missing. Associated Samples: Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
SDG=E2AR0	Submitted Method(s)	Volatile Organics	Equals	Semivolatiles by SIM, Aroclors, Trace Volatiles, Volatile Organics, Pesticides, Semivolatiles

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Automated Full Assessment (FA) Defect Detail - Volatile Organics

Test Name: EXES-445				
Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable.				
Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1				
Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AN7, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AN7, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AN7, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AN7, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AN7, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AN7, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AN7, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AN7, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AN7, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AN7, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AN7, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AN7, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AN7, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AN7, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AN7, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AN7, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AN7, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AN7, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AN7, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AN7, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AN7, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AN7, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AN7, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AN7, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AN7, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AN7, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AN7, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AN7, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AN7, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AN7, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AN7, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AN7, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AN7, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AN7, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AN7, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AN7, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AN7, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AN7, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AN7, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AN7, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AN7, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AN7, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AN7, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AN7, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AN7, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AN7, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AN7, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AN7, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AN7, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AN7, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AN7, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AN7, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AN7, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AP8, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AP8, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AP8, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AP8, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AP8, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AP8, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AP8, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AP8, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AP8, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AP8, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AP8, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AP8, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AP8, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AP8, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AP8, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AP8, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AP8, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AP8, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AP8, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AP8, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AP8, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AP8, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AP8, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AP8, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AP8, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AP8, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AP8, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AP8, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AP8, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AP8, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AP8, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AP8, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AP8, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AP8, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AP8, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AP8, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AP8, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AP8, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AP8, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AP8, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AP8, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AP8, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AP8, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AP8, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AP8, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AP8, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AP8, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AP8, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AP8, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AP8, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AP8, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AP8, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AP8, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AP9, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AP9, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AP9, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AP9, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AP9, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AP9, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AP9, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AP9, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AP9, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AP9, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AP9, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AP9, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AP9, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AP9, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AP9, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AP9, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AP9, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AP9, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AP9, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AP9, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AP9, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AP9, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AP9, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AP9, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AP9, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AP9, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AP9, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AP9, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AP9, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AP9, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AP9, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AP9, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AP9, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AP9, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AP9, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AP9, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AP9, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AP9, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AP9, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AP9, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AP9, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AP9, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AP9, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AP9, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AP9, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AP9, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AP9, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AP9, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AP9, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AP9, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AP9, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AP9, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AP9, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AQ0, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AQ0, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AQ0, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AQ0, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AQ0, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AQ0, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AQ0, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AQ0, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AQ0, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AQ0, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AQ0, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AQ0, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AQ0, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AQ0, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AQ0, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AQ0, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AQ0, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AQ0, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AQ0, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AQ0, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AQ0, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AQ0, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AQ0, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AQ0, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AQ0, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AQ0, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AQ0, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AQ0, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AQ0, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AQ0, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AQ0, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AQ0, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AQ0, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AQ0, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AQ0, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AQ0, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AQ0, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AQ0, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AQ0, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AQ0, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AQ0, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AQ0, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AQ0, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AQ0, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AQ0, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AQ0, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AQ0, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AQ0, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AQ0, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AQ0, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AQ0, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AQ0, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AQ0, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AQ2, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AQ2, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AQ2, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AQ2, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AQ2, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AQ2, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AQ2, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AQ2, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AQ2, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AQ2, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AQ2, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AQ2, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AQ2, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AQ2, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AQ2, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AQ2, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AQ2, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AQ2, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AQ2, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AQ2, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AQ2, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AQ2, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AQ2, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AQ2, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AQ2, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AQ2, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AQ2, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AQ2, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AQ2, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AQ2, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AQ2, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AQ2, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AQ2, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AQ2, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AQ2, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AQ2, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AQ2, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AQ2, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AQ2, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AQ2, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AQ2, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AQ2, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AQ2, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AQ2, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AQ2, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AQ2, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AQ2, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AQ2, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AQ2, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AQ2, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AQ2, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AQ2, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AQ2, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR0, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR0, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR0, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR0, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR0, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR0, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR0, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR0, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR0, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR0, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR0, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR0, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR0, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR0, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR0, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR0, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR0, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR0, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR0, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR0, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR0, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR0, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR0, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR0, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR0, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR0, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR0, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR0, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR0, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR0, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR0, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR0, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR0, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR0, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR0, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR0, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR0, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR0, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR0, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR0, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR0, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR0, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR0, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR0, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR0, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR0, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR0, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR0, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR0, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR0, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR0, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR0, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR0, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR1, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR1, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR1, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR1, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR1, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR1, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR1, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR1, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR1, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR1, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR1, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR1, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR1, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR1, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR1, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR1, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR1, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR1, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR1, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR1, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR1, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR1, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR1, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR1, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR1, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR1, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR1, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR1, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR1, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR1, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR1, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR1, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR1, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR1, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR1, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR1, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR1, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR1, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR1, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR1, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR1, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR1, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR1, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR1, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR1, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR1, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR1, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR1, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR1, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR1, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR1, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR1, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR1, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR6, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR6, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR6, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR6, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR6, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR6, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR6, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR6, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR6, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR6, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR6, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR6, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR6, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR6, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR6, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR6, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR6, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR6, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR6, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR6, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR6, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR6, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR6, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR6, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR6, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR6, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR6, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR6, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR6, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR6, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR6, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR6, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR6, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR6, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR6, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR6, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR6, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR6, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR6, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR6, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR6, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR6, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR6, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR6, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR6, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR6, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR6, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR6, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR6, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR6, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR6, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR6, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR6, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR6MS, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR6MS, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR6MS, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR6MS, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR6MS, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR6MS, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR6MS, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR6MS, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR6MS, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR6MS, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR6MS, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR6MS, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR6MS, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR6MS, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR6MS, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR6MS, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR6MS, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR6MS, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR6MS, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR6MS, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR6MS, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR6MS, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR6MS, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR6MS, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR6MS, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR6MS, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR6MS, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR6MS, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR6MS, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR6MS, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR6MS, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR6MS, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR6MS, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR6MS, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR6MS, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR6MS, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR6MS, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR6MS, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR6MS, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR6MS, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR6MS, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR6MS, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR6MS, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR6MS, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR6MS, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR6MS, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR6MS, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR6MS, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR6MS, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR6MS, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR6MS, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR6MS, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR6MS, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR6MSD, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR6MSD, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR6MSD, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR6MSD, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR6MSD, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR6MSD, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR6MSD, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR6MSD, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR6MSD, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR6MSD, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR6MSD, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR6MSD, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR6MSD, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR6MSD, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR6MSD, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR6MSD, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR6MSD, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR6MSD, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR6MSD, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR6MSD, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR6MSD, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR6MSD, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR6MSD, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR6MSD, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR6MSD, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR6MSD, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR6MSD, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR6MSD, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR6MSD, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR6MSD, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR6MSD, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR6MSD, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR6MSD, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR6MSD, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR6MSD, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR6MSD, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR6MSD, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR6MSD, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR6MSD, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR6MSD, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR6MSD, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR6MSD, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR6MSD, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR6MSD, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR6MSD, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR6MSD, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR6MSD, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR6MSD, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR6MSD, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR6MSD, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR6MSD, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR6MSD, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR6MSD, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR7, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR7, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR7, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR7, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR7, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR7, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR7, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR7, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR7, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR7, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR7, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR7, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR7, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR7, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR7, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR7, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR7, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR7, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR7, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR7, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR7, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR7, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR7, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR7, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR7, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR7, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR7, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR7, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR7, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR7, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR7, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR7, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR7, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR7, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR7, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR7, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR7, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR7, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR7, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR7, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR7, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR7, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR7, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR7, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR7, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR7, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR7, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR7, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR7, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR7, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR7, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR7, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR7, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR8, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR8, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR8, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR8, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR8, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR8, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR8, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR8, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR8, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AR8, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR8, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR8, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR8, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR8, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR8, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR8, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR8, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR8, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR8, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR8, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR8, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR8, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR8, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR8, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR8, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR8, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR8, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR8, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR8, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR8, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR8, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR8, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR8, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR8, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR8, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR8, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR8, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR8, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR8, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR8, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR8, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR8, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR8, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AR8, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR8, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR8, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR8, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR8, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR8, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR8, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR8, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR8, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR8, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AR9, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AR9, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AR9, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AR9, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AR9, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AR9, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AR9, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AR9, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AR9, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR9, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AR9, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AR9, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AR9, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AR9, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AR9, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AR9, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AR9, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AR9, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AR9, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AR9, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AR9, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AR9, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AR9, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AR9, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AR9, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AR9, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AR9, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AR9, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AR9, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AR9, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AR9, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AR9, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AR9, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AR9, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AR9, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AR9, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AR9, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AR9, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AR9, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AR9, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AR9, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AR9, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AR9, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AR9, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AR9, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AR9, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AR9, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AR9, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AR9, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AR9, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AR9, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AR9, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AR9, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AS0, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AS0, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AS0, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AS0, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AS0, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2AS0, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AS0, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AS0, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AS0, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AS0, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AS0, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AS0, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AS0, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AS0, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AS0, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AS0, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AS0, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AS0, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AS0, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AS0, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AS0, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AS0, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AS0, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AS0, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AS0, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AS0, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AS0, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AS0, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AS0, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AS0, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AS0, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AS0, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AS0, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AS0, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AS0, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AS0, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AS0, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AS0, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AS0, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2AS0, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AS0, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AS0, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AS0, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AS0, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AS0, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AS0, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AS0, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AS0, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AS0, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AS0, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AS0, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AS0, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AS0, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2AS1, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2AS1, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2AS1, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2AS1, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2AS1, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AS1, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2AS1, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2AS1, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2AS1, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2AS1, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2AS1, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2AS1, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2AS1, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2AS1, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2AS1, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2AS1, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2AS1, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2AS1, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2AS1, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2AS1, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2AS1, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2AS1, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2AS1, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2AS1, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2AS1, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2AS1, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2AS1, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2AS1, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2AS1, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2AS1, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2AS1, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2AS1, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2AS1, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2AS1, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2AS1, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2AS1, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2AS1, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2AS1, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2AS1, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2AS1, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2AS1, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2AS1, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2AS1, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2AS1, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2AS1, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2AS1, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2AS1, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2AS1, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2AS1, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2AS1, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2AS1, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2AS1, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2AS1, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK410, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK410, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK410, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK410, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK410, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK410, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK410, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK410, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK410, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK410, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK410, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK410, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK410, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK410, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK410, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK410, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK410, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK410, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK410, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK410, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK410, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK410, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK410, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK410, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK410, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK410, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK410, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK410, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK410, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK410, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK410, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK410, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK410, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK410, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK410, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK410, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK410, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK410, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK410, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK410, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK410, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK410, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK410, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK410, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK410, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK410, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK410, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK410, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK410, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK410, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK410, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK410, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK410, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK411, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK411, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK411, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK411, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK411, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK411, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK411, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK411, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK411, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK411, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK411, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK411, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK411, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK411, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK411, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK411, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK411, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK411, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK411, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK411, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK411, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK411, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK411, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK411, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK411, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK411, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK411, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK411, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK411, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK411, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK411, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK411, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK411, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK411, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK411, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK411, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK411, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK411, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK411, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK411, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK411, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK411, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK411, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK411, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK411, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK411, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK411, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK411, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK411, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK411, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK411, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK411, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK411, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK412, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK412, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK412, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK412, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK412, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK412, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK412, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK412, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK412, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK412, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK412, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK412, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK412, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK412, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK412, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK412, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK412, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK412, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK412, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK412, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK412, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK412, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK412, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK412, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK412, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK412, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK412, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK412, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK412, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK412, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK412, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK412, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK412, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK412, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK412, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK412, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK412, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK412, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK412, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK412, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK412, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK412, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK412, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK412, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK412, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK412, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK412, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK412, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK412, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK412, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK412, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK412, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK412, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK414, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK414, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK414, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK414, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK414, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK414, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK414, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK414, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK414, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK414, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK414, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK414, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK414, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK414, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK414, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK414, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK414, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK414, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK414, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK414, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK414, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK414, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK414, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK414, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK414, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK414, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK414, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK414, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK414, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK414, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK414, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK414, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK414, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK414, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK414, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK414, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK414, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK414, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK414, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK414, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK414, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK414, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK414, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK414, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK414, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK414, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK414, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK414, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK414, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK414, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK414, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK414, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK414, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK415, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK415, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK415, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK415, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK415, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK415, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK415, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK415, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK415, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK415, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK415, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK415, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK415, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK415, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK415, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK415, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK415, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK415, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK415, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK415, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK415, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK415, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK415, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK415, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK415, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK415, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK415, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK415, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK415, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK415, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK415, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK415, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK415, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK415, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK415, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK415, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK415, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK415, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK415, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK415, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK415, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK415, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK415, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK415, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK415, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK415, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK415, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK415, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK415, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK415, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK415, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK415, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK415, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK421, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK421, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK421, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK421, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK421, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK421, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK421, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK421, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK421, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK421, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK421, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK421, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK421, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK421, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK421, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK421, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK421, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK421, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK421, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK421, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK421, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK421, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK421, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK421, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK421, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK421, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK421, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK421, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK421, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK421, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK421, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK421, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK421, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK421, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK421, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK421, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK421, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK421, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK421, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK421, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK421, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK421, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK421, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK421, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK421, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK421, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK421, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK421, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK421, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK421, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK421, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK421, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK421, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VHBLK001, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VHBLK001, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VHBLK001, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VHBLK001, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VHBLK001, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VHBLK001, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VHBLK001, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VHBLK001, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VHBLK001, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VHBLK001, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VHBLK001, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VHBLK001, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VHBLK001, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VHBLK001, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VHBLK001, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VHBLK001, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VHBLK001, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VHBLK001, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VHBLK001, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VHBLK001, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VHBLK001, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VHBLK001, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VHBLK001, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VHBLK001, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VHBLK001, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VHBLK001, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VHBLK001, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VHBLK001, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VHBLK001, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VHBLK001, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VHBLK001, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VHBLK001, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VHBLK001, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VHBLK001, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VHBLK001, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VHBLK001, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VHBLK001, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VHBLK001, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VHBLK001, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VHBLK001, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VHBLK001, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VHBLK001, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72

Method Compliance Results Report

SDG: E2AR0	Case: 51933	Client: EPA Region 5	Submission Event ID: 3972184	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-18-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491340

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2AN7, E2AP8, E2AP9, E2AQ0, E2AQ2, E2AR0, E2AR1, E2AR6, E2AR7, E2AR8, E2AR9, E2AR9ME, E2AS0, E2AS1 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VHBLK001, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VHBLK001, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VHBLK001, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VHBLK001, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VHBLK001, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VHBLK001, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VHBLK001, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VHBLK001, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VHBLK001, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VHBLK001, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VHBLK001, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54

Method Compliance Results Report

SDG: E2AR0

Case: 51933

Client: EPA Region 5

Submission Event ID: 3972184

Version: 2.00

Submission Type: Self Inspection

SOW: SFAM01.1

Contract: 68HERH20D0011

**Lab Name: Alliance Technical
Group, LLC**

DRD:

LRD: 12-18-2024

Mailed:

Screening Type: Automated

Sub Group ID: 34491340

Grace Period Defect Detail - Volatile Organics

NONE FOUND