

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Cover Page

Uploaded	Method	Case	Contract	SDG	File Name	MA
01-06-2025 07:28:56	Volatile Organics	51847	68HERH20D0011	E2922	51847_E2922_68HERH20D0011_1_SEDD_5-2_GENERAL_3_3_VOA_LOW_MED.xml	

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Sample Summary and Lab Receipt Date		
Sample Number	Volatile Organics	Automated
E2922	12-19-2024 10:33:00	X
E2924	12-19-2024 10:33:00	X
E2925	12-19-2024 10:33:00	X
E2926	12-19-2024 10:33:00	X
Totals	4	

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Grace Period Notification

<i>Some defects have been modified/enhanced in the Method Compliance automated screening system. CLP laboratories are allowed a grace period to make necessary changes for future submissions. Only those defects for which an active grace period currently exists for the methods associated to this submission are listed in the table below. Please refer to the grace period expiration date as displayed below for each listed defect. If any of these active grace period defects are applicable to this SDG, they will be listed in the Grace Period Defect Detail section of this report and disincentives will not be applied for those defects that are assessed during the active grace period. Disincentives will be applied to those defects that are assessed after the grace period has expired.</i>			
Method	Test Name	Defect Message	Expiration Date

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Initial Assessment (IA) Defect Summary				
Method	Category	Test Name	Defect Message	Samples with Defect
Volatile Organics		IAT-04	Required method is missing.	0

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Full Assessment (FA) Defect Summary				
Method	Category	Test Name	Defect Message	Samples with Defect
Volatile Organics		EXES-445	The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable.	4
Volatile Organics		EXES-57	Matrix-Spike not reported at SOW-specified frequency.	4
Volatile Organics		EXES-58	Matrix-Spike Duplicate not reported at SOW-specified frequency.	4

Method Compliance Results Report

SDG: E2922		Case: 51847		Client: EPA Region 5		Submission Event ID: 3972150		Version: 2.00		Submission Type: Self Inspection		SOW: SFAM01.1			
Contract: 68HERH20D0011		Lab Name: Alliance Technical Group, LLC		DRD:		LRD: 12-19-2024		Mailed:		Screening Type: Automated		Sub Group ID: 34491306			

File Skeleton

Volatile Organics																
#	QC	Sample	Type	Date	M	L	DF	File ID	Inst	Col	Run	AB	ABE	PREP	Clean	Store
1	Tune	BFB412	Initial	12-13-2024 08:43:00			1.0	VW031225.D	MSVOA_W	RXI-624	VW031226.D					
2	ICAL	VSTD2.5446	RRF2.5	12-13-2024 09:28:00			1.0	VW031226.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
3	ICAL	VSTD2.5446	RRF005	12-13-2024 09:51:00			1.0	VW031227.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
4	ICAL	VSTD2.5446	RRF025	12-13-2024 10:15:00			1.0	VW031228.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
5	ICAL	VSTD2.5446	RRF050	12-13-2024 10:39:00			1.0	VW031229.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
6	ICAL	VSTD2.5446	RRF100	12-13-2024 11:03:00			1.0	VW031230.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D				
7	ICV	VICV451	RRF025	12-13-2024 12:00:00			1.0	VW031232.D	MSVOA_W	RXI-624	VW031226.D	VW031228.D	VW031232.D			
8	Tune	BFB419	Initial	12-23-2024 08:03:00			1.0	VW031497.D	MSVOA_W	RXI-624	VW031226.D					
9	CCV	VSTD050606	RRF050	12-23-2024 09:27:00			1.0	VW031498.D	MSVOA_W	RXI-624	VW031226.D	VW031498.D	VW031498.D			
10	MB	VBLK417	Initial	12-23-2024 10:17:00	S	L	1.0	VW031499.D	MSVOA_W	RXI-624	VW031226.D	VW031498.D	VW031517.D	VW031499.D		VW031547.D
11	FS	E2922	Initial	12-23-2024 14:24:00	S	L	1.0	VW031505.D	MSVOA_W	RXI-624	VW031226.D	VW031498.D	VW031517.D	VW031499.D		VW031547.D
12	FS	E2924	Initial	12-23-2024 14:47:00	S	L	1.0	VW031506.D	MSVOA_W	RXI-624	VW031226.D	VW031498.D	VW031517.D	VW031499.D		VW031547.D
13	FS	E2926	Initial	12-23-2024 15:35:00	S	L	1.0	VW031508.D	MSVOA_W	RXI-624	VW031226.D	VW031498.D	VW031517.D	VW031499.D		VW031547.D
14	CCV	VSTD050607	RRF050	12-23-2024 19:09:00			1.0	VW031517.D	MSVOA_W	RXI-624	VW031226.D	VW031517.D	VW031517.D			
15	Tune	BFB420	Initial	12-26-2024 09:41:00			1.0	VW031518.D	MSVOA_W	RXI-624	VW031226.D					
16	CCV	VSTD025481	RRF025	12-26-2024 10:29:00			1.0	VW031519.D	MSVOA_W	RXI-624	VW031226.D	VW031519.D	VW031519.D			
17	MB	VBLK420	Initial	12-26-2024 12:13:00	S	L	1.0	VW031522.D	MSVOA_W	RXI-624	VW031226.D	VW031519.D	VW031539.D	VW031522.D		VW031547.D
18	FS	E2925	Initial	12-26-2024 14:12:00	S	L	1.0	VW031526.D	MSVOA_W	RXI-624	VW031226.D	VW031519.D	VW031539.D	VW031522.D		VW031547.D
19	CCV	VSTD025482	RRF025	12-26-2024 19:23:00			1.0	VW031539.D	MSVOA_W	RXI-624	VW031226.D	VW031539.D	VW031539.D			
20	Tune	BFB421	Initial	12-27-2024 08:24:00			1.0	VW031540.D	MSVOA_W	RXI-624	VW031226.D					
21	CCV	VSTD025483	RRF025	12-27-2024 09:51:00			1.0	VW031541.D	MSVOA_W	RXI-624	VW031226.D	VW031541.D	VW031541.D			

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

File Skeleton

Volatile Organics																
#	QC	Sample	Type	Date	M	L	DF	File ID	Inst	Col	Run	AB	ABE	PREP	Clean	Store
22	MB	VBLK421	Initial	12-27-2024 11:11:00	S	L	1.0	VW031542.D	MSVOA_W	RXI-624	VW031226.D	VW031541.D	VW031552.D	VW031542.D		VW031547.D
23	SB	VHBLK001	Initial	12-27-2024 13:19:00	S	L	1.0	VW031547.D	MSVOA_W	RXI-624	VW031226.D	VW031541.D	VW031552.D	VW031542.D		VW031547.D
24	CCV	VSTD025484	RRF025	12-27-2024 15:36:00			1.0	VW031552.D	MSVOA_W	RXI-624	VW031226.D	VW031552.D	VW031552.D			

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Automated Initial Assessment (IA) Defect Detail - Volatile Organics

Test Name: IAT-04 Defect Message: Required method is missing. Associated Samples: Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
SDG=E2922	Submitted Method(s)	Volatile Organics	Equals	Semivolatiles by SIM, Aroclors, Volatile Organics, Semivolatiles

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Automated Full Assessment (FA) Defect Detail - Volatile Organics

Test Name: EXES-445				
Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable.				
Associated Samples: E2922, E2924, E2925, E2926				
Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2922, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2922, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2922, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2922, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2922, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2922, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2922, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2922, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2922, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2922, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2922, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2922, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2922, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2922, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2922, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2922, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2922, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2922, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2922, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2922, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2922, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2922, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2922, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2922, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2922, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2922, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2922, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2922, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2922, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2922, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2922, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2922, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2922, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2922, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2922, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2922, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2922, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2922, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2922, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2922, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2922, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2922, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2922, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2922, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2922, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2922, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2922, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2922, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2922, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2922, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2922, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2922, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2922, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2924, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2924, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2924, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2924, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2924, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2924, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2924, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2924, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2924, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2924, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2924, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2924, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2924, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2924, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2924, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2924, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2924, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2924, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2924, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2924, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2924, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2924, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2924, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2924, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2924, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2924, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2924, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2924, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2924, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2924, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2924, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2924, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2924, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2924, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2924, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2924, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2924, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2924, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2924, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2924, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2924, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2924, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2924, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2924, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2924, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2924, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2924, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2924, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2924, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2924, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2924, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2924, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2924, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2925, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2925, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2925, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2925, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2925, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2925, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2925, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2925, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2925, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2925, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=E2925, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2925, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2925, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2925, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2925, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2925, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2925, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2925, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2925, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2925, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2925, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2925, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2925, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2925, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2925, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2925, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2925, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2925, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2925, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2925, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2925, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2925, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2925, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2925, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2925, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2925, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2925, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2925, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2925, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2925, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2925, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2925, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2925, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2925, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=E2925, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2925, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2925, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2925, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2925, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2925, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2925, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2925, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2925, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=E2926, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=E2926, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=E2926, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=E2926, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=E2926, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=E2926, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=E2926, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=E2926, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=E2926, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=E2926, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2926, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=E2926, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=E2926, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=E2926, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=E2926, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=E2926, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=E2926, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=E2926, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=E2926, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=E2926, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=E2926, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=E2926, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=E2926, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=E2926, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=E2926, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=E2926, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=E2926, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=E2926, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=E2926, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=E2926, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=E2926, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=E2926, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=E2926, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=E2926, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=E2926, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=E2926, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=E2926, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=E2926, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=E2926, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=E2926, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=E2926, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=E2926, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=E2926, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=E2926, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2926, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=E2926, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=E2926, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=E2926, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=E2926, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=E2926, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=E2926, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=E2926, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=E2926, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK417, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK417, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK417, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK417, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK417, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK417, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK417, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK417, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK417, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK417, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK417, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK417, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK417, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK417, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK417, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK417, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK417, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK417, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK417, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK417, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK417, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK417, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK417, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK417, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK417, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK417, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK417, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK417, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK417, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK417, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK417, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK417, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK417, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK417, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK417, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK417, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK417, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK417, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK417, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK417, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK417, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK417, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK417, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK417, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK417, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK417, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK417, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK417, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK417, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK417, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK417, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK417, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK417, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK420, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK420, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK420, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK420, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK420, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK420, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK420, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK420, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK420, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK420, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK420, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK420, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK420, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK420, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK420, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK420, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK420, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK420, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK420, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK420, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK420, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VBLK420, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK420, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK420, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK420, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK420, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK420, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK420, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK420, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK420, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK420, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK420, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK420, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK420, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK420, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK420, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK420, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK420, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK420, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK420, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK420, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK420, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK420, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK420, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK420, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK420, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK420, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK420, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK420, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK420, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK420, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK420, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK420, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBLK421, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBLK421, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55
Sample=VBLK421, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VBLK421, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VBLK421, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VBLK421, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VBLK421, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VBLK421, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VBLK421, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VBLK421, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VBLK421, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VBLK421, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VBLK421, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VBLK421, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VBLK421, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VBLK421, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VBLK421, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VBLK421, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VBLK421, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VBLK421, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VBLK421, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VBLK421, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VBLK421, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VBLK421, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VBLK421, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VBLK421, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VBLK421, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VBLK421, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VBLK421, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VBLK421, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VBLK421, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VBLK421, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VBLK421, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VBLK421, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VBLK421, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VBLK421, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76
Sample=VBLK421, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VBLK421, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VBLK421, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VBLK421, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VBLK421, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VBLK421, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VBLK421, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VBLK421, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VBLK421, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VBLK421, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VBLK421, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VBLK421, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VBLK421, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VBLK421, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VBLK421, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VBLK421, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VBLK421, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Sample=VBHLK001, Reported Result=100-41-4	ReportedResult/null	.54	notEquals	.52
Sample=VBHLK001, Reported Result=100-42-5	ReportedResult/null	.6	notEquals	.55

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VHBLK001, Reported Result=10061-01-5	ReportedResult/null	.71	notEquals	.7
Sample=VHBLK001, Reported Result=10061-02-6	ReportedResult/null	1.2	notEquals	1.1
Sample=VHBLK001, Reported Result=106-46-7	ReportedResult/null	.76	notEquals	.75
Sample=VHBLK001, Reported Result=106-93-4	ReportedResult/null	.82	notEquals	.81
Sample=VHBLK001, Reported Result=107-06-2	ReportedResult/null	.83	notEquals	.8
Sample=VHBLK001, Reported Result=108-10-1	ReportedResult/null	1.7	notEquals	1.9
Sample=VHBLK001, Reported Result=108-67-8	ReportedResult/null	.58	notEquals	.57
Sample=VHBLK001, Reported Result=108-87-2	ReportedResult/null	.57	notEquals	.49
Sample=VHBLK001, Reported Result=108-88-3	ReportedResult/null	.62	notEquals	.61
Sample=VHBLK001, Reported Result=108-90-7	ReportedResult/null	.66	notEquals	.69
Sample=VHBLK001, Reported Result=110-82-7	ReportedResult/null	.72	notEquals	.54
Sample=VHBLK001, Reported Result=120-82-1	ReportedResult/null	.7	notEquals	.55
Sample=VHBLK001, Reported Result=124-48-1	ReportedResult/null	.78	notEquals	.75
Sample=VHBLK001, Reported Result=127-18-4	ReportedResult/null	.58	notEquals	.66
Sample=VHBLK001, Reported Result=156-59-2	ReportedResult/null	.71	notEquals	.63
Sample=VHBLK001, Reported Result=156-60-5	ReportedResult/null	.61	notEquals	.59
Sample=VHBLK001, Reported Result=1634-04-4	ReportedResult/null	.71	notEquals	.75
Sample=VHBLK001, Reported Result=179601-23-1	ReportedResult/null	.54	notEquals	.52
Sample=VHBLK001, Reported Result=541-73-1	ReportedResult/null	.62	notEquals	.66
Sample=VHBLK001, Reported Result=56-23-5	ReportedResult/null	.61	notEquals	.67
Sample=VHBLK001, Reported Result=591-78-6	ReportedResult/null	2.5	notEquals	2.1
Sample=VHBLK001, Reported Result=67-64-1	ReportedResult/null	7.5	notEquals	2.2
Sample=VHBLK001, Reported Result=67-66-3	ReportedResult/null	.64	notEquals	.79
Sample=VHBLK001, Reported Result=71-43-2	ReportedResult/null	.95	notEquals	.83
Sample=VHBLK001, Reported Result=71-55-6	ReportedResult/null	.69	notEquals	.62
Sample=VHBLK001, Reported Result=74-83-9	ReportedResult/null	.79	notEquals	.86
Sample=VHBLK001, Reported Result=74-87-3	ReportedResult/null	1.1	notEquals	.92
Sample=VHBLK001, Reported Result=74-97-5	ReportedResult/null	.87	notEquals	.88
Sample=VHBLK001, Reported Result=75-00-3	ReportedResult/null	.71	notEquals	.69
Sample=VHBLK001, Reported Result=75-01-4	ReportedResult/null	.93	notEquals	.74
Sample=VHBLK001, Reported Result=75-09-2	ReportedResult/null	4.2	notEquals	.21
Sample=VHBLK001, Reported Result=75-15-0	ReportedResult/null	.64	notEquals	.58
Sample=VHBLK001, Reported Result=75-25-2	ReportedResult/null	1.1	notEquals	.91
Sample=VHBLK001, Reported Result=75-27-4	ReportedResult/null	.75	notEquals	.76

Method Compliance Results Report

SDG: E2922	Case: 51847	Client: EPA Region 5	Submission Event ID: 3972150	Version: 2.00	Submission Type: Self Inspection	SOW: SFAM01.1
Contract: 68HERH20D0011	Lab Name: Alliance Technical Group, LLC	DRD:	LRD: 12-19-2024	Mailed:	Screening Type: Automated	Sub Group ID: 34491306

Test Name: EXES-445 Defect Message: The reported Detection Limit in the EDD does not match the Detection Limit reported in the submitted MDL deliverable. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=VHBLK001, Reported Result=75-34-3	ReportedResult/null	.71	notEquals	.75
Sample=VHBLK001, Reported Result=75-35-4	ReportedResult/null	1.1	notEquals	.68
Sample=VHBLK001, Reported Result=75-69-4	ReportedResult/null	.52	notEquals	.89
Sample=VHBLK001, Reported Result=75-71-8	ReportedResult/null	.75	notEquals	.68
Sample=VHBLK001, Reported Result=76-13-1	ReportedResult/null	.7	notEquals	.79
Sample=VHBLK001, Reported Result=78-87-5	ReportedResult/null	.87	notEquals	.72
Sample=VHBLK001, Reported Result=78-93-3	ReportedResult/null	4.6	notEquals	4.4
Sample=VHBLK001, Reported Result=79-00-5	ReportedResult/null	.7	notEquals	.73
Sample=VHBLK001, Reported Result=79-01-6	ReportedResult/null	.69	notEquals	.64
Sample=VHBLK001, Reported Result=79-20-9	ReportedResult/null	.57	notEquals	1
Sample=VHBLK001, Reported Result=79-34-5	ReportedResult/null	.93	notEquals	1.1
Sample=VHBLK001, Reported Result=87-61-6	ReportedResult/null	.63	notEquals	.76
Sample=VHBLK001, Reported Result=95-47-6	ReportedResult/null	.62	notEquals	.56
Sample=VHBLK001, Reported Result=95-50-1	ReportedResult/null	.76	notEquals	.83
Sample=VHBLK001, Reported Result=95-63-6	ReportedResult/null	.66	notEquals	.54
Sample=VHBLK001, Reported Result=96-12-8	ReportedResult/null	1.4	notEquals	1.2
Sample=VHBLK001, Reported Result=98-82-8	ReportedResult/null	.62	notEquals	.54
Test Name: EXES-57 Defect Message: Matrix-Spike not reported at SOW-specified frequency. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2922	SamplePlusMethod/null	0	lessThan	1
Sample=E2924	SamplePlusMethod/null	0	lessThan	1
Sample=E2925	SamplePlusMethod/null	0	lessThan	1
Sample=E2926	SamplePlusMethod/null	0	lessThan	1
Test Name: EXES-58 Defect Message: Matrix-Spike Duplicate not reported at SOW-specified frequency. Associated Samples: E2922, E2924, E2925, E2926 Comments:				
Location	Attribute	Actual Value	Operator	Expected Value
Sample=E2922	SamplePlusMethod/null	0	lessThan	1
Sample=E2924	SamplePlusMethod/null	0	lessThan	1
Sample=E2925	SamplePlusMethod/null	0	lessThan	1
Sample=E2926	SamplePlusMethod/null	0	lessThan	1

Method Compliance Results Report

SDG: E2922

Case: 51847

Client: EPA Region 5

Submission Event ID: 3972150

Version: 2.00

Submission Type: Self Inspection

SOW: SFAM01.1

Contract: 68HERH20D0011

**Lab Name: Alliance Technical
Group, LLC**

DRD:

LRD: 12-19-2024

Mailed:

Screening Type: Automated

Sub Group ID: 34491306

Grace Period Defect Detail - Volatile Organics

NONE FOUND