

WORKLIST(Hardcopy Internal Chain)

WorkList Name : P5355

WorkList ID : 186511

Department : Extraction

Date : 12-20-2024 08:19:14

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P5355-01	RBR251688	Solid	PCB	Cool 4 deg C	PSEG03	N13	12/19/2024	8082A
P5357-02	121824-A	Solid	PCB	Cool 4 deg C	PSEG03	N13	12/19/2024	8082A
P5359-01	ORA-2065	Solid	PCB	Cool 4 deg C	PSEG03	N13	12/19/2024	8082A
P5359-02	ORA-2064	Solid	PCB	Cool 4 deg C	PSEG03	N13	12/19/2024	8082A

Date/Time 12/20/24 8:25
Raw Sample Received by: RJ (from lab)
Raw Sample Relinquished by: J-C (sum)

Date/Time 12/20/24 8:45
Raw Sample Received by: J-C (sum)
Raw Sample Relinquished by: RJ (from lab)

WORKLIST(Hardcopy Internal Chain)

WorkList Name : P5361

WorkList ID : 186536

Department : Extraction

Date : 12-20-2024 11:12:24

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P5361-01	SB-01-20241219-7.0-7.5	Solid	PCB	Cool 4 deg C	PARS02	N12	12/20/2024	8082A
P5361-02	SB-01-20241219-9.0-9.5	Solid	PCB	Cool 4 deg C	PARS02	N12	12/20/2024	8082A
P5362-01	WC-SOIL-20241219	Solid	PCB	Cool 4 deg C	PARS02	N21	12/19/2024	8082A

Date/Time 12/20/24 11:12
Raw Sample Received by: R.J. (Ext 105)
Raw Sample Relinquished by: R.J. (Ext 105)

Date/Time 12/20/24 11:25
Raw Sample Received by: R.J. (Ext 105)
Raw Sample Relinquished by: R.J. (Ext 105)