

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:Tully Construction Co., Inc.Date Collected:03/20/25 12:30Project:DOT Harper Street Yard - North SideDate Received:03/21/25

Client Sample ID: GRID-LINE-1.2-NORTH SDG No.: Q1627

Lab Sample ID: Q1627-01 Matrix: SOIL

% Solid: 85.5

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	10.8	Н	1	0	0	pН		03/24/25 17:05	9045D
Ignitability	NO		1	0	0	oC		03/24/25 11:45	1030
Reactive Cyanide	0.0086	J	1	0.0083	0.050	mg/Kg	03/25/25 11:30	03/25/25 15:45	9012B
Reactive Sulfide	6.31	J	1	0.20	10.0	mg/Kg	03/25/25 09:20	03/25/25 11:38	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits