

WORKLIST(Hardcopy Internal Chain)

WorkList Name : Q3012 **WorkList ID :** 191656 **Department :** Extraction **Date :** 09-04-2025 08:59:33

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
Q3011-03	1	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3011-04	2	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3011-05	3	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3011-06	4	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3011-07	5	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3011-08	6	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3012-03	1	Solid	EPH_F2	Cool 4 deg C	SCIA01	J33	09/03/2025	NJEPH
Q3012-04	2	Solid	EPH_F2	Cool 4 deg C	SCIA01	J42	09/03/2025	NJEPH
Q3012-05	3	Solid	EPH_F2	Cool 4 deg C	SCIA01	J42	09/03/2025	NJEPH
Q3012-06	4	Solid	EPH_F2	Cool 4 deg C	SCIA01	J42	09/03/2025	NJEPH
Q3012-07	5	Solid	EPH_F2	Cool 4 deg C	SCIA01	J42	09/03/2025	NJEPH

Date/Time 09/04/25 9:00
Raw Sample Received by: R.S. C. (7-1-2025)
Raw Sample Relinquished by: CP8

Date/Time 09/04/25 9:15
Raw Sample Received by: CP8
Raw Sample Relinquished by: R.S. C. (7-1-2025)