

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Tully Construction Co., Inc.
Project: MTA 26 Stations - Pierrepont

Client Sample ID: 304 FURMAN SOIL

Lab Sample ID: Q3790-02

Date Collected: 12/05/25 07:25

100

Date Received: 12/05/25 SDG No.: Q3790 Matrix: SOIL

% Solid:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.95	Н	1	0	0	рН		12/08/25 12:22	9045D
Ignitability	NO		1	0	0	oC		12/08/25 09:40	1030
Reactive Cyanide	0.0084	U	1	0.0084	0.050	mg/Kg	12/08/25 08:50	12/08/25 11:21	9012B
Reactive Sulfide	3 10	ī	1	0.20	10.0	mg/Kg	12/09/25 09:15	12/09/25 13:05	9034

Comments: pH result reported at temperature 20.8 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits