



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : SOM02.4_PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pr102820 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PR048306.D	28 Oct 2020 08:53	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
AIBLK93	PR048307.D	28 Oct 2020 09:08	AIBLK93	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PR048308.D	28 Oct 2020 09:22	AR1660369	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PR048309.D	28 Oct 2020 09:38	AR1248364	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PR048310.D	28 Oct 2020 10:00	AR1254386	PCB	CCAL400	1	--	OK	UPDATE STATUS
PB132615BS	PR048311.D	28 Oct 2020 10:18	PB132615BS	EPH_NF	LCS	1	TYPO	NotOK	UPDATE STATUS
L4506-12DL	PR048312.D	28 Oct 2020 10:33	C0BJ3DL	PCB	SAM	5	AR1254 hit	OK	UPDATE STATUS
L4506-13DL	PR048313.D	28 Oct 2020 10:47	C0BJ4DL	PCB	SAM	2	AR1254 hit	OK	UPDATE STATUS
L4506-01DL	PR048314.D	28 Oct 2020 11:02	C0BF4DL	PCB	SAM	100	AR1254 hit	OK	Surr Fail UPDATE STATUS
L4506-02DL	PR048315.D	28 Oct 2020 11:16	C0BF6DL	PCB	SAM	100	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
		28					AR1254 hits,		

L4506-03DL	PR048316.D	Oct 2020 11:30	C0BF7DL	PCB	SAM	200	Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4506-03DL2	PR048317.D	28 Oct 2020 11:45	C0BF7DL2	PCB	SAM	2000	AR1254 hits, Need more dilution, Not matched with original	NotOK	Surr, OR Fail UPDATE STATUS
L4506-04	PR048318.D	28 Oct 2020 11:59	C0BG1	PCB	SAM	5	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-04DL	PR048319.D	28 Oct 2020 12:14	C0BG1DL	PCB	SAM	50	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-05	PR048320.D	28 Oct 2020 12:28	C0BG2	PCB	SAM	5	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-05DL	PR048321.D	28 Oct 2020 12:43	C0BG2DL	PCB	SAM	50	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-06	PR048322.D	28 Oct 2020 12:57	C0BG4	PCB	SAM	2	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-06DL	PR048323.D	28 Oct 2020 13:11	C0BG4DL	PCB	SAM	20	AR1254 hits, Need more dilution	NotOK	Surr Fail UPDATE STATUS
L4506-07DL	PR048324.D	28 Oct 2020 13:26	C0BG5DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-09	PR048325.D	28 Oct 2020 13:40	C0BH5	PCB	SAM	5	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-09DL	PR048326.D	28 Oct 2020 13:55	C0BH5DL	PCB	SAM	50	AR1254 hits, Check 2nd column 5th peak concentration	OK	Surr Fail UPDATE STATUS
L4506-10	PR048327.D	28 Oct 2020 14:09	C0BH6	PCB	SAM	2	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-10DL	PR048328.D	28 Oct 2020 14:24	C0BH6DL	PCB	SAM	20	AR1254 hits, Need more dilution, DCB low in 1st column	OK	Surr Fail UPDATE STATUS
L4506-14DL	PR048329.D	28 Oct 2020 14:38	C0BJ7DL	PCB	SAM	100	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4506-14DL2	PR048330.D	28 Oct 2020 14:53	C0BJ7DL2	PCB	SAM	1000	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-16	PR048331.D	28 Oct 2020 15:07	C0BJ9	PCB	SAM	1	AR1248, 1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
AIBLK94	PR048332.D	28 Oct 2020 15:22	AIBLK94	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
		28							

AR1660CCC400	PR048333.D	Oct 2020 15:36	AR1660370	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PR048334.D	28 Oct 2020 15:52	AR1248365	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PR048335.D	28 Oct 2020 16:07	AR1254387	PCB	CCAL400	1	--	OK	UPDATE STATUS
L4506-15	PR048336.D	28 Oct 2020 16:21	C0BJ8	PCB	SAM	5	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-15DL	PR048337.D	28 Oct 2020 16:36	C0BJ8DL	PCB	SAM	50	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-17DL	PR048338.D	28 Oct 2020 16:50	C0BK4DL	PCB	SAM	100	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4506-17DL2	PR048339.D	28 Oct 2020 17:05	C0BK4DL2	PCB	SAM	1000	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-20DL	PR048340.D	28 Oct 2020 17:19	C0BK5DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-21DL	PR048341.D	28 Oct 2020 17:33	C0BK6DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4506-22	PR048342.D	28 Oct 2020 17:48	C0BL1	PCB	SAM	5	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4506-22DL	PR048343.D	28 Oct 2020 18:02	C0BL1DL	PCB	SAM	50	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-01DL	PR048344.D	28 Oct 2020 18:17	C0BL2DL	PCB	SAM	20	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4507-01DL2	PR048345.D	28 Oct 2020 18:31	C0BL2DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-02DL	PR048346.D	28 Oct 2020 18:46	C0BL3DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-03	PR048347.D	28 Oct 2020 19:00	C0BM1	PCB	SAM	2	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4507-03DL	PR048348.D	28 Oct 2020 19:15	C0BM1DL	PCB	SAM	20	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-04	PR048349.D	28 Oct 2020 19:29	C0BM2	PCB	SAM	1	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4507-05DL	PR048350.D	28 Oct 2020 19:44	C0BL8DL	PCB	SAM	20	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS

L4507-05DL2	PR048351.D	28 Oct 2020 19:58	COBL8DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-06	PR048352.D	28 Oct 2020 20:12	COBL9	PCB	SAM	2	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4507-06DL	PR048353.D	28 Oct 2020 20:27	COBL9DL	PCB	SAM	20	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-07DL	PR048354.D	28 Oct 2020 20:41	COBM0DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-08	PR048355.D	28 Oct 2020 20:56	COBM3	PCB	SAM	2	AR1254 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4507-08DL	PR048356.D	28 Oct 2020 21:10	COBM3DL	PCB	SAM	20	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-09DL	PR048357.D	28 Oct 2020 21:25	COBM4DL	PCB	SAM	50	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4507-09DL2	PR048358.D	28 Oct 2020 21:39	COBM4DL2	PCB	SAM	500	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-10DL	PR048359.D	28 Oct 2020 21:54	COBM5DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-11DL	PR048360.D	28 Oct 2020 22:08	COBM6DL	PCB	SAM	20	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4507-11DL2	PR048361.D	28 Oct 2020 22:23	COBM6DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-12DL	PR048362.D	28 Oct 2020 22:37	COBM7DL	PCB	SAM	100	AR1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4507-12DL2	PR048363.D	28 Oct 2020 22:51	COBM7DL2	PCB	SAM	1000	AR1254 hits	OK	Surr Fail UPDATE STATUS
AIBLK95	PR048364.D	28 Oct 2020 23:06	AIBLK95	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PR048365.D	28 Oct 2020 23:20	AR1660371	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PR048366.D	28 Oct 2020 23:35	AR1248366	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PR048367.D	28 Oct 2020 23:49	AR1254388	PCB	CCAL400	1	--	OK	UPDATE STATUS
L4507-13	PR048368.D	29 Oct 2020	COBN0	PCB	SAM	1	AR1254 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS

		00:04							
L4507-14	PR048369.D	29 Oct 2020 00:18	COBN1	PCB	SAM	1	AR1254 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4507-15DL	PR048370.D	29 Oct 2020 00:33	COBN2DL	PCB	SAM	100	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4507-16	PR048371.D	29 Oct 2020 00:47	COBN3	PCB	SAM	1	AR1254 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4507-17	PR048372.D	29 Oct 2020 01:02	COBN4	PCB	SAM	1	Surrogate not detected	NotOK	Surr Fail UPDATE STATUS
L4507-18	PR048373.D	29 Oct 2020 01:16	COBN5	PCB	SAM	1	AR1248,1254 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4507-19DL	PR048374.D	29 Oct 2020 01:31	COBN6DL	PCB	SAM	20	AR1254 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
L4507-19DL2	PR048375.D	29 Oct 2020 01:45	COBN6DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail UPDATE STATUS
AIBLK96	PR048376.D	29 Oct 2020 02:14	AIBLK96	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PR048377.D	29 Oct 2020 02:28	AR1660372	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PR048378.D	29 Oct 2020 02:43	AR1248367	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PR048379.D	29 Oct 2020 02:57	AR1254389	PCB	CCAL400	1	--	OK	UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)