



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pp111820 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PP031339.D	18 Nov 2020 8:28	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
AR1660CCC500	PP031340.D	18 Nov 2020 8:45	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP031341.D	18 Nov 2020 9:10	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4770-11RE	PP031342.D	18 Nov 2020 9:26	FJ-BH-02-4-5RE	PCB	SAM	1	DCB high in both column	CONFIRMS	Surr Fail UPDATE STATUS
L4743-01	PP031343.D	18 Nov 2020 9:43	HEF119K-END-1	PCB	SAM	10	--	OK	UPDATE STATUS
L4741-01	PP031344.D	18 Nov 2020 10:00	11-13-A	PCB	SAM	5	TCMX high in both column	RERUN	Surr Fail UPDATE STATUS
L4741-02	PP031345.D	18 Nov 2020 10:16	11-13-B	PCB	SAM	5	TCMX high in both column, DCB high in 2nd column	RERUN	Surr Fail UPDATE STATUS
L4741-03	PP031346.D	18 Nov 2020 10:33	11-13-C	PCB	SAM	5	TCMX high in both column, DCB high in 2nd column, DCB has a F flag	NotOK	Surr Fail UPDATE STATUS
L4743-02	PP031347.D	18 Nov 2020 10:50	HEF119K-END-2	PCB	SAM	5	--	OK	UPDATE STATUS
L4743-03	PP031348.D	18 Nov 2020 11:06	GHH052Y-END-1	PCB	SAM	5	AR1260 hits	OK	UPDATE STATUS

L4743-04	PP031349.D	18 Nov 2020 11:23	GHH052Y-END-2	PCB	SAM	5	--	OK	UPDATE STATUS
L4743-05	PP031350.D	18 Nov 2020 11:40	HIA775H-END-1	PCB	SAM	5	AR1260 hits, Need more dilution	DILUTION	OR Fail UPDATE STATUS
L4743-06	PP031351.D	18 Nov 2020 11:56	HIA775H-END-2	PCB	SAM	5	--	OK	UPDATE STATUS
AR1660CCC500	PP031352.D	18 Nov 2020 12:13	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP031353.D	18 Nov 2020 12:30	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4778-01	PP031354.D	18 Nov 2020 13:24	1840	PCB	SAM	5	--	OK	UPDATE STATUS
L4778-04	PP031355.D	18 Nov 2020 13:40	1811	PCB	SAM	1	--	OK	UPDATE STATUS
L4744-02	PP031356.D	18 Nov 2020 13:57	JEC4860-END-2	PCB	SAM	5	AR1254 hits	OK	UPDATE STATUS
L4744-01	PP031357.D	18 Nov 2020 14:13	JEC4860-END-1	PCB	SAM	5	AR1254 hits, Need to straight run	NotOK	UPDATE STATUS
L4777-01	PP031358.D	18 Nov 2020 14:30	RT877	PCB	SAM	1	--	OK	UPDATE STATUS
L4778-06	PP031359.D	18 Nov 2020 14:47	VNJ-223	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4778-07	PP031360.D	18 Nov 2020 15:03	358	PCB	SAM	1	--	OK	UPDATE STATUS
L4780-01	PP031361.D	18 Nov 2020 15:20	CL-01-111720	PCB	SAM	1	--	OK	UPDATE STATUS
PB133081BL	PP031362.D	18 Nov 2020 15:37	PB133081BL	PCB	MB	1	--	OK	UPDATE STATUS
PB133081BS	PP031363.D	18 Nov 2020 15:53	PB133081BS	PCB	LCS	1	--	OK	UPDATE STATUS
AR1660CCC500	PP031364.D	18 Nov 2020 16:10	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP031365.D	18 Nov 2020 16:28	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4784-01	PP031366.D	18 Nov 2020	SIMW-02-20201117	PCB	SAM	1	--	OK	UPDATE STATUS

		16:45							
L4784-02MS	PP031367.D	18 Nov 2020 17:01	SIMW-02-20201117MS	PCB	MS	1	--	OK	UPDATE STATUS
L4784-03MSD	PP031368.D	18 Nov 2020 17:18	SIMW-02-20201117MSD	PCB	MSD	1	--	OK	UPDATE STATUS
L4784-04	PP031369.D	18 Nov 2020 17:35	SIMW-02-20201117-A	PCB	SAM	1	--	OK	UPDATE STATUS
L4784-05	PP031370.D	18 Nov 2020 17:51	MW-3-20201117	PCB	SAM	1	--	OK	UPDATE STATUS
L4784-06	PP031371.D	18 Nov 2020 18:08	SIMW-04-20201117	PCB	SAM	1	--	OK	UPDATE STATUS
L4784-07	PP031372.D	18 Nov 2020 18:25	SIMW-07-20201117	PCB	SAM	1	--	OK	UPDATE STATUS
L4784-08	PP031373.D	18 Nov 2020 18:41	CSIMW-01-20201117	PCB	SAM	1	--	OK	UPDATE STATUS
L4784-09	PP031374.D	18 Nov 2020 18:58	RW-2-20201117	PCB	SAM	1	--	OK	UPDATE STATUS
L4784-10	PP031375.D	18 Nov 2020 19:15	RW-M-20201117	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
AR1660CCC500	PP031376.D	18 Nov 2020 19:31	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP031377.D	18 Nov 2020 20:04	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4784-11	PP031378.D	18 Nov 2020 20:21	FB-20201117	PCB	SAM	1	--	OK	UPDATE STATUS
L4776-01	PP031379.D	18 Nov 2020 20:38	ND-SOIL	PCB	SAM	1	AR1254,1260 hits, Need 2X, DCB has a F flag	NotOK	OR Fail UPDATE STATUS
L4776-01MS	PP031380.D	18 Nov 2020 20:54	ND-SOILMS	PCB	MS	1	Recovery Fail for AR1260, Original sample is NOTOK	NotOK	Surr, Recovery Fail UPDATE STATUS
L4776-01MSD	PP031381.D	18 Nov 2020 21:11	ND-SOILMSD	PCB	MSD	1	Recovery Fail for AR1260, Original sample is NOTOK	NotOK	Surr, Recovery Fail UPDATE STATUS
L4775-01	PP031382.D	18 Nov 2020 21:28	FMI-124	PCB	SAM	1	DCB has a F flag	NotOK	UPDATE STATUS
L4779-14	PP031383.D	18 Nov 2020 21:44	COMP-1605-1607	PCB	SAM	1	--	OK	UPDATE STATUS

L4779-13	PP031384.D	18 Nov 2020 22:01	COMP-1654-1658	PCB	SAM	1	DCB low in both column, DCB has a F flag	NotOK	Surr Fail UPDATE STATUS
PB133078BL	PP031385.D	18 Nov 2020 22:18	PB133078BL	PCB	MB	1	--	OK	UPDATE STATUS
PB133078BS	PP031386.D	18 Nov 2020 22:34	PB133078BS	PCB	LCS	1	DCB has a F flag	NotOK	UPDATE STATUS
AR1660CCC500	PP031387.D	18 Nov 2020 22:51	AR1660CCC500	PCB	CCAL500	1	DCB has a F flag	OK	UPDATE STATUS
I.BLK	PP031388.D	18 Nov 2020 23:24	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4779-05	PP031389.D	18 Nov 2020 23:41	1555	PCB	SAM	1	DCB low in both column, TCMX has a F flag	NotOK	Surr Fail UPDATE STATUS
L4778-11	PP031390.D	18 Nov 2020 23:57	1814	PCB	SAM	1	DCB low in 1st column, TCMX low in 2nd column, DCB has a F flag	NotOK	Surr Fail UPDATE STATUS
L4779-01	PP031391.D	19 Nov 2020 00:14	1643	PCB	SAM	1	DCB low in both column, DCB has a F flag	NotOK	Surr Fail UPDATE STATUS
L4779-02	PP031392.D	19 Nov 2020 00:31	1641	PCB	SAM	1	All surrogate failing low	NotOK	Surr Fail UPDATE STATUS
L4779-03	PP031393.D	19 Nov 2020 00:47	1623	PCB	SAM	1	DCB has a F flag	NotOK	UPDATE STATUS
L4779-04	PP031394.D	19 Nov 2020 1:04	1608	PCB	SAM	1	All surrogate havinf F flag	NotOK	UPDATE STATUS
AR1660CCC500	PP031395.D	19 Nov 2020 1:20	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP031396.D	19 Nov 2020 1:37	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)