



Suggestion Box    MSDS RICCA    MSDS J.T.Baker  
MSDS emdmillipore    MSDS restek    MSDS CHEMTECH

Welcome Sakhvala  
| Logout

Search :

Dashboard | Edd | Efolder | Fax | Genchem | Projecttrack | Qaqc | Quanttrack | Report | Sequence | Utility |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 608.3 PCB

[FileInfo Form](#)   [Get Test Info](#)   [Analysis RunLog](#)   [Sequence Info](#)   [Maintenance](#)   [Audit Summary Report](#)   [Sequence Process](#)

Data For Sequence Pq040120   **CHEMTECH-NJ Lab Sequence**  
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

| SampleID                     | Data File                  | Date & Time       | ClientId     | Test       | QCType  | Dilution. | Comments                                              | Status   | System Comments                                            |
|------------------------------|----------------------------|-------------------|--------------|------------|---------|-----------|-------------------------------------------------------|----------|------------------------------------------------------------|
| <a href="#">I.BLK</a>        | <a href="#">PQ047182.D</a> | 01 Apr 2020 09:56 | I.BLK        | PCB        | IBLK    | 1         | --                                                    | OK       | <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">AR1660CCC500</a> | <a href="#">PQ047183.D</a> | 01 Apr 2020 10:13 | AR1660CCC500 | PCB        | CCAL500 | 1         | --                                                    | OK       | <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">L2080-03RE</a>   | <a href="#">PQ047184.D</a> | 01 Apr 2020 10:32 | S7-03-ARE    | PCB Group1 | SAM     | 1         | AR1254 & AR1268 hits, DCB failing high in both column | CONFIRMS | Surr Fail <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2077-03RE</a>   | <a href="#">PQ047185.D</a> | 01 Apr 2020 10:48 | S4-05-ARE    | PCB Group1 | SAM     | 1         | DCB failing low in both column                        | CONFIRMS | Surr Fail <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2077-04RE</a>   | <a href="#">PQ047186.D</a> | 01 Apr 2020 11:04 | S4-06-ARE    | PCB Group1 | SAM     | 1         | DCB failing low in both column                        | CONFIRMS | Surr Fail <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2051-01DL</a>   | <a href="#">PQ047187.D</a> | 01 Apr 2020 11:20 | SB-1DL       | PCB        | SAM     | 4         | AR1254 Hits Need lower dilution 2X                    | DILUTION | Surr Fail <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2079-04DL</a>   | <a href="#">PQ047188.D</a> | 01 Apr 2020 11:37 | S6-04-ADL    | PCB Group1 | SAM     | 5         | AR1254,1268 hit, DCB high in both column              | OK       | Surr Fail <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2079-05DL</a>   | <a href="#">PQ047189.D</a> | 01 Apr 2020 11:53 | S6-05-ADL    | PCB Group1 | SAM     | 5         | AR1254,1268 hit, DCB high in both column              | OK       | Surr Fail <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L1758-01</a>     | <a href="#">PQ047190.D</a> | 01 Apr 2020 12:09 | PL-03-033020 | PCB        | SAM     | 1         | --                                                    | OK       | <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">L1759-16</a>     | <a href="#">PQ047191.D</a> | 01 Apr 2020 12:25 | OR-03-033020 | PCB        | SAM     | 1         | --                                                    | OK       | <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |

|                              |                            |                   |              |            |         |   |                                                         |          |                                                                                     |
|------------------------------|----------------------------|-------------------|--------------|------------|---------|---|---------------------------------------------------------|----------|-------------------------------------------------------------------------------------|
| <a href="#">L2080-10</a>     | <a href="#">PQ047192.D</a> | 01 Apr 2020 12:42 | S7-01-A      | PCB Group1 | SAM     | 1 | AR1254 & AR1260 Hits , DCB failing low in first coloumn | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2079-02</a>     | <a href="#">PQ047193.D</a> | 01 Apr 2020 12:58 | S6-02-A      | PCB Group1 | SAM     | 1 | AR1254 & AR1268 hits                                    | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">L2079-03</a>     | <a href="#">PQ047194.D</a> | 01 Apr 2020 13:14 | S6-03-A      | PCB Group1 | SAM     | 1 | AR1254 & AR1268 hits, Need dilution 12x                 | DILUTION | Surr, OR Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2076-04</a>     | <a href="#">PQ047195.D</a> | 01 Apr 2020 13:31 | S3-04-A      | PCB Group1 | SAM     | 1 | AR1260 Hits, DCB failing low in both coloumn            | RERUN    | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2074-01</a>     | <a href="#">PQ047196.D</a> | 01 Apr 2020 13:47 | S1-01-A      | PCB Group1 | SAM     | 1 | DCB failing low in both coloumn                         | RERUN    | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2078-02</a>     | <a href="#">PQ047197.D</a> | 01 Apr 2020 14:03 | S5-02-A      | PCB Group1 | SAM     | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">PB127912BL</a>   | <a href="#">PQ047198.D</a> | 01 Apr 2020 14:19 | PB127912BL   | PCB Group1 | MB      | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">PB127912BS</a>   | <a href="#">PQ047199.D</a> | 01 Apr 2020 14:36 | PB127912BS   | PCB Group1 | LCS     | 1 | --                                                      | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2081-01</a>     | <a href="#">PQ047200.D</a> | 01 Apr 2020 14:52 | S8-01-A      | PCB Group1 | SAM     | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">I.BLK</a>        | <a href="#">PQ047201.D</a> | 01 Apr 2020 15:33 | I.BLK        | PCB        | IBLK    | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">AR1660CCC500</a> | <a href="#">PQ047202.D</a> | 01 Apr 2020 15:49 | AR1660CCC500 | PCB        | CCAL500 | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">L2082-02</a>     | <a href="#">PQ047203.D</a> | 01 Apr 2020 16:06 | S9-02-A      | PCB Group1 | SAM     | 1 | DCB failing high in 2nd coloumn                         | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2084-03</a>     | <a href="#">PQ047204.D</a> | 01 Apr 2020 16:22 | S11-03-A     | PCB Group1 | SAM     | 1 | DCB failing low in both coloumn                         | RERUN    | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2084-02</a>     | <a href="#">PQ047205.D</a> | 01 Apr 2020 16:38 | S11-02-A     | PCB Group1 | SAM     | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">L2081-02</a>     | <a href="#">PQ047206.D</a> | 01 Apr 2020 16:55 | S8-02-A      | PCB Group1 | SAM     | 1 | --                                                      | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>               |
| <a href="#">L2081-03</a>     | <a href="#">PQ047207.D</a> | 01 Apr 2020 17:11 | S8-03-A      | PCB Group1 | SAM     | 1 | AR1254 & AR1260 hits, DCB failing high in both coloumn  | RERUN    | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
| <a href="#">L2081-04</a>     | <a href="#">PQ047208.D</a> | 01 Apr 2020 17:27 | S8-04-A      | PCB Group1 | SAM     | 1 | AR1254 & AR1260 hits, DCB failing high in both coloumn  | RERUN    | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>     |
|                              |                            |                   |              |            |         |   |                                                         |          |                                                                                     |

|                              |                            |                        |              |                                               |         |   |                                                    |          |                                                                                           |
|------------------------------|----------------------------|------------------------|--------------|-----------------------------------------------|---------|---|----------------------------------------------------|----------|-------------------------------------------------------------------------------------------|
| <a href="#">L2081-05</a>     | <a href="#">PQ047209.D</a> | 01 Apr 2020 17:43      | S8-05-A      | PCB                                           | SAM     | 1 | --                                                 | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">L2081-06</a>     | <a href="#">PQ047210.D</a> | 01 Apr 2020 18:00      | S8-06-A      | PCB                                           | SAM     | 1 | AR1254,1260 & AR1268 hits,Need 2X & confirm AR1260 | DILUTION | Surr, OR Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>       |
| <a href="#">L2081-06MS</a>   | <a href="#">PQ047211.D</a> | 01 Apr 2020 18:16      | S8-06-AMS    | PCB                                           | MS      | 1 | --                                                 | OK       | Surr, Recovery Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2081-06MSD</a>  | <a href="#">PQ047212.D</a> | 01 Apr 2020 18:32      | S8-06-AMSD   | PCB                                           | MSD     | 1 | --                                                 | OK       | Surr, Recovery, RPC <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a> |
| <a href="#">L2081-07</a>     | <a href="#">PQ047213.D</a> | 01 Apr 2020 18:49      | S8-07-A      | PCB                                           | SAM     | 1 | AR1254,1260 & AR1268 hits                          | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">L2081-08</a>     | <a href="#">PQ047214.D</a> | 01 Apr 2020 19:05      | S8-08-A      | PCB                                           | SAM     | 1 | Check AR1260 hit                                   | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">L2081-09</a>     | <a href="#">PQ047215.D</a> | 01 Apr 2020 19:21      | S8-09-A      | PCB                                           | SAM     | 1 | AR1254,1260 & AR1268 hits,Need 5X                  | DILUTION | Surr, OR Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>       |
| <a href="#">L2081-10</a>     | <a href="#">PQ047216.D</a> | 01 Apr 2020 19:38      | S8-10-A      | PCB                                           | SAM     | 1 | AR1254,1260 & AR1268 hits                          | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">L2081-26</a>     | <a href="#">PQ047217.D</a> | 01 Apr 2020 19:54      | DUP-10       | PCB                                           | SAM     | 1 | Check AR1260 hit                                   | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">L2082-01</a>     | <a href="#">PQ047218.D</a> | 01 Apr 2020 20:10      | S9-01-A      | PCB                                           | SAM     | 1 | AR1254 hits, confirm hit, Check AR1260 hit         | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">L2084-01</a>     | <a href="#">PQ047219.D</a> | 01 Apr 2020 20:26      | S11-01-A     | PCB                                           | SAM     | 1 | AR1254 & AR1260 hits                               | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">L2086-01</a>     | <a href="#">PQ047220.D</a> | 01 Apr 2020 20:43      | S13-01-A     | PCB                                           | SAM     | 1 | --                                                 | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">L2086-02</a>     | <a href="#">PQ047221.D</a> | 01 Apr 2020 20:59      | S13-02-A     | PCB                                           | SAM     | 1 | --                                                 | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">L2086-03</a>     | <a href="#">PQ047222.D</a> | 01 Apr 2020 21:15      | S13-03-A     | PCB                                           | SAM     | 1 | AR1254,1260 & AR1268 hits                          | OK       | Surr Fail <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>           |
| <a href="#">I.BLK</a>        | <a href="#">PQ047223.D</a> | 01 Apr 2020 21:48      | I.BLK        | PCB                                           | IBLK    | 1 | --                                                 | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">AR1660CCC500</a> | <a href="#">PQ047224.D</a> | 01 Apr 2020 22:37      | AR1660CCC500 | PCB                                           | CCAL500 | 1 | --                                                 | OK       | <input type="text"/> <a href="#">UPDATE</a><br><a href="#">STATUS</a>                     |
| <a href="#">Read Files</a>   |                            | <a href="#">Update</a> |              | <a href="#">All Manual Integration Report</a> |         |   |                                                    |          |                                                                                           |

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved