



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

Dashboard | Edd | Efolder | Fax | Genchem | Projecttrack | Qaqc | Quanttrack | Report | Sequence | Utility |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po121420 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PO073745.D	14 Dec 2020 8:48	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073746.D	14 Dec 2020 9:05	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1242CCC500	PO073747.D	14 Dec 2020 9:22	AR1242CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PO073748.D	14 Dec 2020 9:39	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1262CCC500	PO073749.D	14 Dec 2020 9:58	AR1262CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1268CCC500	PO073750.D	14 Dec 2020 10:16	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PO073751.D	14 Dec 2020 10:33	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
PB133580BL	PO073752.D	14 Dec 2020 10:50	PB133580BL	PCB	MB	1	--	OK	UPDATE STATUS
PB133580BS	PO073753.D	14 Dec 2020 11:07	PB133580BS	PCB	LCS	1	--	OK	UPDATE STATUS
L5042-02	PO073754.D	14 Dec 2020 11:24	KENS-B6-121020-0-6	PCB	SAM	1	--	OK	UPDATE STATUS
		14							

L5042-04MS	PO073755.D	Dec 2020 11:41	KENS-B6-121020-0-6MS	PCB	MS	1	--	OK	UPDATE STATUS
L5042-06MSD	PO073756.D	14 Dec 2020 11:58	KENS-B6-121020-0-6MSD	PCB	MSD	1	--	OK	UPDATE STATUS
L5042-08	PO073757.D	14 Dec 2020 12:15	KENS-B6-121020-13-15	PCB	SAM	1	--	OK	UPDATE STATUS
L5081-01	PO073758.D	14 Dec 2020 12:33	WOOSPK-043-0002	PCB	SAM	10	DCB high in 2nd column, Need cleanup	NotOK	Surr Fail UPDATE STATUS
L5081-02	PO073759.D	14 Dec 2020 12:53	WOOSPK-043-0204	PCB	SAM	1	--	OK	UPDATE STATUS
L5081-03	PO073760.D	14 Dec 2020 13:10	WOOSPK-041-0002	PCB	SAM	1	--	OK	UPDATE STATUS
L5081-04	PO073761.D	14 Dec 2020 13:27	WOOSPK-041-0204	PCB	SAM	1	AR1262 Hits, Need 20X, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
AR1660CCC500	PO073762.D	14 Dec 2020 14:35	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PO073763.D	14 Dec 2020 15:29	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1262CCC500	PO073764.D	14 Dec 2020 15:46	AR1262CCC500	PCB	CCAL500	1	TCMX high in both column	OK	UPDATE STATUS
AR1268CCC500	PO073765.D	14 Dec 2020 16:03	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PO073766.D	14 Dec 2020 16:20	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
PB133603BL	PO073767.D	14 Dec 2020 16:37	PB133603BL	PCB	MB	1	--	OK	UPDATE STATUS
PB133603BS	PO073768.D	14 Dec 2020 16:54	PB133603BS	PCB	LCS	1	--	OK	UPDATE STATUS
L5026-11	PO073769.D	14 Dec 2020 17:11	SB-56(6.5-7.0)	PCB	SAM	1	AR1254 hits, Need 10X	DILUTION	OR Fail UPDATE STATUS
L5026-12	PO073770.D	14 Dec 2020 17:29	SB-56(8.0-8.5)	PCB	SAM	1	AR1254 hits	OK	UPDATE STATUS
L5026-14	PO073771.D	14 Dec 2020 17:46	SB-57(6.5-7.0)	PCB	SAM	1	AR1254 hits, Need 5X	DILUTION	OR Fail UPDATE STATUS
L5026-15	PO073772.D	14 Dec 2020 18:03	SB-57(8.0-8.5)	PCB	SAM	1	AR1254 hits, Need 2X	DILUTION	OR Fail UPDATE STATUS

L5026-26	PO073773.D	14 Dec 2020 18:20	SB-61(4.5-5.0)	PCB	SAM	1	AR1254 hits	OK	UPDATE STATUS
L5026-28	PO073774.D	14 Dec 2020 18:37	SB-61(8.0-8.5)	PCB	SAM	1	AR1254 hits, Confirm hit	OK	UPDATE STATUS
L5026-28MS	PO073775.D	14 Dec 2020 18:54	SB-61(8.0-8.5) MS	PCB	MS	1	--	OK	UPDATE STATUS
L5026-28MSD	PO073776.D	14 Dec 2020 19:11	SB-61(8.0-8.5) MSD	PCB	MSD	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073777.D	14 Dec 2020 19:45	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PO073778.D	14 Dec 2020 20:03	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1262CCC500	PO073779.D	14 Dec 2020 20:20	AR1262CCC500	PCB	CCAL500	1	TCMX high in both column, DCB high in 2nd column	OK	UPDATE STATUS
AR1268CCC500	PO073780.D	14 Dec 2020 20:37	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PO073781.D	14 Dec 2020 20:54	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L5026-27	PO073782.D	14 Dec 2020 21:11	SB-61(6.5-7.0)	PCB	SAM	1	AR1254,1260 hits	OK	UPDATE STATUS
L5081-01	PO073783.D	14 Dec 2020 21:28	WOOSPK-043-0002	PCB	SAM	1	AR1260 Hits, Confirm hit	OK	UPDATE STATUS
L5081-08	PO073784.D	14 Dec 2020 21:45	WOOSPK-039-0204	PCB	SAM	1	AR1262 Hits, Need 100X & DCB high in both column, TCMX high in 1st column, CCC fail for Surrogate	NotOK	UPDATE STATUS Surr, OR Fail
L5081-05	PO073785.D	14 Dec 2020 22:02	WOOSPK-039-0002	PCB	SAM	10	Need cleanup	NotOK	UPDATE STATUS Surr Fail
L5081-06MS	PO073786.D	14 Dec 2020 22:20	WOOSPK-039-0002MS 10X	PCB	MS	10	Need cleanup	NotOK	UPDATE STATUS Surr, Recovery Fail
L5081-07MSD	PO073787.D	14 Dec 2020 22:37	WOOSPK-039-0002MSD 10X	PCB	MSD	10	Need cleanup	NotOK	UPDATE STATUS
L5081-09	PO073788.D	14 Dec 2020 22:54	WOOSPK-051-0002	PCB	SAM	10	AR1262 Hits, All surrogate fail, CCC fail for surrogate	NotOK	UPDATE STATUS Surr Fail
		14					AR1262 Hits, DCB high in both		

L5081-12	PO073789.D	Dec 2020 23:11	WOOSPK-051-0204	PCB	SAM	10	column, TCMX high in 2nd column, CCC fail for surrogate	NotOK	Surr Fail UPDATE STATUS
L5081-13	PO073790.D	14 Dec 2020 23:28	WOOSPK-047-0002	PCB	SAM	10	AR1262 Hits, DCB high in both column, CCC fail	NotOK	Surr Fail UPDATE STATUS
L5081-14	PO073791.D	14 Dec 2020 23:45	WOOSPK-047-0204	PCB	SAM	10	AR1262 Hits, Need 5X, DCB high in both column, CCC fail for surrogate	NotOK	Surr, OR Fail UPDATE STATUS
AR1660CCC500	PO073792.D	15 Dec 2020 00:54	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PO073793.D	15 Dec 2020 1:11	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1262CCC500	PO073794.D	15 Dec 2020 1:28	AR1262CCC500	PCB	CCAL500	1	TCMX high in both column, DCB high in 2nd column	OK	UPDATE STATUS
AR1268CCC500	PO073795.D	15 Dec 2020 1:45	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PO073796.D	15 Dec 2020 2:02	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L5081-15	PO073797.D	15 Dec 2020 2:19	WOOSPK-045-0002	PCB	SAM	10	AR1262 Hits, Need more dilution & DCB high in both column, TCMX high in 1st column, CCC fail for surrogate	NotOK	Surr, OR Fail UPDATE STATUS
L5081-16	PO073798.D	15 Dec 2020 2:36	WOOSPK-045-0204	PCB	SAM	10	AR1262 Hits, DCB high in 2nd column, CCC fail for surrogate	NotOK	Surr Fail UPDATE STATUS
L5081-17	PO073799.D	15 Dec 2020 2:53	WOOSPK-033-0002	PCB	SAM	10	Need cleanup	NotOK	Surr Fail UPDATE STATUS
L5081-18	PO073800.D	15 Dec 2020 3:10	WOOSPK-033-0204	PCB	SAM	10	AR1262 Hits, Need more dilution & DCB high in both column, CCC fail for surrogate	NotOK	Surr, OR Fail UPDATE STATUS
L5081-19	PO073801.D	15 Dec 2020 3:28	WOOSPK-035-0002	PCB	SAM	10	Need cleanup	NotOK	Surr Fail UPDATE STATUS
L5081-20	PO073802.D	15 Dec 2020 3:45	WOOSPK-035-0204	PCB	SAM	10	AR1262 Hits, Need more dilution & DCB high in both column, CCC fail for	NotOK	Surr, OR Fail UPDATE STATUS

							surrogate		
AR1660CCC500	PO073803.D	15 Dec 2020 4:53	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PO073804.D	15 Dec 2020 5:10	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1262CCC500	PO073805.D	15 Dec 2020 6:02	AR1262CCC500	PCB	CCAL500	1	TCMX & DCB high in both column	OK	UPDATE STATUS
AR1268CCC500	PO073806.D	15 Dec 2020 6:19	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PO073807.D	15 Dec 2020 6:36	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved