



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_D

Daily Analysis Runlog For Sequence/QC Batch ID # VD011823

Review By	Krupa Patel	Review On	1/19/2023 7:25:30 PM				
Supervise By	Mahesh Dadoda	Supervise On	1/19/2023 7:27:08 PM				
SubDirectory	VD011823	HP Acquire Method	MSVOA_D	HP Processing Method	82D011823S.0		
STD. NAME		STD REF.#					
Tune/Reschk		VP118035					
Initial Calibration Stds		VP118036,VP118037,VP118038,VP118039,VP118040,VP118041					
CCC							
Internal Standard/PEM							
ICV/I.BLK		VP118042					
Surrogate Standard							
MS/MSD Standard							
LCS Standard							

Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VD075123.D	18 Jan 2023 09:22		KP/SY	Ok
2	VSTDICC005	VSTDICC005	VD075124.D	18 Jan 2023 10:25	Good for DOD	KP/SY	Ok,M
3	VSTDICC010	VSTDICC010	VD075125.D	18 Jan 2023 11:20		KP/SY	Ok,M
4	VSTDICC020	VSTDICC020	VD075126.D	18 Jan 2023 11:48	Comp. #02,13,20 on Linear Regression	KP/SY	Ok,M
5	VSTDICCC050	VSTDICCC050	VD075127.D	18 Jan 2023 12:15		KP/SY	Ok,M
6	VSTDICC100	VSTDICC100	VD075128.D	18 Jan 2023 12:42		KP/SY	Ok,M
7	VSTDICC150	VSTDICC150	VD075129.D	18 Jan 2023 13:10		KP/SY	Ok,M
8	VIBLK	VIBLK	VD075130.D	18 Jan 2023 13:38		KP/SY	Ok
9	VSTDICV050	ICVVD011823	VD075131.D	18 Jan 2023 14:19		KP/SY	Ok,M

M : Manual Integration

Instrument ID: MSVOA_D

Daily Analysis Runlog For Sequence/QC Batch ID # VD012023

Review By	Mahesh Dadoda	Review On	1/25/2023 12:30:15 AM				
Supervise By	Krupa Patel	Supervise On	1/25/2023 4:38:23 AM				
SubDirectory	VD012023	HP Acquire Method	MSVOA_D	HP Processing Method	82d011823s.m		
STD. NAME		STD REF.#					
Tune/Reschk Initial Calibration Stds		VP118097					
CCC		VP118098,VP118099,VP118100-MDL,VP118101-MDL					
Internal Standard/PEM		VP116738					
ICV/I.BLK							
Surrogate Standard							
MS/MSD Standard							
LCS Standard							

Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VD075145.D	20 Jan 2023 10:40		KP/SY	Ok
2	VSTDCCC050	VSTDCCC050	VD075146.D	20 Jan 2023 11:13		KP/SY	Ok,M
3	VD0120SBL04	VD0120SBL04	VD075147.D	20 Jan 2023 12:23		KP/SY	Ok
4	VD0120SBL05	VD0120SBL05	VD075148.D	20 Jan 2023 12:51		KP/SY	Ok
5	VD0120SBS01	VD0120SBS01	VD075149.D	20 Jan 2023 13:18	spike error	KP/SY	Not Ok
6	VD0120SBS02	VD0120SBS02	VD075150.D	20 Jan 2023 13:45		KP/SY	Ok,M
7	O1234-01	EO-02-11923	VD075151.D	20 Jan 2023 14:13	Vial B, Not Purged	KP/SY	Not Ok
8	O1229-01	OK-02-011923	VD075152.D	20 Jan 2023 14:41	Vial B	KP/SY	Ok
9	MDL04	MDL04	VD075153.D	20 Jan 2023 15:08		KP/SY	Ok,M
10	MDL05	MDL05	VD075154.D	20 Jan 2023 15:35		KP/SY	Ok,M
11	O1233-02	B-P34A	VD075155.D	20 Jan 2023 16:03	BS Failed, Internal standard fail	KP/SY	ReRun
12	O1233-03	B-P34B	VD075156.D	20 Jan 2023 16:31	BS Failed	KP/SY	ReRun
13	O1233-04	B-P36A	VD075157.D	20 Jan 2023 16:58	BS Failed	KP/SY	ReRun
14	O1233-05	B-P36B	VD075158.D	20 Jan 2023 17:26	BS Failed , Surrogate fail;Internal standard fail	KP/SY	ReRun
15	O1233-06	B-P37A	VD075159.D	20 Jan 2023 17:54	BS Failed , Not Purged	KP/SY	Not Ok
16	O1233-07	B-P37B	VD075160.D	20 Jan 2023 18:22	BS Failed , Not Purged	KP/SY	Not Ok
17	O1233-08	B-P38A	VD075161.D	20 Jan 2023 18:49	BS Failed , Surrogate fail;Internal standard fail	KP/SY	ReRun
18	O1233-09	B-P38B	VD075162.D	20 Jan 2023 19:17	BS Failed , Internal standard fail	KP/SY	ReRun



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_D

Daily Analysis Runlog For Sequence/QC Batch ID # VD012023

Review By	Mahesh Dadoda	Review On	1/25/2023 12:30:15 AM					
Supervise By	Krupa Patel	Supervise On	1/25/2023 4:38:23 AM					
SubDirectory	VD012023	HP Acquire Method	MSVOA_D	HP Processing Method	82d011823s.m			
STD. NAME		STD REF.#						
Tune/Reschk Initial Calibration Stds		VP118097						
CCC		VP118098,VP118099,VP118100-MDL,VP118101-MDL						
Internal Standard/PEM		VP116738						
ICV/I.BLK								
Surrogate Standard								
MS/MSD Standard								
LCS Standard								

19	O1233-11	B-P38C	VD075163.D	20 Jan 2023 19:45	Not purge;Need MeOH	KP/SY	Not Ok
20	O1240-01	TR-05-011923	VD075164.D	20 Jan 2023 20:13	BS Failed , Internal standard fail	KP/SY	ReRun
21	O1258-01	WASTE-VOA-2	VD075165.D	20 Jan 2023 20:41	Not Purge	KP/SY	Not Ok
22	VSTDCCC050	VSTDCCC050EC	VD075166.D	20 Jan 2023 21:08		KP/SY	Ok,M

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_D

Daily Analysis Runlog For Sequence/QC Batch ID # VD012323

Review By	Mahesh Dadoda	Review On	1/25/2023 12:47:06 AM					
Supervise By	Krupa Patel	Supervise On	1/25/2023 4:39:25 AM					
SubDirectory	VD012323	HP Acquire Method	MSVOA_D	HP Processing Method	82D011823S.M			
STD. NAME		STD REF.#						
Tune/Reschk Initial Calibration Stds CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard		VD118121						
		VP118122,VP118123						
		VP116738						
Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status	
1	BFB	BFB	VD075167.D	23 Jan 2023 09:38		KP/SY	Ok	
2	VSTDCCC050	VSTDCCC050	VD075168.D	23 Jan 2023 10:15		KP/SY	Ok,M	
3	VD0123SBL01	VD0123SBL01	VD075169.D	23 Jan 2023 12:14		KP/SY	Ok	
4	VD0123SBS01	VD0123SBS01	VD075170.D	23 Jan 2023 12:41		KP/SY	Ok,M	
5	VD0123SBSD01	VD0123SBSD01	VD075171.D	23 Jan 2023 13:08		KP/SY	Ok,M	
6	O1233-02	B-P34A	VD075172.D	23 Jan 2023 13:36	Vial B	KP/SY	Ok	
7	O1233-03	B-P34B	VD075173.D	23 Jan 2023 14:04	Vial B	KP/SY	Ok	
8	O1233-04	B-P36A	VD075174.D	23 Jan 2023 14:32	Vial B	KP/SY	Ok	
9	O1233-05RE	B-P36BRE	VD075175.D	23 Jan 2023 15:00	Vial B, ISTD Fail	KP/SY	Confirms	
10	O1233-06	B-P37A	VD075176.D	23 Jan 2023 15:27	Vial B	KP/SY	Ok	
11	O1240-01	TR-05-011923	VD075177.D	23 Jan 2023 15:55	Vial B	KP/SY	Ok	
12	O1233-09RE	B-P38BRE	VD075178.D	23 Jan 2023 16:23	Vial B, ISTD Fail	KP/SY	Confirms	
13	VSTDCCC050	VSTDCCC050EC	VD075179.D	23 Jan 2023 16:50		KP/SY	Ok,M	

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_N

Daily Analysis Runlog For Sequence/QC Batch ID # VN011623

Review By	John Carlone	Review On	1/17/2023 9:37:32 AM				
Supervise By	Krupa Patel	Supervise On	1/17/2023 2:36:23 PM				
SubDirectory	VN011623	HP Acquire Method	HP Processing Method		82N011623W.M		
STD. NAME		STD REF.#					
Tune/Reschk Initial Calibration Stds		VP118000 VP118001,VP118002,VP118003,VP118004,VP118005,VP118006					
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard		VP118007					
Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VN076259.D	16 Jan 2023 09:57		JC\MD	Ok
2	VSTDICC001	VSTDICC001	VN076260.D	16 Jan 2023 10:30	Not used	JC\MD	Not Ok
3	VSTDICC005	VSTDICC005	VN076261.D	16 Jan 2023 10:54		JC\MD	Ok
4	VSTDICC010	VSTDICC010	VN076262.D	16 Jan 2023 11:18		JC\MD	Ok,M
5	VSTDICC020	VSTDICC020	VN076263.D	16 Jan 2023 11:42		JC\MD	Ok,M
6	VSTDICCC050	VSTDICCC050	VN076264.D	16 Jan 2023 12:06		JC\MD	Ok,M
7	VSTDICC075	VSTDICC075	VN076265.D	16 Jan 2023 12:30		JC\MD	Ok,M
8	IBLK	IBLK	VN076266.D	16 Jan 2023 12:53		JC\MD	Ok
9	VSTDICC001	VSTDICC001	VN076267.D	16 Jan 2023 13:17		JC\MD	Ok,M
10	VSTDICV050	ICVVN011623	VN076268.D	16 Jan 2023 14:40		JC\MD	Ok,M

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_N

Daily Analysis Runlog For Sequence/QC Batch ID # VN012023

Review By	John Carlone	Review On	1/23/2023 9:38:40 AM				
Supervise By	Mahesh Dadoda	Supervise On	1/25/2023 12:36:06 AM				
SubDirectory	VN012023	HP Acquire Method	HP Processing Method 82N011623W.M				
STD. NAME		STD REF.#					
Tune/Reschk Initial Calibration Stds		VP118110					
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard		VP118111,VP118112					
Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VN076336.D	20 Jan 2023 09:54		JC\MD	Ok
2	VSTDCCC050	VSTDCCC050	VN076337.D	20 Jan 2023 10:27	pH#Lot#V12668	JC\MD	Ok,M
3	VN0120MBL01	VN0120MBL01	VN076338.D	20 Jan 2023 11:01		JC\MD	Ok
4	VN0120WBL01	VN0120WBL01	VN076339.D	20 Jan 2023 11:25		JC\MD	Ok
5	VN0120WBS01	VN0120WBS01	VN076340.D	20 Jan 2023 11:49		JC\MD	Ok,M
6	VN0120WBSD01	VN0120WBSD01	VN076341.D	20 Jan 2023 12:25		JC\MD	Ok,M
7	IBLK	IBLK	VN076342.D	20 Jan 2023 12:49		JC\MD	Ok
8	O1248-01	STORAGE-BLANK-SO	VN076343.D	20 Jan 2023 13:13	vial A pH<2	JC\MD	Ok
9	O1248-02	STORAGE-BLANK-WA	VN076344.D	20 Jan 2023 13:37	vial A pH<2	JC\MD	Ok
10	O1248-03	STORAGE-BLANK-WA	VN076345.D	20 Jan 2023 14:01	vial A pH<2	JC\MD	Ok
11	O1248-04	STORAGE-BLANK-SAI	VN076346.D	20 Jan 2023 14:25	vial A pH<2	JC\MD	Ok
12	O1233-12	FB01	VN076347.D	20 Jan 2023 14:49	vial A pH<2 FB	JC\MD	Ok
13	O1233-12RE	FB01RE	VN076348.D	20 Jan 2023 15:26	Not Required	JC\MD	Not Ok
14	VN0120MBS01	VN0120MBS01	VN076349.D	20 Jan 2023 16:20		JC\MD	Ok,M
15	VN0120MBSD01	VN0120MBSD01	VN076350.D	20 Jan 2023 16:54		JC\MD	Ok,M
16	O1258-01	WASTE-VOA-2	VN076351.D	20 Jan 2023 17:18	Need 20X	JC\MD	Dilution
17	O1258-01DL	WASTE-VOA-2DL	VN076352.D	20 Jan 2023 18:06		JC\MD	Ok
18	VSTDCCC050	VSTDCCC050EC	VN076353.D	20 Jan 2023 18:30		JC\MD	Ok,M

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_N

Daily Analysis Runlog For Sequence/QC Batch ID # VN012323

Review By	John Carlone	Review On	1/24/2023 9:34:32 AM				
Supervise By	Mahesh Dadoda	Supervise On	1/25/2023 12:39:37 AM				
SubDirectory	VN012323	HP Acquire Method	HP Processing Method		82N011623W.M		
STD. NAME		STD REF.#					
Tune/Reschk Initial Calibration Stds		VP118126					
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard		VP118127,VP118128					

Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VN076354.D	23 Jan 2023 09:44		JC\MD	Ok
2	VSTDCCC050	VSTDCCC050	VN076355.D	23 Jan 2023 10:17		JC\MD	Ok,M
3	VN0123MBL01	VN0123MBL01	VN076356.D	23 Jan 2023 10:51		JC\MD	Ok
4	VN0123WBL01	VN0123WBL01	VN076357.D	23 Jan 2023 11:15		JC\MD	Ok
5	VN0123MBS01	VN0123MBS01	VN076358.D	23 Jan 2023 11:39		JC\MD	Ok,M
6	VN0123MBSD01	VN0123MBSD01	VN076359.D	23 Jan 2023 12:12		JC\MD	Ok,M
7	O1233-11DL	B-P38CDL	VN076360.D	23 Jan 2023 12:36	Run @10X, not match	JC\MD	Not Ok
8	IBLK	IBLK	VN076361.D	23 Jan 2023 13:00		JC\MD	Ok
9	O1233-06	B-P37A	VN076362.D	23 Jan 2023 13:24	Not req	JC\MD	Not Ok
10	O1233-07	B-P37B	VN076363.D	23 Jan 2023 13:48	Not req	JC\MD	Not Ok
11	O1233-11	B-P38C	VN076364.D	23 Jan 2023 14:12	Run @40X	JC\MD	Dilution
12	O1234-01	EO-02-11923	VN076365.D	23 Jan 2023 14:36		JC\MD	Ok
13	VN0123WBS01	VN0123WBS01	VN076366.D	23 Jan 2023 15:00		JC\MD	Ok,M
14	O1233-11DL	B-P38CDL	VN076367.D	23 Jan 2023 15:25		JC\MD	Ok
15	VN0123WBSD01	VN0123WBSD01	VN076368.D	23 Jan 2023 15:48		JC\MD	Ok,M
16	VSTDCCC050	VSTDCCC050EC	VN076369.D	23 Jan 2023 17:06		JC\MD	Ok,M

M : Manual Integration

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY011623

Review By	Krupa Patel	Review On	1/17/2023 2:36:16 PM				
Supervise By	Mahesh Dadoda	Supervise On	1/17/2023 2:38:16 PM				
SubDirectory	VY011623	HP Acquire Method	MSVOA_Y	HP Processing Method	82y011623s.m		
STD. NAME		STD REF.#					
Tune/Reschk		VP117988					
Initial Calibration Stds		VP117989,VP117990,VP117991,VP117992,VP117993,VP117994					
CCC		VP117996					
Internal Standard/PEM		VP116738					
ICV/I.BLK		VP117995					
Surrogate Standard							
MS/MSD Standard							
LCS Standard							

Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VY012193.D	16 Jan 2023 09:00		KP/MD	Ok
2	VSTDICC005	VSTDICC005	VY012194.D	16 Jan 2023 12:17		KP/MD	Ok,M
3	VSTDICC010	VSTDICC010	VY012195.D	16 Jan 2023 13:03		KP/MD	Ok,M
4	VSTDICC020	VSTDICC020	VY012196.D	16 Jan 2023 13:26		KP/MD	Ok,M
5	VSTDICCC050	VSTDICCC050	VY012197.D	16 Jan 2023 13:48		KP/MD	Ok,M
6	VSTDICC100	VSTDICC100	VY012198.D	16 Jan 2023 14:11		KP/MD	Ok,M
7	VSTDICC150	VSTDICC150	VY012199.D	16 Jan 2023 14:34		KP/MD	Ok,M
8	VIBLK	VIBLK	VY012200.D	16 Jan 2023 14:58		KP/MD	Ok
9	VSTDICV050	ICVVY011623	VY012201.D	16 Jan 2023 15:21		KP/MD	Ok,M
10	VY0116SBL01	VY0116SBL01	VY012202.D	16 Jan 2023 16:21		KP/MD	Ok
11	O1100-05	WASTE	VY012203.D	16 Jan 2023 16:45	Vial A	KP/MD	Ok
12	VY0116SBS01	VY0116SBS01	VY012204.D	16 Jan 2023 17:08		KP/MD	Ok,M
13	VY0116SBSD01	VY0116SBSD01	VY012205.D	16 Jan 2023 17:31		KP/MD	Ok,M
14	O1159-01	TP-E	VY012206.D	16 Jan 2023 17:55	Vial A	KP/MD	Ok
15	O1160-01	B-04-SB02	VY012207.D	16 Jan 2023 18:18	Vial A	KP/MD	Ok
16	O1125-01RE	B-04-SB01RE	VY012208.D	16 Jan 2023 18:42	Vial B, ISTD Fail	KP/MD	Confirms
17	O1157-01	TR-4-011323	VY012209.D	16 Jan 2023 19:05	Vial A, Not purged well	KP/MD	Not Ok
18	O1133-08	TOT-VOC	VY012210.D	16 Jan 2023 19:29	Vial A	KP/MD	Ok
19	VSTDCCC050	VSTDCCC050EC	VY012211.D	16 Jan 2023 19:51		KP/MD	Ok,M



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY011623

Review By	Krupa Patel	Review On	1/17/2023 2:36:16 PM
Supervise By	Maresh Dadoda	Supervise On	1/17/2023 2:38:16 PM
SubDirectory	VY011623	HP Acquire Method	MSVOA_Y HP Processing Method 82y011623s.m
STD. NAME	STD REF.#		
Tune/Reschk	VP117988		
Initial Calibration Stds	VP117989,VP117990,VP117991,VP117992,VP117993,VP117994		
CCC	VP117996		
Internal Standard/PEM	VP116738		
ICV/I.BLK	VP117995		
Surrogate Standard			
MS/MSD Standard			
LCS Standard			

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY012323

Review By		Review On						
Supervise By		Supervise On						
SubDirectory		VY012323	HP Acquire Method		MSVOA_Y	HP Processing Method		82y011623s.m
STD. NAME		STD REF.#						
Tune/Reschk Initial Calibration Stds		VP118120						
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard		VP118124,VP118125 VP116738						
Sr#	SampleId	ClientID	Data File Name	Date-Time	Comment	Operator	Status	
1	BFB	BFB	VY012306.D	23 Jan 2023 10:03		KP/MD	Ok	
2	VSTDCCC050	VSTDCCC050	VY012307.D	23 Jan 2023 12:09		KP/MD	Ok,NR	
3	VY0123SBL01	VY0123SBL01	VY012308.D	23 Jan 2023 13:04		KP/MD	Ok	
4	VY0123SBS01	VY0123SBS01	VY012309.D	23 Jan 2023 13:27		KP/MD	Ok,M	
5	VY0123SBSD01	VY0123SBSD01	VY012310.D	23 Jan 2023 13:50		KP/MD	Ok,M	
6	O1232-04	B-P18A	VY012311.D	23 Jan 2023 14:14	Vial B	KP/MD	Ok	
7	O1232-06	B-P19A	VY012312.D	23 Jan 2023 14:37	Vial B	KP/MD	Ok	
8	O1232-07	B-P19B	VY012313.D	23 Jan 2023 15:01	Vial B, Not purged well	KP/MD	Not Ok	
9	O1232-09RE	B-P35BRE	VY012314.D	23 Jan 2023 15:24	Vial B, ISTD Fail and surr fail	KP/MD	Confirms	
10	O1233-07	B-P37B	VY012315.D	23 Jan 2023 15:48	Vial B, Internal Standard and Surrogate Fail	KP/MD	Ok	
11	O1233-08RE	B-P38ARE	VY012316.D	23 Jan 2023 16:11	Vial B, Surrogate fail;Internal standard fail	KP/MD	Confirms	
12	O1244-02	VNJ-223	VY012317.D	23 Jan 2023 16:34	Vial A	KP/MD	Ok	
13	O1251-05	TOT-VOC-1	VY012318.D	23 Jan 2023 16:58	Vial A, ISTD Fail	KP/MD	ReRun	
14	O1251-06	TOT-VOC-2	VY012319.D	23 Jan 2023 17:21	Vial A	KP/MD	Ok	
15	O1251-11	TOT-VOC-3	VY012320.D	23 Jan 2023 17:45	Vial A, ISTD Fail	KP/MD	ReRun	
16	O1251-12	TOT-VOC-4	VY012321.D	23 Jan 2023 18:08	Vial A, ISTD Fail	KP/MD	ReRun	
17	O1237-02	3A	VY012322.D	23 Jan 2023 18:31	Vial B, Not Purge	KP/MD	Not Ok	
18	O1254-01	HR-04-012023	VY012323.D	23 Jan 2023 18:55	Vial A, ISTD Fail	KP/MD	ReRun	



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY012323

Review By		Review On									
Supervise By		Supervise On									
SubDirectory		VY012323		HP Acquire Method		MSVOA_Y		HP Processing Method		82y011623s.m	
STD. NAME		STD REF.#									
Tune/Reschk Initial Calibration Stds		VP118120									
CCC		VP118124,VP118125									
Internal Standard/PEM		VP116738									
ICV/I.BLK											
Surrogate Standard											
MS/MSD Standard											
LCS Standard											

19	O1253-01	SU-04-012023	VY012324.D	23 Jan 2023 19:18	Vial A, Surrogate Fail	KP/MD	ReRun
20	O1243-01	TJRC-11823-B4-0-10	VY012325.D	23 Jan 2023 19:42	Vial A	KP/MD	Ok
21	O1243-03	TJRC-11823-B4-10-20	VY012326.D	23 Jan 2023 20:05	Vial A, Surrogate Fail	KP/MD	ReRun
22	O1243-05	TJRC-011923-B4-20-30	VY012327.D	23 Jan 2023 20:29	Vial A	KP/MD	Ok
23	O1243-07	TJRC-011923-B4-30-40	VY012328.D	23 Jan 2023 20:52	Vial A, ISTD Fail	KP/MD	ReRun
24	VSTDCCC050	VSTDCCC050EC	VY012329.D	23 Jan 2023 21:15		KP/MD	Ok,M

M : Manual Integration