



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QC Batch ID # VX042523

Review By	John Carlone	Review On	4/26/2023 9:41:43 AM
Supervise By	Krupa Patel	Supervise On	4/26/2023 1:38:22 PM
SubDirectory	VX042523	HP Acquire Method	HP Processing Method 82X042523W.M
STD. NAME	STD REF.#		
Tune/Reschk Initial Calibration Stds	VP120077 VP120095,VP120096,VP120097,VP120098,VP120099,VP120100		
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard	VP120078,VP120094 VP120101		

Sr#	SampleID	Data File Name	Date-Time	Operator	Status
1	BFB	VX035269.D	25 Apr 2023 08:57	JC/MD	Ok
2	VSTDCCC050	VX035270.D	25 Apr 2023 09:25	JC/MD	Not Ok
3	IBLK	VX035271.D	25 Apr 2023 09:51	JC/MD	Ok
4	VSTDICC001	VX035272.D	25 Apr 2023 10:37	JC/MD	Ok,M
5	VSTDICC005	VX035273.D	25 Apr 2023 11:00	JC/MD	Ok,M
6	VSTDICC020	VX035274.D	25 Apr 2023 11:23	JC/MD	Ok,M
7	VSTDICCC050	VX035275.D	25 Apr 2023 11:46	JC/MD	Ok,M
8	VSTDICC100	VX035276.D	25 Apr 2023 12:09	JC/MD	Not Ok
9	VSTDICC150	VX035277.D	25 Apr 2023 12:32	JC/MD	Ok,M
10	IBLK	VX035278.D	25 Apr 2023 12:56	JC/MD	Ok
11	VSTDICC100	VX035279.D	25 Apr 2023 13:21	JC/MD	Ok,M
12	IBLK	VX035280.D	25 Apr 2023 13:44	JC/MD	Ok
13	VSTDICV050	VX035281.D	25 Apr 2023 14:10	JC/MD	Ok,M
14	VX0425MBL01	VX035282.D	25 Apr 2023 14:40	JC/MD	Ok
15	VX0425WBL01	VX035283.D	25 Apr 2023 15:03	JC/MD	Ok
16	O2406-01	VX035284.D	25 Apr 2023 15:26	JC/MD	Ok
17	O2431-01	VX035285.D	25 Apr 2023 15:50	JC/MD	Ok
18	O2431-02	VX035286.D	25 Apr 2023 16:13	JC/MD	Ok
19	O2403-01DL	VX035287.D	25 Apr 2023 16:36	JC/MD	Ok
20	O2403-07DL	VX035288.D	25 Apr 2023 17:00	JC/MD	Ok
21	O2403-13DL	VX035289.D	25 Apr 2023 17:23	JC/MD	Ok
22	VX0425MBS01	VX035290.D	25 Apr 2023 17:46	JC/MD	Ok,M
23	VX0425MBSD01	VX035291.D	25 Apr 2023 18:09	JC/MD	Ok,M



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QC Batch ID # VX042523

Review By	John Carlone	Review On	4/26/2023 9:41:43 AM		
Supervise By	Krupa Patel	Supervise On	4/26/2023 1:38:22 PM		
SubDirectory	VX042523	HP Acquire Method		HP Processing Method	82X042523W.M
STD. NAME	STD REF.#				
Tune/Reschk	VP120077				
Initial Calibration Stds	VP120095,VP120096,VP120097,VP120098,VP120099,VP120100				
CCC	VP120078,VP120094				
Internal Standard/PEM					
ICV/I.BLK	VP120101				
Surrogate Standard					
MS/MSD Standard					
LCS Standard					

24	VX0425WBS01	VX035292.D	25 Apr 2023 18:32	JC/MD	Ok,M
25	VX0425WBSD01	VX035293.D	25 Apr 2023 18:55	JC/MD	Ok,M
26	IBLK	VX035294.D	25 Apr 2023 19:18	JC/MD	Ok
27	O2423-17	VX035295.D	25 Apr 2023 19:42	JC/MD	Ok
28	O2429-01	VX035296.D	25 Apr 2023 20:05	JC/MD	Ok
29	VSTDCCC050	VX035297.D	25 Apr 2023 20:28	JC/MD	Ok,M

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QC Batch ID # VX051023

Review By	John Carlone	Review On	5/11/2023 10:02:29 AM
Supervise By	Krupa Patel	Supervise On	5/11/2023 12:16:17 PM
SubDirectory	VX051023	HP Acquire Method	HP Processing Method 82X042523W.M
STD. NAME	STD REF.#		
Tune/Reschk Initial Calibration Stds	VP120449		
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard	VP120450,VP120451		

Sr#	SampleId	Data File Name	Date-Time	Operator	Status
1	BFB	VX035576.D	10 May 2023 09:41	JC/MD	Ok
2	VSTDCCC050	VX035577.D	10 May 2023 11:03	JC/MD	Ok,M
3	VX0510MBL01	VX035578.D	10 May 2023 11:39	JC/MD	Ok
4	VX0510WBL01	VX035579.D	10 May 2023 12:02	JC/MD	Ok
5	VX0510MBS01	VX035580.D	10 May 2023 12:30	JC/MD	Ok,M
6	VX0510MBSD01	VX035581.D	10 May 2023 13:07	JC/MD	Ok,M
7	O2666-01	VX035582.D	10 May 2023 13:30	JC/MD	Ok
8	O2505-05ME	VX035583.D	10 May 2023 13:53	JC/MD	Ok
9	VX0510WBS01	VX035584.D	10 May 2023 14:17	JC/MD	Ok,M
10	VX0510WBSD01	VX035585.D	10 May 2023 14:50	JC/MD	Ok,M
11	O2658-05	VX035586.D	10 May 2023 15:14	JC/MD	Ok
12	O2648-03DL	VX035587.D	10 May 2023 15:37	JC/MD	Ok
13	VX0510MBSD01	VX035588.D	10 May 2023 16:00	JC/MD	Ok,M
14	O2658-07DL	VX035589.D	10 May 2023 16:23	JC/MD	Ok,M
15	O2719-14	VX035590.D	10 May 2023 16:46	JC/MD	ReRun
16	O2723-12	VX035591.D	10 May 2023 17:10	JC/MD	Ok
17	O2719-12	VX035592.D	10 May 2023 17:33	JC/MD	Ok
18	O2746-03	VX035593.D	10 May 2023 17:56	JC/MD	Ok
19	O2743-07	VX035594.D	10 May 2023 18:19	JC/MD	Ok
20	O2744-01	VX035595.D	10 May 2023 18:43	JC/MD	Dilution
21	O2742-01	VX035596.D	10 May 2023 19:06	JC/MD	ReRun
22	O2652-04	VX035597.D	10 May 2023 19:29	JC/MD	Ok
23	VSTDCCC050	VX035598.D	10 May 2023 19:52	JC/MD	Ok,M



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_X

Daily Analysis Runlog For Sequence/QC Batch ID # VX051023

Review By	John Carlone	Review On	5/11/2023 10:02:29 AM
Supervise By	Krupa Patel	Supervise On	5/11/2023 12:16:17 PM
SubDirectory	VX051023	HP Acquire Method	HP Processing Method 82X042523W.M
STD. NAME	STD REF.#		
Tune/Reschk Initial Calibration Stds	VP120449		
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard	VP120450,VP120451		

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY042423

Review By	Krupa Patel	Review On	4/25/2023 2:57:10 PM		
Supervise By	Mahesh Dadoda	Supervise On	4/25/2023 2:58:19 PM		
SubDirectory	VY042423	HP Acquire Method	MSVOA_Y	HP Processing Method	82y042423s.m
STD. NAME		STD REF.#			
Tune/Reschk		VP120034,VP120070			
Initial Calibration Stds		VP120035,VP120036,VP120037,VP120038,VP120039,VP120040			
CCC		VP120042,VP120068,VP120069			
Internal Standard/PEM		VP116738			
ICV/I.BLK		VP120042			
Surrogate Standard					
MS/MSD Standard					
LCS Standard					

Sr#	SampleId	Data File Name	Date-Time	Operator	Status
1	BFB	VY013391.D	24 Apr 2023 09:12	KP/MD	Ok
2	VSTDICV050	VY013392.D	24 Apr 2023 10:23	KP/MD	Not Ok
3	VSTDICCC005	VY013393.D	24 Apr 2023 11:26	KP/MD	Ok,M
4	VSTDICCC010	VY013394.D	24 Apr 2023 11:48	KP/MD	Ok,M
5	VSTDICCC020	VY013395.D	24 Apr 2023 12:11	KP/MD	Ok,M
6	VSTDICCC050	VY013396.D	24 Apr 2023 12:34	KP/MD	Ok,M
7	VSTDICCC100	VY013397.D	24 Apr 2023 12:56	KP/MD	Ok,M
8	VSTDICCC150	VY013398.D	24 Apr 2023 13:19	KP/MD	Ok,M
9	VIBLK	VY013399.D	24 Apr 2023 13:43	KP/MD	Ok
10	VSTDICV050	VY013400.D	24 Apr 2023 14:26	KP/MD	Ok,M
11	VY0424SBL01	VY013401.D	24 Apr 2023 15:24	KP/MD	Ok
12	VY0424SBS01	VY013402.D	24 Apr 2023 15:52	KP/MD	Ok,M
13	VY0424SBSD01	VY013403.D	24 Apr 2023 16:15	KP/MD	Ok,M
14	O2406-01RE	VY013404.D	24 Apr 2023 16:40	KP/MD	Not Ok
15	O2406-03	VY013405.D	24 Apr 2023 17:03	KP/MD	Ok
16	O2371-01	VY013406.D	24 Apr 2023 17:26	KP/MD	Not Ok
17	O2371-03	VY013407.D	24 Apr 2023 17:50	KP/MD	Not Ok
18	O2371-05RE	VY013408.D	24 Apr 2023 18:13	KP/MD	Confirms
19	O2371-07	VY013409.D	24 Apr 2023 18:37	KP/MD	Ok
20	O2371-09RE	VY013410.D	24 Apr 2023 19:00	KP/MD	Confirms
21	O2371-11RE	VY013411.D	24 Apr 2023 19:24	KP/MD	Confirms
22	O2371-15RE	VY013412.D	24 Apr 2023 19:47	KP/MD	Confirms
23	O2371-17	VY013413.D	24 Apr 2023 20:10	KP/MD	Ok

Daily Analysis Runlog For Sequence/QC Batch ID # VY042423

Review By	Krupa Patel	Review On	4/25/2023 2:57:10 PM
Supervise By	Maresh Dadoda	Supervise On	4/25/2023 2:58:19 PM
SubDirectory	VY042423	HP Acquire Method	MSVOA_Y
		HP Processing Method	82y042423s.m

STD. NAME	STD REF.#
Tune/Reschk	VP120034,VP120070
Initial Calibration Stds	VP120035,VP120036,VP120037,VP120038,VP120039,VP120040
CCC	VP120042,VP120068,VP120069
Internal Standard/PEM	VP116738
ICV/I.BLK	VP120042
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

24	VSTDCCC050	VY013414.D	24 Apr 2023 20:33	KP/MD	Ok,M
25	BFB	VY013415.D	24 Apr 2023 22:49	KP/MD	Ok
26	VSTDCCC050	VY013416.D	24 Apr 2023 23:34	KP/MD	Ok,M
27	VY0424SBL02	VY013417.D	25 Apr 2023 00:21	KP/MD	Ok
28	VY0424SBS02	VY013418.D	25 Apr 2023 00:44	KP/MD	Ok,M
29	VY0424SBSD02	VY013419.D	25 Apr 2023 01:29	KP/MD	Ok,M
30	O2427-01	VY013420.D	25 Apr 2023 01:54	KP/MD	Ok
31	O2427-02	VY013421.D	25 Apr 2023 02:17	KP/MD	Ok
32	O2427-03	VY013422.D	25 Apr 2023 02:40	KP/MD	Not Ok
33	O2427-04	VY013423.D	25 Apr 2023 03:04	KP/MD	Ok
34	O2389-14	VY013424.D	25 Apr 2023 03:27	KP/MD	Ok
35	O2389-18	VY013425.D	25 Apr 2023 03:51	KP/MD	Ok
36	O2389-22	VY013426.D	25 Apr 2023 04:14	KP/MD	Ok
37	O2389-26	VY013427.D	25 Apr 2023 04:38	KP/MD	Ok
38	O2389-30	VY013428.D	25 Apr 2023 05:01	KP/MD	ReRun
39	O2423-02	VY013429.D	25 Apr 2023 05:24	KP/MD	ReRun
40	O2423-06	VY013430.D	25 Apr 2023 05:48	KP/MD	Ok
41	O2423-10	VY013431.D	25 Apr 2023 06:11	KP/MD	Ok
42	O2423-14	VY013432.D	25 Apr 2023 06:35	KP/MD	Ok
43	O2390-02	VY013433.D	25 Apr 2023 06:58	KP/MD	Ok
44	O2390-06	VY013434.D	25 Apr 2023 07:22	KP/MD	ReRun
45	VSTDCCC050	VY013435.D	25 Apr 2023 07:44	KP/MD	Ok,M

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY050323

Review By	Mahesh Dadoda	Review On	5/4/2023 2:01:40 PM		
Supervise By	Krupa Patel	Supervise On	5/4/2023 2:09:49 PM		
SubDirectory	VY050323	HP Acquire Method	MSVOA_Y	HP Processing Method	82Y042423S.M
STD. NAME		STD REF.#			
Tune/Reschk Initial Calibration Stds		VP120322			
CCC Internal Standard/PEM ICV/I.BLK Surrogate Standard MS/MSD Standard LCS Standard		VP120320,VP120321 VP116738			

Sr#	SampleId	Data File Name	Date-Time	Operator	Status
1	BFB	VY013568.D	03 May 2023 09:07	KP/MD	Ok
2	VSTDCCC050	VY013569.D	03 May 2023 09:38	KP/MD	Ok,M
3	VY0503SBL01	VY013570.D	03 May 2023 10:43	KP/MD	Ok
4	VY0503SBS01	VY013571.D	03 May 2023 11:05	KP/MD	Ok,M
5	VY0503SBSD01	VY013572.D	03 May 2023 11:28	KP/MD	Ok,M
6	O2568-01	VY013573.D	03 May 2023 11:52	KP/MD	Not Ok
7	O2569-01	VY013574.D	03 May 2023 12:16	KP/MD	Ok
8	O2558-07	VY013575.D	03 May 2023 12:39	KP/MD	Ok
9	O2558-08	VY013576.D	03 May 2023 13:03	KP/MD	Ok
10	O2558-06	VY013577.D	03 May 2023 13:26	KP/MD	Ok
11	O2554-01RE	VY013578.D	03 May 2023 13:49	KP/MD	Confirms
12	VIBLK	VY013579.D	03 May 2023 14:13	KP/MD	Ok
13	O2500-24	VY013580.D	03 May 2023 14:36	KP/MD	Dilution
14	VIBLK	VY013581.D	03 May 2023 15:00	KP/MD	Ok
15	O2567-02RE	VY013582.D	03 May 2023 15:23	KP/MD	Confirms
16	O2500-24DL	VY013583.D	03 May 2023 15:46	KP/MD	Ok
17	O2573-02	VY013584.D	03 May 2023 16:11	KP/MD	ReRun
18	O2582-01	VY013585.D	03 May 2023 16:34	KP/MD	Ok
19	O2584-01	VY013586.D	03 May 2023 16:57	KP/MD	Ok
20	O2585-01	VY013587.D	03 May 2023 17:21	KP/MD	Ok
21	O2571-01	VY013588.D	03 May 2023 17:44	KP/MD	Ok
22	O2559-02	VY013589.D	03 May 2023 18:08	KP/MD	Ok
23	O2505-04	VY013590.D	03 May 2023 18:31	KP/MD	ReRun



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY050323

Review By	Mahesh Dadoda	Review On	5/4/2023 2:01:40 PM		
Supervise By	Krupa Patel	Supervise On	5/4/2023 2:09:49 PM		
SubDirectory	VY050323	HP Acquire Method	MSVOA_Y	HP Processing Method	82Y042423S.M
STD. NAME	STD REF.#				
Tune/Reschk Initial Calibration Stds	VP120322				
CCC	VP120320,VP120321				
Internal Standard/PEM	VP116738				
ICV/I.BLK					
Surrogate Standard					
MS/MSD Standard					
LCS Standard					
24	VSTDCCC050	VY013591.D	03 May 2023 18:54	KP/MD	Ok,M

M : Manual Integration



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Instrument ID: MSVOA_Y

Daily Analysis Runlog For Sequence/QC Batch ID # VY050423

Review By	Krupa Patel	Review On	5/5/2023 11:53:24 AM		
Supervise By	Maresh Dadoda	Supervise On	5/5/2023 11:54:06 AM		
SubDirectory	VY050423	HP Acquire Method	MSVOA_Y	HP Processing Method	82Y042423S.M
STD. NAME		STD REF.#			
Tune/Reschk Initial Calibration Stds		VP120322			
CCC		VP120323,VP120324			
Internal Standard/PEM		VP116738			
ICV/I.BLK					
Surrogate Standard					
MS/MSD Standard					
LCS Standard					

Sr#	SampleId	Data File Name	Date-Time	Operator	Status
1	BFB	VY013592.D	04 May 2023 09:17	KP/MD	Ok
2	VSTDCCC050	VY013593.D	04 May 2023 10:51	KP/MD	Ok,M
3	VY0504SBL01	VY013594.D	04 May 2023 12:56	KP/MD	Ok
4	VY0504SBS01	VY013595.D	04 May 2023 13:18	KP/MD	Ok,M
5	VY0504SBSD01	VY013596.D	04 May 2023 13:41	KP/MD	Ok,M
6	O2573-02RE	VY013597.D	04 May 2023 14:05	KP/MD	Confirms
7	O2505-05	VY013598.D	04 May 2023 14:29	KP/MD	Dilution
8	O2598-04	VY013599.D	04 May 2023 14:52	KP/MD	Ok
9	VIBLK	VY013600.D	04 May 2023 15:16	KP/MD	Ok
10	O2598-01	VY013601.D	04 May 2023 15:39	KP/MD	Ok
11	O2607-01	VY013602.D	04 May 2023 16:02	KP/MD	Ok
12	O2605-01	VY013603.D	04 May 2023 16:26	KP/MD	Not Ok
13	O2604-01	VY013604.D	04 May 2023 16:49	KP/MD	Ok
14	O2505-04RE	VY013605.D	04 May 2023 17:13	KP/MD	Confirms
15	O2588-05	VY013606.D	04 May 2023 17:36	KP/MD	Ok
16	O2588-08	VY013607.D	04 May 2023 18:00	KP/MD	Ok
17	O2588-10	VY013608.D	04 May 2023 18:23	KP/MD	Ok
18	O2588-11	VY013609.D	04 May 2023 18:46	KP/MD	Ok
19	O2588-15	VY013610.D	04 May 2023 19:10	KP/MD	Ok
20	O2588-06	VY013611.D	04 May 2023 19:33	KP/MD	Ok
21	VSTDCCC050	VY013612.D	04 May 2023 19:56	KP/MD	Ok,M

M : Manual Integration