

284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

NEW JERSEY LAB ID#:20012 : NEW YORK LAB ID#: 11376

## GENERAL CHEMISTRY CONFORMANCE/NON-CONFORMANCE SUMMARY

2.Matrix Spike Recoveries Meet Criteria  ff not met, list those compounds and their recoveries which fall outside of the acceptance range:  MS MSD NOTANAYZED AS NO ENOUGH VOLUME PROVIDED.  3. Sample Duplicate Analysis Meet QC Criteria:  If not met, list those compounds and their % differences which fall outside of the acceptance range:  DUP NOT ANAYZED AS NO ENOUGH VOLUME PROVIDED.  4. Analysis Holding Time Met:  If not met, list number of days exceeded for each sample:	QA REVIEW	Date	Date		
1. Blank Contamination  If YES, list compounds and concentrations in each blank:  2.Matrix Spike Recoveries Meet Criteria  If not met, list those compounds and their recoveries which fall outside of the acceptance range:  MS MSD NOTANAYZED AS NO ENOUGH VOLUME PROVIDED.	Analyst jignesh	Date	03/15/2024		
1. Blank Contamination  If YES, list compounds and concentrations in each blank:  2.Matrix Spike Recoveries Meet Criteria  If not met, list those compounds and their recoveries which fall outside of the acceptance range:  MS MSD NOTANAYZED AS NO ENOUGH VOLUME PROVIDED.  3. Sample Duplicate Analysis Meet QC Criteria:  If not met, list those compounds and their % differences which fall outside of the acceptance range:  DUP NOT ANAYZED AS NO ENOUGH VOLUME PROVIDED.					
1. Blank Contamination  If YES, list compounds and concentrations in each blank:  2.Matrix Spike Recoveries Meet Criteria  If not met, list those compounds and their recoveries which fall outside of the acceptance range:  MS MSD NOTANAYZED AS NO ENOUGH VOLUME PROVIDED.  3. Sample Duplicate Analysis Meet QC Criteria:  If not met, list those compounds and their % differences which fall outside of the acceptance range:  DUP NOT ANAYZED AS NO ENOUGH VOLUME PROVIDED.					
1. Blank Contamination  If YES, list compounds and concentrations in each blank:  2. Matrix Spike Recoveries Meet Criteria  If not met, list those compounds and their recoveries which fall outside of the acceptance range:  MS MSD NOTANAYZED AS NO ENOUGH VOLUME PROVIDED.  3. Sample Duplicate Analysis Meet QC Criteria:  If not met, list those compounds and their % differences which fall outside of the acceptance range:  DUP NOT ANAYZED AS NO ENOUGH VOLUME PROVIDED.	ADDITIONAL COMMENTS:				
1. Blank Contamination  If YES, list compounds and concentrations in each blank:  2. Matrix Spike Recoveries Meet Criteria  If not met, list those compounds and their recoveries which fall outside of the acceptance range:  MS MSD NOTANAYZED AS NO ENOUGH VOLUME PROVIDED.  3. Sample Duplicate Analysis Meet QC Criteria:  If not met, list those compounds and their % differences which fall outside of the acceptance range:					
1. Blank Contamination  If YES, list compounds and concentrations in each blank:  2.Matrix Spike Recoveries Meet Criteria  If not met, list those compounds and their recoveries which fall outside of the acceptance range:	If not met, list those compounds and their % differences which fall outside of the a	cceptance range:			
1. Blank Contamination ✓	If not met, list those compounds and their recoveries which fall outside of the acce	ptance range:			
NA NO YES					
CHEMTECH QC BATCHID: LB129904	CHEMTECH QC BATCHID. LB129904		NA	NO	YES