



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:	po031224	Instrument	ECD_o
-----------	----------	------------	-------

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
AR1660ICC050	PO102413.D	AR-1016-3 #2	yogesh	3/13/2024 8:17:29 AM	Ankita	3/13/2024 9:40:28	Peak Integrated by Software incorrectly
AR1248ICC050	PO102425.D	AR-1248-2	yogesh	3/13/2024 8:17:31 AM	Ankita	3/13/2024 9:40:30	Peak Integrated by Software incorrectly



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

PO031424

Instrument

ECD_o

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
AR1660CCC500	PO102486.D	AR-1016-5	yogesh	3/15/2024 7:53:23 AM	Ankita	3/15/2024 10:14:00	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-1	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-1 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-2 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-3	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-3 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-4	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-4 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-5	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1016-5 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1260-1	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1260-1 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

PO031424

Instrument

ECD_o

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
PB159600BS	PO102527.D	AR-1260-2 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1260-3	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1260-3 #2	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BS	PO102527.D	AR-1260-5	yogesh	3/15/2024 7:53:38 AM	Ankita	3/15/2024 10:14:13	Peak Integrated by Software incorrectly
PB159600BSD	PO102528.D	AR-1016-1	yogesh	3/15/2024 7:53:40 AM	Ankita	3/15/2024 10:14:15	Peak Integrated by Software incorrectly
PB159600BSD	PO102528.D	AR-1260-5	yogesh	3/15/2024 7:53:40 AM	Ankita	3/15/2024 10:14:15	Peak Integrated by Software incorrectly
P1747-03	PO102530.D	Decachlorobiphenyl #2	yogesh	3/15/2024 7:53:41 AM	Ankita	3/15/2024 10:14:16	Peak Integrated by Software incorrectly
P1747-03	PO102530.D	Tetrachloro-m-xylene	yogesh	3/15/2024 7:53:41 AM	Ankita	3/15/2024 10:14:16	Peak Integrated by Software incorrectly
P1747-03	PO102530.D	Tetrachloro-m-xylene #2	yogesh	3/15/2024 7:53:41 AM	Ankita	3/15/2024 10:14:16	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1016-1 #2	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1016-2 #2	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1016-3 #2	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1016-4 #2	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Manual Integration Report

Sequence:

PO031424

Instrument

ECD_o

Sample ID	File ID	Parameter	Review By	Review On	Supervised By	Supervised On	Reason
AR1660CCC500	PO102531.D	AR-1260-2	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1260-3	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1260-4	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1260-5	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly
AR1660CCC500	PO102531.D	AR-1260-5 #2	yogesh	3/15/2024 7:53:43 AM	Ankita	3/15/2024 10:14:18	Peak Integrated by Software incorrectly