



284 Sheffield Street, Mountainside, NJ 07092 Phone: 908 789 8900 Fax: 908 789 8922

Laboratory Control Sample/Laboratory Control Sample Duplicate Summary

SW-846

SDG No.: P1747

Client: LiRo Engineers, Inc.

Analytical Method: 8081B

Datafile : PL088616.D

Lab Sample ID	Parameter	Spike	Result	Units	Rec	RPD	Qual	RPD	Low	Limits	RPD
								Qual		High	
PB159588BS	alpha-BHC	0.5	0.51	ug/L	102				85	130	
	beta-BHC	0.5	0.49	ug/L	98				83	126	
	delta-BHC	0.5	0.46	ug/L	93				69	141	
	gamma-BHC (Lindane)	0.5	0.50	ug/L	99				82	129	
	Heptachlor	0.5	0.51	ug/L	101				79	127	
	Aldrin	0.5	0.49	ug/L	98				79	126	
	Heptachlor epoxide	0.5	0.50	ug/L	100				81	124	
	Endosulfan I	0.5	0.50	ug/L	101				85	122	
	Dieldrin	0.5	0.51	ug/L	101				83	125	
	4,4'-DDE	0.5	0.51	ug/L	101				80	127	
	Endrin	0.5	0.50	ug/L	101				81	128	
	Endosulfan II	0.5	0.50	ug/L	100				82	123	
	4,4'-DDD	0.5	0.50	ug/L	100				77	131	
	Endosulfan sulfate	0.5	0.50	ug/L	99				76	129	
	4,4'-DDT	0.5	0.51	ug/L	102				80	133	
	Methoxychlor	0.5	0.48	ug/L	96				76	137	
	Endrin ketone	0.5	0.50	ug/L	100				80	131	
	Endrin aldehyde	0.5	0.52	ug/L	103				82	127	
	alpha-Chlordane	0.5	0.51	ug/L	103				82	125	
	gamma-Chlordane	0.5	0.53	ug/L	105				82	125	