

164296
9:05

WORKLIST(Hardcopy Internal Chain)

WorkList Name : P4518N WorkList ID : 184766 Department : Extraction Date : 10-25-2024 08:45:25

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P4495-16	PT-NJEPH-SOIL	Solid	EPH	Cool 4 deg C	CHEM02	QA Of	10/21/2024	NJEPH
P4518-01	EX-5-TPH-1	Solid	EPH	Cool 4 deg C	ENTA05	K61	10/23/2024	NJEPH
P4518-02	EX-5-TPH-2	Solid	EPH	Cool 4 deg C	ENTA05	K61	10/23/2024	NJEPH
P4518-03	EX-5-TPH-3	Solid	EPH	Cool 4 deg C	ENTA05	K61	10/23/2024	NJEPH
P4518-04	EX-5-TPH-4	Solid	EPH	Cool 4 deg C	ENTA05	K61	10/23/2024	NJEPH
P4518-05	EX-5-TPH-5	Solid	EPH	Cool 4 deg C	ENTA05	K61	10/23/2024	NJEPH
P4531-01	OR-03-102424	Solid	EPH_NF	Cool 4 deg C	PSEG05	K61	10/24/2024	NJEPH
P4531-02	OR-03-102424-E2	Solid	EPH_NF	Cool 4 deg C	PSEG05	K61	10/24/2024	NJEPH
P4545-01	VNJ-215	Solid	EPH_NF	Cool 4 deg C	PSEG03	K61	10/24/2024	NJEPH
P4547-01	BP-F-21	Solid	EPH_NF	Cool 4 deg C	PSEG03	K51	10/24/2024	NJEPH
P4547-02	BP-F-21-EPH	Solid	EPH_NF	Cool 4 deg C	PSEG03	K51	10/24/2024	NJEPH
P4547-05	BP-F-20	Solid	EPH_NF	Cool 4 deg C	PSEG03	K51	10/24/2024	NJEPH
P4547-06	BP-F-20-EPH	Solid	EPH_NF	Cool 4 deg C	PSEG03	K51	10/24/2024	NJEPH

Date/Time 10/25/24 9:00
Raw Sample Received by: RJ (get lab)
Raw Sample Relinquished by: [Signature]

Date/Time 10/25/24 9:30
Raw Sample Received by: [Signature]
Raw Sample Relinquished by: RJ (get lab)