

Manual Integration Report

Sample ID	ClientID ID	File ID	Sequence ID	Parameter	Supervised By	Supervised On	Reason
50 TRPH STD		FF014707.D	FF102124	N-DECANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-DOCOSANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-DODECANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-DOTRIACONTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-EICOSANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-HEXACOSANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-HEXADECANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-HEXATRIACONTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-OCTACOSANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-OCTADECANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-OCTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-OCTATRIACONTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-TETRACONTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-TETRACOSANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-TETRADECANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-TETRATRIACONTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	N-TRIACONTANE	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly
50 TRPH STD		FF014707.D	FF102124	TETRACOSANE-d50 (SURROGA	Ankita	10/22/2024 8:58:29 AM	Peak Integrated by Software incorrectly

Manual Integration Report

Sample ID	ClientID ID	File ID	Sequence ID	Parameter	Supervised By	Supervised On	Reason
RT MARKER		FF014758.D	FF102424	N-OCTACOSANE	Ankita	10/25/2024 11:44:20 AM	Peak Integrated by Software incorrectly
P4495-14		FF014761.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:21 AM	Peak Integrated by Software incorrectly
50 PPM TRPH STD		FF014764.D	FF102424	N-HEXADECANE	Ankita	10/25/2024 11:44:22 AM	Peak Integrated by Software incorrectly
50 PPM TRPH STD		FF014764.D	FF102424	N-TETRACOSANE	Ankita	10/25/2024 11:44:22 AM	Peak Integrated by Software incorrectly
P4518-01		FF014765.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:24 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-DOCOSANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-DODECANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-DOTRIACONTANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-EICOSANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-HEXACOSANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-HEXADECANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-OCTACOSANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-OCTADECANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-OCTATRIACONTANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-TETRACONTANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-TETRACOSANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-TETRADECANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-TETRATRIACONTANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	N-TRIACONTANE	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MS		FF014766.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:27 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-DOCOSANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-DODECANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly

Manual Integration Report

P4518-01MSD		FF014767.D	FF102424	N-DOTRIACONTANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-EICOSANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-HEXACOSANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-HEXADECANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-HEXATRIACONTANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-OCTACOSANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-OCTADECANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-OCTATRIACONTANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-TETRACOSANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-TETRADECANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-TETRATRIACONTANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	N-TRIACONTANE	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-01MSD		FF014767.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:29 AM	Peak Integrated by Software incorrectly
P4518-05		FF014768.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:31 AM	Peak Integrated by Software incorrectly
P4518-04		FF014769.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:32 AM	Peak Integrated by Software incorrectly
P4518-03		FF014770.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:34 AM	Peak Integrated by Software incorrectly
P4518-02		FF014771.D	FF102424	TETRACOSANE-d50 (SURROGA	Ankita	10/25/2024 11:44:36 AM	Peak Integrated by Software incorrectly
50 PPM TRPH STD		FF014773.D	FF102424	N-TETRACOSANE	Ankita	10/25/2024 11:44:39 AM	Peak Integrated by Software incorrectly

Manual Integration Report

Sample ID	ClientID ID	File ID	Sequence ID	Parameter	Supervised By	Supervised On	Reason
P4518-01		FF014779.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:32 AM	Peak Integrated by Software incorrectly
P4518-03		FF014782.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:34 AM	Peak Integrated by Software incorrectly
.BLK		FF014786.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:35 AM	Peak Integrated by Software incorrectly
50 PPM TRPH STD		FF014787.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:37 AM	Peak Integrated by Software incorrectly
.BLK		FF014788.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:39 AM	Peak Integrated by Software incorrectly
50 PPM TRPH STD		FF014789.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:40 AM	Peak Integrated by Software incorrectly
PB164426BS		FF014792.D	FF102524	N-HEXATRIACONTANE	Ankita	10/28/2024 10:36:42 AM	Peak Integrated by Software incorrectly
P4509-01		FF014793.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:43 AM	Peak Integrated by Software incorrectly
P4509-01MS		FF014794.D	FF102524	N-HEXATRIACONTANE	Ankita	10/28/2024 10:36:45 AM	Peak Integrated by Software incorrectly
P4509-01MS		FF014794.D	FF102524	N-OCTATRIACONTANE	Ankita	10/28/2024 10:36:45 AM	Peak Integrated by Software incorrectly
P4509-01MS		FF014794.D	FF102524	N-TETRACONTANE	Ankita	10/28/2024 10:36:45 AM	Peak Integrated by Software incorrectly
P4509-01MS		FF014794.D	FF102524	N-TETRATRIACONTANE	Ankita	10/28/2024 10:36:45 AM	Peak Integrated by Software incorrectly
P4509-01MS		FF014794.D	FF102524	N-TRIACONTANE	Ankita	10/28/2024 10:36:45 AM	Peak Integrated by Software incorrectly
P4509-01MSD		FF014795.D	FF102524	N-HEXATRIACONTANE	Ankita	10/28/2024 10:36:46 AM	Peak Integrated by Software incorrectly
P4509-01MSD		FF014795.D	FF102524	N-OCTADECANE	Ankita	10/28/2024 10:36:46 AM	Peak Integrated by Software incorrectly
P4509-01MSD		FF014795.D	FF102524	N-OCTATRIACONTANE	Ankita	10/28/2024 10:36:46 AM	Peak Integrated by Software incorrectly
P4509-01MSD		FF014795.D	FF102524	N-TETRACONTANE	Ankita	10/28/2024 10:36:46 AM	Peak Integrated by Software incorrectly
P4509-01MSD		FF014795.D	FF102524	N-TRIACONTANE	Ankita	10/28/2024 10:36:46 AM	Peak Integrated by Software incorrectly
P4509-01		FF014796.D	FF102524	TETRACOSANE-d50 (SURROGA	Ankita	10/28/2024 10:36:48 AM	Peak Integrated by Software incorrectly
50 PPM TRPH STD		FF014799.D	FF102524	N-TETRACONTANE	Ankita	10/28/2024 10:36:49 AM	Peak Integrated by Software incorrectly