

NEW JERSEY LAB ID#:20012 : NEW YORK LAB ID#: 11376

GENERAL CHEMISTRY CONFORMANCE/NON-CONFORMANCE SUMMARY

CHEMTECH QC BATCHID: LB133262

	NA	NO	YES
1. Blank Contamination	_____	<u>✓</u>	_____
If YES, list compounds and concentrations in each blank:			
2. Matrix Spike Recoveries Meet Criteria	_____	_____	<u>✓</u>
If not met, list those compounds and their recoveries which fall outside of the acceptance range:			
3. Sample Duplicate Analysis Meet QC Criteria:	_____	_____	<u>✓</u>
If not met, list those compounds and their % differences which fall outside of the acceptance			
4. Analysis Holding Time Met :	_____	<u>✓</u>	_____
If not met, list number of days exceeded for each sample:			
SAMPLE RECEIVE OUT OF HOLD.			

ADDITIONAL COMMENTS:

Analyst jignesh

Date 11/03/2024

QA REVIEW

Date

QA Control # A3040188