FORM DC-1 SAMPLE LOG-IN SHEET

| Lab Name : Alliance Technical Group, LLC | Page_1_of_1 | |
|--|-----------------------|--|
| Received By (Print Name) GONSE JESUS | Log-in Date 12/3/2024 | |
| Received By (Signature) | • | |
| Case Number 51879 SDG No. MBHKX9 | MA No. N/A | |

| Remarks: | | |
|---|---------------------------------|--|
| 1. Custody Seal (s) | Present, Intact | |
| 2. Custody Seal Nos. | n/a | |
| 3. Traffic Reports/Chain Of Custody Records | Present | |
| 4. Airbill | Present | |
| 5. Airbill No. and Shipping Container ID No. | 770419013667 1 | |
| Shipping Container Temperature Indicator Bottle | Present | |
| 7. Shipping Container Temperature | 2.3 Degree C | |
| 8. Sample Condition | Intact | |
| 9. Sample Tags Sample Tag Numbers | Absent Listed on Traffic Report | |
| 10. Does information on Traffic Reports/Chain of Custody Records and Sample Tags agree ? | Yes | |
| 11. Date Received at Lab | 12/03/2024 | |
| | | |

| | | | ľ | | |
|----|----------|-----------------|---------------|----------|-----------------------|
| | | | Corresponding | | Remarks: Condition |
| | | Aqueous | i i | | of Sample |
| | EPA | Water Sample | Sample | Assigned | |
| | Sample # | pH | Tag # | Lab # | etc. |
| 1 | мвнкх9 | N/A | 4886 | P5056-01 | Intact |
| 2 | мвнкуо | N/A | 4887 | P5056-02 | Intact |
| 3 | MBHKY1 | | | | |
| _ | | N/A | 4888 | P5056-03 | Intact |
| 4 | МВНКҮ2 | N/A | 4889 | P5056-04 | Intact |
| 5 | МВНКҮЗ | N/A | 4890 | P5056-05 | Intact |
| 6 | МВНКҮ4 | N/A | 4891 | P5056-06 | Intact |
| 7 | мвнкү5 | N/A | 4892 | P5056-07 | Intact |
| 8 | MBHL35 | N/A | 4991 | P5056-08 | Intact |
| 9 | MBHL36 | N/A | 4992 | P5056-09 | Intact |
| 10 | MBHL37 | N/A | 4993 | P5056-10 | Intact |
| 11 | MBHL38 | N/A | 4994 | P5056-11 | Intact |
| 12 | MBHL39 | N/A | 4995 | P5056-12 | Intact |
| 13 | MBHL40 | N/A | 4996 | P5056-13 | Intact |
| 14 | MBHL41 | N/A | 4997 | P5056-14 | Intact |
| 15 | MBHL42 | N/A | 4970 | P5056-15 | Intact |
| 16 | MBHL43 | N/A | 4971 | P5056-16 | Intact |
| 17 | MBHL44 | N/A | 4972 | P5056-17 | Intact |
| 18 | MBHL45 | N/A | 4973 | P5056-18 | Intact |
| 19 | MBHL46 | N/A | 4974 | P5056-19 | Intact |
| 20 | MBHL47 | N/A | 4975 | P5056-20 | Intact |
| 21 | MBHL47D | N/A | 4975 | P5056-21 | Intact |
| 22 | MBHL47S | N/A | 4975 | P5056-22 | Intact |
| 23 | N/A | N/A | N/A | N/A | N/A |

* Contact SMO and attach record of resolution

| Reviewed By | 1 | Logbook No. | N/A |
|-------------|---------|------------------|-----|
| Date | 12/3/24 | Logbook Page No. | N/A |