

FORM DC-1
SAMPLE LOG-IN SHEET

| | |
|---|---|
| Lab Name : Alliance Technical Group, LLC | Page <u>1</u> of <u>1</u> |
| Received By (Print Name) <u>Cezar Pereira</u> | Log-in Date 12/4/2024 |
| Received By (Signature) <u>[Signature]</u> | |
| Case Number 51879 | SDG No. MBHLZ4 MA No. N/A |

| | |
|--|------------------------------------|
| Remarks: | |
| 1. Custody Seal (s) | Present, Intact |
| 2. Custody Seal Nos. | <u>n/a</u> |
| 3. Traffic Reports/Chain Of Custody Records | Present |
| 4. Airbill | Present |
| 5. Airbill No. and Shipping Container ID No. | <u>770459380530</u> <u>1</u> |
| 6. Shipping Container Temperature Indicator Bottle | Present |
| 7. Shipping Container Temperature | <u>2.3</u> Degree C |
| 8. Sample Condition | Intact |
| 9. Sample Tags Sample Tag Numbers | Absent Listed on Traffic Report |
| 10. Does information on Traffic Reports/Chain of Custody Records and Sample Tags agree ? | Yes |
| 11. Date Received at Lab | <u>12/04/2024</u> |
| 12. Time Received | <u>10:20</u> |

| | EPA Sample # | Aqueous/ Water Sample pH | Corresponding | | Remarks: Condition of Sample Shipment, etc. |
|----|--------------|-----------------------------|---------------|----------------|--|
| | | | Sample Tag # | Assigned Lab # | |
| 1 | MBHLZ4 | N/A | 4263 | P5089-01 | Intact |
| 2 | MBHLZ4D | N/A | 4263 | P5089-02 | Intact |
| 3 | MBHLZ4S | N/A | 4263 | P5089-03 | Intact |
| 4 | MBHLZ5 | N/A | 4264 | P5089-04 | Intact |
| 5 | MBHLZ6 | N/A | 4265 | P5089-05 | Intact |
| 6 | MBHLZ7 | N/A | 4266 | P5089-06 | Intact |
| 7 | MBHLZ8 | N/A | 4267 | P5089-07 | Intact |
| 8 | MBHLZ9 | N/A | 4268 | P5089-08 | Intact |
| 9 | MBHM00 | N/A | 4269 | P5089-09 | Intact |
| 10 | MBHM01 | N/A | 4248 | P5089-10 | Intact |
| 11 | MBHM02 | N/A | 4249 | P5089-11 | Intact |
| 12 | MBHM03 | N/A | 4200 | P5089-12 | Intact |
| 13 | MBHM04 | N/A | 4201 | P5089-13 | Intact |
| 14 | MBHM05 | N/A | 4202 | P5089-14 | Intact |
| 15 | MBHM06 | N/A | 4203 | P5089-15 | Intact |
| 16 | MBHM07 | N/A | 4204 | P5089-16 | Intact |
| 17 | MBHM08 | N/A | 4259 | P5089-17 | Intact |
| 18 | MBHM09 | N/A | 4210 | P5089-18 | Intact |
| 19 | MBHM10 | N/A | 4211 | P5089-19 | Intact |
| 20 | MBHM11 | N/A | 4212 | P5089-20 | Intact |
| 21 | MBHM12 | N/A | 4213 | P5089-21 | Intact |
| 22 | MBHM13 | N/A | 4214 | P5089-22 | Intact |
| 23 | N/A | N/A | N/A | N/A | N/A |

* Contact SMO and attach record of resolution

| | |
|--------------------------------|-----------------------------|
| Reviewed By <u>[Signature]</u> | Logbook No. N/A |
| Date <u>12/4/24</u> | Logbook Page No. N/A |