

Instrument ID: MSVOA_L

Daily Analysis Runlog For Sequence/QC Batch ID # VL121124

Review By	Mahesh Dadoda	Review On	12/13/2024 1:50:07 PM
Supervise By	Semsettin Yesilyurt	Supervise On	12/13/2024 1:55:51 PM
SubDirectory	VL121124	HP Acquire Method	TO15AIR.M HP Processing Method VL121124AIR.M

STD. NAME	STD REF.#
Tune/Reschk	AP2557
Initial Calibration Stds	AP2560,AP2561,AP2562
CCC	AP2560
Internal Standard/PEM	AP2557
ICV/I.BLK	AP2558
Surrogate Standard	
MS/MSD Standard	
LCS Standard	

Sr#	SampleID	ClientID	Data File Name	Date-Time	Comment	Operator	Status
1	BFB	BFB	VL041718.D	11 Dec 2024 13:38		SY/MD	Ok
2	VSTDICCC010	VSTDICCC010	VL041719.D	11 Dec 2024 14:10	Method failed for Comp.#13,19,80	SY/MD	Ok,M
3	VSTDICCC002	VSTDICCC002	VL041720.D	11 Dec 2024 14:43		SY/MD	Ok,M
4	VSTDICCC001	VSTDICCC001	VL041721.D	11 Dec 2024 15:14		SY/MD	Ok,M
5	VSTDICCC0.5	VSTDICCC0.5	VL041722.D	11 Dec 2024 15:46		SY/MD	Ok,M
6	VSTDICCC0.1	VSTDICCC0.1	VL041723.D	11 Dec 2024 16:17		SY/MD	Ok,M
7	VSTDICCC0.03	VSTDICCC0.03	VL041724.D	11 Dec 2024 16:48		SY/MD	Ok,M
8	VSTDICCC015	VSTDICCC015	VL041725.D	11 Dec 2024 17:21		SY/MD	Ok,M
9	VSTDICCC002	VSTDICCC002	VL041726.D	11 Dec 2024 17:54	Not used	SY/MD	Not Ok
10	VSTDICV010	ICVVVL121124	VL041727.D	11 Dec 2024 18:57	ICV Failed for comp.#08,13,19,63,80	SY/MD	Ok,M
11	VL1211ABL01	VL1211ABL01	VL041728.D	11 Dec 2024 19:28		SY/MD	Ok
12	VL1211ABS01	VL1211ABS01	VL041729.D	11 Dec 2024 19:59	Recovery failed	SY/MD	Not Ok
13	P4368-14 0.5	LOQ-AIR-02-QT4-2024	VL041730.D	11 Dec 2024 20:31	Method failed	SY/MD	Not Ok
14	P4368-13 0.45	LOD-MDL-AIR-01-QT4	VL041731.D	11 Dec 2024 21:02	Method failed	SY/MD	Not Ok
15	P4368-13 0.40	LOD-MDL-AIR-01-QT4	VL041732.D	11 Dec 2024 21:34	Method failed	SY/MD	Not Ok
16	P4368-13 0.1	LOD-MDL-AIR-01-QT4	VL041733.D	11 Dec 2024 22:05	Method failed	SY/MD	Not Ok
17	P4368-13 0.03	LOD-MDL-AIR-01-QT4	VL041734.D	11 Dec 2024 22:37	Method failed	SY/MD	Not Ok

Instrument ID: MSVOA_L

Daily Analysis Runlog For Sequence/QC Batch ID # VL121124

Review By	Mahesh Dadoda	Review On	12/13/2024 1:50:07 PM		
Supervise By	Semsettin Yesilyurt	Supervise On	12/13/2024 1:55:51 PM		
SubDirectory	VL121124	HP Acquire Method	TO15AIR.M	HP Processing Method	VL121124AIR.M
STD. NAME		STD REF.#			
Tune/Reschk		AP2557			
Initial Calibration Stds		AP2560,AP2561,AP2562			
CCC		AP2560			
Internal Standard/PEM		AP2557			
ICV/I.BLK		AP2558			
Surrogate Standard					
MS/MSD Standard					
LCS Standard					

18	P4368-14 0.03	LOQ-AIR-02-QT4-2024	VL041735.D	11 Dec 2024 23:09	Method failed	SY/MD	Not Ok
19	VL1211ABS02	VL1211ABS02	VL041736.D	11 Dec 2024 23:41		SY/MD	Ok,M
20	VIBLK	VIBLK	VL041737.D	12 Dec 2024 00:13		SY/MD	Ok
21	P5150-02	IA1	VL041738.D	12 Dec 2024 07:52		SY/MD	Ok,M
22	P5150-04	IA3	VL041739.D	12 Dec 2024 08:26	Need 4X	SY/MD	Dilution
23	P5150-06	IA4	VL041740.D	12 Dec 2024 08:59		SY/MD	Ok,M
24	P5150-01	SV1	VL041741.D	12 Dec 2024 09:30	Need 40X	SY/MD	Dilution
25	P5150-03	SV3	VL041742.D	12 Dec 2024 10:01	Need 20X	SY/MD	Dilution
26	P5150-05	SV4	VL041743.D	12 Dec 2024 10:32	no sample to run straight	SY/MD	Ok,M
27	P5150-06DUP	IA4DUP	VL041744.D	12 Dec 2024 11:04		SY/MD	Ok,M
28	P5150-04DL	IA3DL	VL041745.D	12 Dec 2024 11:36		SY/MD	Ok,M
29	P5150-01DL	SV1DL	VL041746.D	12 Dec 2024 12:06		SY/MD	Ok
30	P5150-03DL	SV3DL	VL041747.D	12 Dec 2024 12:37		SY/MD	Ok,M
31	P5150-05	SV4	VL041748.D	12 Dec 2024 13:10	not match.	SY/MD	Not Ok
32	VSTDCCC010	VSTDCCC010EC	VL041749.D	12 Dec 2024 13:41		SY/MD	Ok,M

M : Manual Integration