

10-10-10
10-10-10
10-10-10

WORKLIST(Hardcopy Internal Chain)

WorkList Name : Q1624 WorkList ID : 188464 Department : Extraction Date : 03-24-2025 08:13:26

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
Q1624-01	OK-01-03212025	Solid	EPH_NF	Cool 4 deg C	PSEG05	I11	03/21/2025	NJEPH
Q1624-01	OK-01-03212025	Solid	PCB	Cool 4 deg C	PSEG05	I11	03/21/2025	8082A
Q1624-01	OK-01-03212025	Solid	Pesticide-TCL	Cool 4 deg C	PSEG05	I11	03/21/2025	8081B
Q1624-01	OK-01-03212025	Solid	SVOC-TCL BNA -20	Cool 4 deg C	PSEG05	I11	03/21/2025	8270E
Q1624-02	OK-01-03212025-E2	Solid	EPH_NF	Cool 4 deg C	PSEG05		03/21/2025	NJEPH

Date/Time 03/24/24 8:15
Raw Sample Received by: [Signature]
Raw Sample Relinquished by: [Signature]

Date/Time 03/24/24 8:35
Raw Sample Received by: [Signature]
Raw Sample Relinquished by: [Signature]

WORKLIST(Hardcopy Internal Chain)

WorkList Name : Q1626

WorkList ID : 188486

Department : Extraction

Date : 03-24-2025 10:55:21

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
Q1626-01	CO-32-1	Solid	EPH_NF	Cool 4 deg C	WALS01	F11	03/21/2025	NJEPH
Q1626-01	CO-32-1	Solid	PCB	Cool 4 deg C	WALS01	F11	03/21/2025	8082A
Q1626-01	CO-32-1	Solid	Pesticide-TCL	Cool 4 deg C	WALS01	F11	03/21/2025	8081B
Q1626-01	CO-32-1	Solid	SVOC-TCL BNA -20	Cool 4 deg C	WALS01	F11	03/21/2025	8270E

Date/Time 03/26/24

Raw Sample Received by: RJ (Ext Lab)

Raw Sample Relinquished by: [Signature]

Date/Time 03/24/24

Raw Sample Received by: [Signature]

Raw Sample Relinquished by: [Signature]