

NEW JERSEY LAB ID#:20012 : NEW YORK LAB ID#: 11376

GENERAL CHEMISTRY CONFORMANCE/NON-CONFORMANCE SUMMARY

CHEMTECH QC BATCHID: LB135586

	NA	NO	YES
1. Blank Contamination If YES, list compounds and concentrations in each blank:	_____	_____✓_____	_____
2. Matrix Spike Recoveries Meet Criteria If not met, list those compounds and their recoveries which fall outside of the acceptance range:	_____	_____	_____✓_____
3. Sample Duplicate Analysis Meet QC Criteria: If not met, list those compounds and their % differences which fall outside of the acceptance	_____	_____	_____✓_____
4. Analysis Holding Time Met : If not met, list number of days exceeded for each sample: sample receive out of hold.	_____	_____✓_____	_____

ADDITIONAL COMMENTS:

Analyst jignesh

Date 04/29/2025

 QA REVIEW

 Date

QA Control # A3040188