

5m-8
618691

WORKLIST(Hardcopy Internal Chain)

WorkList Name : Q1916 WorkList ID : 189250 Department : Extraction Date : 05-01-2025 08:37:16

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
Q1907-01	CO-8R-WC	Solid	EPH_NF	Cool 4 deg C	WALS01	L51	04/28/2025	NJEPH
Q1916-01	WC-12	Solid	EPH_NF	Cool 4 deg C	PSEG03	L41	04/30/2025	NJEPH
Q1916-02	WC-12-EPH	Solid	EPH_NF	Cool 4 deg C	PSEG03	L41	04/30/2025	NJEPH
Q1917-01	MH-JJ	Solid	EPH_NF	Cool 4 deg C	PSEG03	L41	04/30/2025	NJEPH
Q1917-02	MH-JJ-EPH	Solid	EPH_NF	Cool 4 deg C	PSEG03	L41	04/30/2025	NJEPH
Q1920-01	291	Solid	EPH_NF	Cool 4 deg C	PSEG03	L31	04/30/2025	NJEPH
Q1920-02	291-E2	Solid	EPH_NF	Cool 4 deg C	PSEG03	L31	04/30/2025	NJEPH
Q1922-01	MH-R	Solid	EPH_NF	Cool 4 deg C	PSEG03	L31	04/30/2025	NJEPH
Q1922-02	MH-R-EPH	Solid	EPH_NF	Cool 4 deg C	PSEG03	L31	04/30/2025	NJEPH
Q1922-05	MH-S	Solid	EPH_NF	Cool 4 deg C	PSEG03	L31	04/30/2025	NJEPH
Q1922-06	MH-S-EPH	Solid	EPH_NF	Cool 4 deg C	PSEG03	L31	04/30/2025	NJEPH
Q1923-01	TR-05-04302025	Solid	EPH_NF	Cool 4 deg C	PSEG05	L31	04/30/2025	NJEPH
Q1923-02	TR-05-04302025-E2	Solid	EPH_NF	Cool 4 deg C	PSEG05	L31	04/30/2025	NJEPH

Date/Time 5/1/25 8:40
Raw Sample Received by: RS (Ext Lab)
Raw Sample Relinquished by: QR sm

Date/Time 5/1/25 9:10
Raw Sample Received by: CP sm
Raw Sample Relinquished by: RS (Ext Lab)