

WORKLIST(Hardcopy Internal Chain)

WorkList Name : Q2507 WorkList ID : 190565 Department : Extraction Date : 07-07-2025 08:25:22

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
Q2507-01	SU-04-7.3-2025	Solid	PCB	Cool 4 deg C	PSEG03	O12	07/04/2025	8082A
Q2509-02	AUD-25-0112	Solid	PCB	Cool 4 deg C	PSEG03	O22	07/03/2025	8082A
Q2510-01	#63025-A	Solid	PCB	Cool 4 deg C	PSEG05	O22	07/03/2025	8082A
Q2513-01	HR-2-070325	Solid	PCB	Cool 4 deg C	PSEG05	O21	07/03/2025	8082A
Q2513-03	HR-3-070325	Solid	PCB	Cool 4 deg C	PSEG05	O21	07/03/2025	8082A
Q2514-01	TP-92	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/02/2025	8082A
Q2514-02	TP-93	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/02/2025	8082A
Q2514-03	TP-94	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/02/2025	8082A
Q2514-04	TP-96	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/02/2025	8082A
Q2514-05	TP-97	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/02/2025	8082A
Q2514-06	TP-103	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/02/2025	8082A
Q2514-07	TP-36	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/03/2025	8082A
Q2514-08	TP-78	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/03/2025	8082A
Q2514-09	TP-81	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/03/2025	8082A
Q2514-10	TP-90	Solid	PCB	Cool 4 deg C	CAMP02	O21	07/03/2025	8082A
Q2515-01	wc-1	Solid	PCB	Cool 4 deg C	ENVO01	O23	07/03/2025	8082A

Date/Time 07/07/25 8:25
Raw Sample Received by: RS (FHA-VAB)
Raw Sample Relinquished by: ITS (M)

Date/Time 07/07/25 8:50
Raw Sample Received by: ITS (M)
Raw Sample Relinquished by: RS (FHA-VAB)