

1647L  
10:48

WORKLIST(Hardcopy Internal Chain)

WorkList Name : q3116      WorkList ID : 191899      Department : Extraction      Date : 09-16-2025 10:42:34

| Sample   | Customer Sample | Matrix | Test | Preservative | Customer | Raw Sample Storage Location | Collect Date | Method |
|----------|-----------------|--------|------|--------------|----------|-----------------------------|--------------|--------|
| Q3088-02 | 90525-LQ        | Water  | PCB  | Cool 4 deg C | PSEG03   | D31                         | 09/12/2025   | 8082A  |
| Q3090-01 | 90825-B         | Water  | PCB  | Cool 4 deg C | PSEG03   | D41                         | 09/12/2025   | 8082A  |
| Q3103-01 | TW-WTS-14       | Water  | PCB  | Cool 4 deg C | ENTA05   | J22                         | 09/15/2025   | 8082A  |

Date/Time 9/16/25 10:42  
Raw Sample Received by: RS CETA-CAB  
Raw Sample Relinquished by: \_\_\_\_\_

Date/Time 9/16/25 11:10  
Raw Sample Received by: \_\_\_\_\_  
Raw Sample Relinquished by: RS CETA-1049