



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

Dashboard | Edd | Efolder | Fax | Genchem | Projecttrack | Qaqc | Quanttrack | Report | Sequence | Utility |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 608.3 PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po033120 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
I.BLK	PO067516.D	31 Mar 2020 9:25	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067517.D	31 Mar 2020 14:38	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB127905BL	PO067518.D	31 Mar 2020 15:01	PB127905BL	PCB Group1	MB	1	--	OK	UPDATE STATUS
PB127905BS	PO067519.D	31 Mar 2020 15:18	PB127905BS	PCB Group1	LCS	1	--	OK	UPDATE STATUS
L1752-05	PO067520.D	31 Mar 2020 15:35	HD-02-033020	PCB	SAM	1	--	OK	UPDATE STATUS
L1752-05MS	PO067521.D	31 Mar 2020 15:52	HD-02-033020MS	PCB	MS	1	--	OK	UPDATE STATUS
L1752-05MSD	PO067522.D	31 Mar 2020 16:09	HD-02-033020MSD	PCB	MSD	1	--	OK	UPDATE STATUS
L2007-14	PO067523.D	31 Mar 2020 16:26	K205-7C	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2007-16	PO067524.D	31 Mar 2020 16:43	K205-8C	PCB Group1	SAM	1	AR1260 hits, Need Dilution 2X, End CCC fail high	RERUN	OR Fail UPDATE STATUS
L2007-18	PO067525.D	31 Mar 2020 17:00	K205-9C	PCB Group1	SAM	1	AR1260 hits, Need Dilution 2X, End CCC fail high	RERUN	OR Fail UPDATE STATUS
		31					AR1260 Hits, DCB		

L2007-20	PO067526.D	Mar 2020 17:17	K205-10C	PCB Group1	SAM	1	failing low in both coloumn, End CCC fail high	RERUN	Surr Fail UPDATE STATUS
L2007-22	PO067527.D	31 Mar 2020 17:35	K205-11C	PCB Group1	SAM	1	AR1260 Hits, End CCC fail high	RERUN	UPDATE STATUS
L2071-01	PO067528.D	31 Mar 2020 17:52	INTERIOR-WALL	PCB	SAM	1	AR1242 & AR1254 hits, DCB failing high in 1st , End CCC fail high	RERUN	Surr Fail UPDATE STATUS
L2071-03	PO067529.D	31 Mar 2020 18:09	EXTERIOR-WALL	PCB	SAM	1	AR1242 hits, DCB high in 1st column, End CCC fail high	RERUN	Surr Fail UPDATE STATUS
L2075-01	PO067530.D	31 Mar 2020 18:26	S2-01-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2075-02	PO067531.D	31 Mar 2020 18:43	S2-02-A	PCB Group1	SAM	1	AR1260 hit, End CCC fail high, confirm hit	RERUN	UPDATE STATUS
L2075-03	PO067532.D	31 Mar 2020 19:00	S2-03-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2075-04	PO067533.D	31 Mar 2020 19:17	S2-04-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2075-05	PO067534.D	31 Mar 2020 19:34	S2-05-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2075-06	PO067535.D	31 Mar 2020 19:51	S2-06-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2075-19	PO067536.D	31 Mar 2020 20:08	DUP-1	PCB Group1	SAM	1	AR1260 hit, End CCC fail high, confirm hit	RERUN	UPDATE STATUS
L2078-01	PO067537.D	31 Mar 2020 20:25	S5-01-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
I.BLK	PO067538.D	31 Mar 2020 20:58	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067539.D	31 Mar 2020 21:45	AR1660CCC500	PCB	CCAL500	1	CCAL Failing high for TCMX,DCB,AR1016 & AR1260 in 1st column	OK	CCAL Fail UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)