



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po110220 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PO072965.D	02 Nov 2020 8:39	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
I.BLK	PO072966.D	02 Nov 2020 8:56	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO072967.D	02 Nov 2020 9:31	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1268CCC500	PO072968.D	02 Nov 2020 9:48	AR1268CCC500	PCB	CCAL500	1	CCC failing low	NotOK	CCAL Fail UPDATE STATUS
L4559-07	PO072969.D	02 Nov 2020 11:50	200FB-004-0002	PCB	SAM	1	AR1268 hits, Opening CCC low	NotOK	UPDATE STATUS
L4559-08	PO072970.D	02 Nov 2020 12:07	200FB-004-0204	PCB	SAM	1	AR1268 hits, Opening CCC low, DCB low in both column	NotOK	Surr Fail UPDATE STATUS
L4559-13	PO072971.D	02 Nov 2020 12:24	200FB-005-000.66	PCB	SAM	1	--	OK	UPDATE STATUS
L4559-16	PO072972.D	02 Nov 2020 12:41	200FB-011-0002	PCB	SAM	1	AR1268 hits, Opening CCC low, DCB low in both column	NotOK	Surr Fail UPDATE STATUS
L4559-17	PO072973.D	02 Nov 2020 12:58	200FB-011-0204	PCB	SAM	1	AR1268 hits, Opening CCC low, DCB low in both column, Need 10X	NotOK	Surr, OR Fail UPDATE STATUS
		02 Nov	200FB-008-				AR1268 hits, Opening CCC		

L4557-18	PO072974.D	2020 13:15	0002	PCB	SAM	1	low, DCB high in 2nd column	NotOK	Surr Fail UPDATE STATUS
L4557-19	PO072975.D	02 Nov 2020 13:32	200FB-008- 0204	PCB	SAM	1	AR1268 hits, Opening CCC low	NotOK	UPDATE STATUS
L4557-29	PO072976.D	02 Nov 2020 13:50	200FB-007- 0002	PCB	SAM	1	AR1268 hits, Opening CCC low, DCB low in both column	NotOK	Surr Fail UPDATE STATUS
L4557-30	PO072977.D	02 Nov 2020 14:07	200FB-007- 0204	PCB	SAM	1	AR1268 hits, Opening CCC low	NotOK	UPDATE STATUS
L4559-17DL	PO072978.D	02 Nov 2020 14:24	200FB-011- 0204DL	PCB	SAM	10	AR1268 hits, Opening CCC low, DCB low in both column	NotOK	Surr Fail UPDATE STATUS
I.BLK	PO072979.D	02 Nov 2020 15:15	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO072980.D	02 Nov 2020 15:32	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1268CCC500	PO072981.D	02 Nov 2020 16:41	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB132780BL	PO072982.D	02 Nov 2020 17:33	PB132780BL	EPH_NF	MB	1	TYPO	NotOK	UPDATE STATUS
PB132780BS	PO072983.D	02 Nov 2020 17:50	PB132780BS	EPH_NF	LCS	1	TYPO	NotOK	UPDATE STATUS
PB132735BL	PO072984.D	02 Nov 2020 18:07	PB132735BL	PCB	MB	1	--	OK	UPDATE STATUS
L4541-08RE	PO072985.D	02 Nov 2020 18:24	20-105RE	PCB	SAM	1	DCB low in both column	CONFIRMS	Surr Fail UPDATE STATUS
L4541-10RE	PO072986.D	02 Nov 2020 18:41	2015RE	PCB	SAM	1	DCB low in both column	CONFIRMS	Surr Fail UPDATE STATUS
I.BLK	PO072987.D	02 Nov 2020 18:58	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO072988.D	02 Nov 2020 19:15	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L4565-01	PO072989.D	02 Nov 2020 19:32	FK-GF-02-063- A	PCB	SAM	1	All surrogate failing high	NotOK	Surr Fail UPDATE STATUS
L4565-03	PO072990.D	02 Nov 2020 19:49	FK-GF-02-063- B	PCB	SAM	1	DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4570-01	PO072991.D	02 Nov	MW-PIER-S	PCB	SAM	1	AR1254 hit, DCB high in	OK	Surr Fail UPDATE

		2020 20:07					1st column		STATUS
L4570-02	PO072992.D	02 Nov 2020 20:24	MW-FOUND-T1	PCB	SAM	1	AR1254 hits, F flag in hit	NotOK	UPDATE STATUS
L4607-01	PO072993.D	02 Nov 2020 20:41	LW-06	PCB	SAM	1	--	OK	UPDATE STATUS
L4607-02	PO072994.D	02 Nov 2020 20:58	OW-01	PCB	SAM	1	AR1254 hits	OK	UPDATE STATUS
L4607-03	PO072995.D	02 Nov 2020 21:15	OW-02	PCB	SAM	1	TCMX high in 1st column	OK	Surr Fail UPDATE STATUS
L4607-04	PO072996.D	02 Nov 2020 21:32	OW-05	PCB	SAM	1	TCMX high in 1st column	OK	Surr Fail UPDATE STATUS
L4607-05	PO072997.D	02 Nov 2020 21:49	MW-01	PCB	SAM	1	--	OK	UPDATE STATUS
L4607-06	PO072998.D	02 Nov 2020 22:06	OW-04	PCB	SAM	1	TCMX high in 1st column	OK	Surr Fail UPDATE STATUS
L4564-01	PO072999.D	02 Nov 2020 22:23	FK-GF-03-017- A	PCB	SAM	1	DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4564-03	PO073000.D	02 Nov 2020 22:41	FK-GF-03-017- B	PCB	SAM	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073001.D	02 Nov 2020 23:15	AR1660CCC500	PCB	CCAL500	1	Not required	NotOK	UPDATE STATUS
PB132763BL	PO073002.D	02 Nov 2020 23:32	PB132763BL	PCB	MB	1	--	OK	UPDATE STATUS
PB132763BS	PO073003.D	02 Nov 2020 23:49	PB132763BS	PCB	LCS	1	--	OK	UPDATE STATUS
L4573-01	PO073004.D	03 Nov 2020 00:06	OB-722-EB	PCB	SAM	1	TCMX high in both column, DCB high in 1st column	RERUN	Surr Fail UPDATE STATUS
L4573-03	PO073005.D	03 Nov 2020 00:23	OB-722	PCB	SAM	1	TCMX high in both column, DCB high in 1st column	RERUN	Surr Fail UPDATE STATUS
L4573-04	PO073006.D	03 Nov 2020 00:40	OB-722-X	PCB	SAM	1	All surrogate failing high	NotOK	Surr Fail UPDATE STATUS
L4573-05MS	PO073007.D	03 Nov 2020 00:57	OB-722MS	PCB	MS	1	All surrogate failing high, Original sample NOTOK	NotOK	Surr Fail UPDATE STATUS
L4573-06MSD	PO073008.D	03 Nov 2020 1:15	OB-722MSD	PCB	MSD	1	All surrogate failing high, Original sample	NotOK	Surr Fail UPDATE STATUS

							NOTOK		
I.BLK	PO073009.D	03 Nov 2020 1:32	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073010.D	03 Nov 2020 1:49	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved