



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#) |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence PO110320 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PO073003.D	03 Nov 2020 8:39	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
I.BLK	PO073004.D	03 Nov 2020 8:57	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073005.D	03 Nov 2020 9:33	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1268CCC500	PO073006.D	03 Nov 2020 10:08	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L4559-08	PO073007.D	03 Nov 2020 10:25	200FB-004-0204	PCB	SAM	1	AR1268 hits, DCB high in both column	RERUN	Surr Fail UPDATE STATUS
L4559-16	PO073008.D	03 Nov 2020 10:42	200FB-011-0002	PCB	SAM	1	AR1268 hits, DCB high in both column	RERUN	Surr Fail UPDATE STATUS
L4559-17	PO073009.D	03 Nov 2020 10:59	200FB-011-0204	PCB	SAM	1	AR1268 hits, DCB high in both column, Need 10X	DILUTION	Surr, OR Fail UPDATE STATUS
L4557-18	PO073010.D	03 Nov 2020 11:16	200FB-008-0002	PCB	SAM	1	AR1268 hits, DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4557-19	PO073011.D	03 Nov 2020 11:33	200FB-008-0204	PCB	SAM	1	AR1268 hits	OK	UPDATE STATUS
L4557-29	PO073012.D	03 Nov 2020 11:51	200FB-007-0002	PCB	SAM	1	AR1268 hits, DCB high in both column	RERUN	Surr Fail UPDATE STATUS
		03							

L4557-30	PO073013.D	Nov 2020 12:08	200FB-007-0204	PCB	SAM	1	AR1268 hits	OK	UPDATE STATUS
L4557-17DL	PO073014.D	03 Nov 2020 12:25	200FB-009-0204DL	PCB	SAM	10	AR1268 hits, DCB high in both column	OK	Surr Fail UPDATE STATUS
L4559-07	PO073015.D	03 Nov 2020 12:42	200FB-004-0002	PCB	SAM	1	AR1268 hits	OK	UPDATE STATUS
I.BLK	PO073016.D	03 Nov 2020 12:59	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073017.D	03 Nov 2020 14:26	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1268CCC500	PO073018.D	03 Nov 2020 14:44	AR1268CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB132763BL	PO073019.D	03 Nov 2020 15:01	PB132763BL	PCB	MB	1	--	OK	UPDATE STATUS
PB132763BS	PO073020.D	03 Nov 2020 15:18	PB132763BS	PCB	LCS	1	--	OK	UPDATE STATUS
L4573-01	PO073021.D	03 Nov 2020 15:35	OB-722-EB	PCB	SAM	1	TCMX high in both column	RERUN	Surr Fail UPDATE STATUS
L4573-03	PO073022.D	03 Nov 2020 15:52	OB-722	PCB	SAM	1	DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4373-04	PO073023.D	03 Nov 2020 16:10	L4373-04	PCB	SAM	1	TYPO-correct as L4573-04	NotOK	Surr Fail UPDATE STATUS
L4573-05MS	PO073024.D	03 Nov 2020 16:27	OB-722MS	PCB	MS	1	please check all peaks	OK	Surr Fail UPDATE STATUS
L4573-06MSD	PO073025.D	03 Nov 2020 16:44	OB-722MSD	PCB	MSD	1	please check all peaks	OK	Surr Fail UPDATE STATUS
I.BLK	PO073026.D	03 Nov 2020 17:01	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073027.D	03 Nov 2020 17:18	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073028.D	03 Nov 2020 17:35	AR1660CCC500	PCB	CCAL500	1	DCB high in 1st column	OK	UPDATE STATUS
I.BLK	PO073029.D	03 Nov 2020 17:52	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
PB132761BL	PO073030.D	03 Nov 2020 18:09	PB132761BL	PCB	MB	1	--	OK	Surr Fail UPDATE STATUS

PB132761BS	PO073031.D	03 Nov 2020 18:26	PB132761BS	PCB	LCS	1	--	OK	UPDATE STATUS
PB132779BL	PO073032.D	03 Nov 2020 18:43	PB132779BL	PCB	MB	1	--	OK	UPDATE STATUS
PB132779BS	PO073033.D	03 Nov 2020 19:00	PB132779BS	PCB	LCS	1	Recovery Fail for AR1016 & 1260	NotOK	Recovery Fail UPDATE STATUS
PB132779BSD	PO073034.D	03 Nov 2020 19:18	PB132779BSD	PCB	LCSD	1	Recovery Fail for AR1016 & 1260	NotOK	Recovery Fail UPDATE STATUS
L4564-03MS	PO073035.D	03 Nov 2020 19:35	FK-GF-03-017-BMS	PCB	MS	1	--	OK	Surr Fail UPDATE STATUS
L4564-03MSD	PO073036.D	03 Nov 2020 19:52	FK-GF-03-017-BMSD	PCB	MSD	1	--	OK	Surr Fail UPDATE STATUS
PB132787BL	PO073037.D	03 Nov 2020 20:09	PB132787BL	PCB	MB	1	--	OK	Surr Fail UPDATE STATUS
PB132787BS	PO073038.D	03 Nov 2020 20:26	PB132787BS	PCB	LCS	1	--	OK	UPDATE STATUS
AR1660CCC500	PO073039.D	03 Nov 2020 20:43	AR1660CCC500	PCB	CCAL500	1	CCAL Fail high for DCB,AR1016 & 1260 in 1st column	OK	CCAL Fail UPDATE STATUS
I.BLK	PO073040.D	03 Nov 2020 21:00	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4600-01	PO073041.D	03 Nov 2020 21:17	CRT-17	PCB	SAM	1	DCB having F flag	OK	UPDATE STATUS
L4600-05	PO073042.D	03 Nov 2020 21:34	CRT-23	PCB	SAM	1	--	OK	UPDATE STATUS
L4600-09	PO073043.D	03 Nov 2020 21:51	CRT-19	PCB	SAM	1	DCB having F flag	OK	UPDATE STATUS
L4600-13	PO073044.D	03 Nov 2020 22:09	CRT-6	PCB	SAM	1	DCB having F flag	OK	UPDATE STATUS
L4605-01	PO073045.D	03 Nov 2020 22:26	CRT-01	PCB	SAM	1	--	OK	UPDATE STATUS
L4608-01	PO073046.D	03 Nov 2020 22:43	OIL-1	PCB	SAM	1	AR1260 hits, DCB having F flag	OK	UPDATE STATUS
L4608-02	PO073047.D	03 Nov 2020 23:00	PE-1	PCB	SAM	1	DCB low in 2nd column, Opening & End CCC fail high	NotOK	Surr Fail UPDATE STATUS
		03					DCB low in		

L4608-03	PO073048.D	Nov 2020 23:17	PE-2	PCB	SAM	1	2nd column, Opening & End CCC fail high	NotOK	Surr Fail UPDATE STATUS
L4608-04	PO073049.D	03 Nov 2020 23:34	PE-3	PCB	SAM	1	DCB low in 2nd column, Opening & End CCC fail high	NotOK	Surr Fail UPDATE STATUS
L4608-05	PO073050.D	03 Nov 2020 23:51	PE-4	PCB	SAM	1	DCB low in 2nd column, Opening & End CCC fail high	NotOK	Surr Fail UPDATE STATUS
AR1660CCC500	PO073051.D	04 Nov 2020 00:08	AR1660CCC500	PCB	CCAL500	1	CCAL Fail high for DCB,TCMX, AR1016 & 1260 in 1st column	OK	CCAL Fail UPDATE STATUS
I.BLK	PO073052.D	04 Nov 2020 00:26	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
L4606-01	PO073053.D	04 Nov 2020 00:43	S-1	PCB	SAM	1	DCB having F flag, DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4608-06	PO073054.D	04 Nov 2020 1:00	DUP	PCB	DUP	1	DCB having F flag	OK	UPDATE STATUS
L4609-01	PO073055.D	04 Nov 2020 1:17	12016	PCB	SAM	1	DCB having F flag	OK	UPDATE STATUS
L4609-01MS	PO073056.D	04 Nov 2020 1:34	12016MS	PCB	MS	1	DCB having F flag, Bad chromatogram	NotOK	Surr Fail UPDATE STATUS
L4609-01MSD	PO073057.D	04 Nov 2020 1:51	12016MSD	PCB	MSD	1	TCMX high in 1st column, DCB having F flag, MS is notok, CCC fail	NotOK	Surr Fail UPDATE STATUS
L4565-01RE	PO073058.D	04 Nov 2020 2:08	FK-GF-02-063-ARE	PCB	SAM	1	All surrogate failing high , DCB having F flag	CONFIRMS	Surr Fail UPDATE STATUS
AR1660CCC500	PO073059.D	04 Nov 2020 2:25	AR1660CCC500	PCB	CCAL500	1	CCAL Fail high for DCB,AR1016 & 1260 in 1st column, DCB having F flag	OK	CCAL Fail UPDATE STATUS
I.BLK	PO073060.D	04 Nov 2020 2:42	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)