



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : SOM02.4_PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pq110420 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PQ050858.D	04 Nov 2020 09:48	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
AIBLK03	PQ050859.D	04 Nov 2020 10:04	AIBLK03	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PQ050860.D	04 Nov 2020 10:20	AR1660394	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1242CCC400	PQ050861.D	04 Nov 2020 10:38	AR1242364	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PQ050862.D	04 Nov 2020 10:54	AR1248344	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PQ050863.D	04 Nov 2020 11:29	AR1254334	PCB	CCAL400	1	--	OK	UPDATE STATUS
PB132773BL	PQ050864.D	04 Nov 2020 11:46	ABLK73	PCB	MB	1	--	OK	Surr Fail UPDATE STATUS
PB132773BS	PQ050865.D	04 Nov 2020 12:02	ALCS73	PCB	LCS	1	--	OK	Surr Fail UPDATE STATUS
L4534-01	PQ050866.D	04 Nov 2020 12:18	COBN7	PCB	SAM	1	AR1254 hits	OK	UPDATE STATUS
L4534-02	PQ050867.D	04 Nov 2020 12:35	COBN9	PCB	SAM	1	AR1254 hits, Need dilution, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
		04					AR1248		

L4534-03	PQ050868.D	Nov 2020 12:51	COBP0	PCB	SAM	1	&1254 hits, Need dilution, DCB high in both column	DILUTION	Surr, OR Fail STATUS UPDATE
L4534-04	PQ050869.D	04 Nov 2020 13:07	COBP1	PCB	SAM	1	AR1254 hits, Need dilution, DCB high in both column	DILUTION	Surr, OR Fail STATUS UPDATE
L4534-05	PQ050870.D	04 Nov 2020 13:24	COBP2	PCB	SAM	1	AR1254 hits, Need dilution, DCB high in both column	DILUTION	Surr, OR Fail STATUS UPDATE
L4534-06	PQ050871.D	04 Nov 2020 13:40	COBP3	PCB	SAM	1	AR1254 hits, Need dilution, DCB high in both column	DILUTION	Surr, OR Fail STATUS UPDATE
L4534-07	PQ050872.D	04 Nov 2020 13:57	COBP4	PCB	SAM	1	AR1254 hits, Need cleanup	NotOK	STATUS UPDATE
L4534-08MS	PQ050873.D	04 Nov 2020 14:13	COBP4MS	PCB	MS	1	Recovery Fail for AR1260	OK	Surr, Recovery Fail STATUS UPDATE
L4534-09MSD	PQ050874.D	04 Nov 2020 14:29	COBP4MSD	PCB	MSD	1	Recovery Fail for AR1260, RPD Fail for AR1016	OK	Surr, Recovery, RPD STATUS UPDATE
L4534-07	PQ050875.D	04 Nov 2020 14:45	COBP4	PCB	SAM	1	AR1254 hits	OK	STATUS UPDATE
AIBLK04	PQ050876.D	04 Nov 2020 15:03	AIBLK04	PCB	IBLK	1	--	OK	Surr Fail STATUS UPDATE
AR1660CCC400	PQ050877.D	04 Nov 2020 15:19	AR1660395	PCB	CCAL400	1	--	OK	STATUS UPDATE
AR1248CCC400	PQ050878.D	04 Nov 2020 15:39	AR1248345	PCB	CCAL400	1	--	OK	STATUS UPDATE
AR1254CCC400	PQ050879.D	04 Nov 2020 15:56	AR1254335	PCB	CCAL400	1	--	OK	STATUS UPDATE
L4534-02DL	PQ050880.D	04 Nov 2020 16:12	COBN9DL	PCB	SAM	20	AR1254 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail STATUS UPDATE
L4534-02DL2	PQ050881.D	04 Nov 2020 16:28	COBN9DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail STATUS UPDATE
L4534-03DL	PQ050882.D	04 Nov 2020 16:45	COBP0DL	PCB	SAM	10	AR1248 &1254 hits, Need more dilution, DCB high in both column	DILUTION	Surr Fail STATUS UPDATE
L4534-04DL	PQ050883.D	04 Nov 2020 17:01	COBP1DL	PCB	SAM	20	AR1254 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail STATUS UPDATE
L4534-04DL2	PQ050884.D	04 Nov 2020 17:17	COBP1DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail STATUS UPDATE

L4534-05DL	PQ050885.D	04 Nov 2020 17:34	C0BP2DL	PCB	SAM	20	AR1254 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
L4534-05DL2	PQ050886.D	04 Nov 2020 17:50	C0BP2DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail UPDATE STATUS
L4534-06DL	PQ050887.D	04 Nov 2020 18:07	C0BP3DL	PCB	SAM	20	AR1254 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
L4534-06DL2	PQ050888.D	04 Nov 2020 18:23	C0BP3DL2	PCB	SAM	200	AR1254 hits	OK	Surr Fail UPDATE STATUS
AIBLK05	PQ050889.D	04 Nov 2020 18:56	AIBLK05	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PQ050890.D	04 Nov 2020 19:12	AR1660396	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PQ050891.D	04 Nov 2020 19:28	AR1248346	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PQ050892.D	04 Nov 2020 19:45	AR1254336	PCB	CCAL400	1	--	OK	UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)