



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#) |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 608.3 PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po032620 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
I.BLK	PO067443.D	26 Mar 2020 11:25	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067444.D	26 Mar 2020 11:42	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L2013-08DL	PO067445.D	26 Mar 2020 11:59	GHD1-SB-01-0-52DL	PCB	SAM	2	AR1254 hits, DCB failing high in first column	OK	Surr Fail UPDATE STATUS
L2013-09DL	PO067446.D	26 Mar 2020 12:16	GHD1-SB-0203-0-11DL	PCB	SAM	2	AR1254 hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
L2013-06DL	PO067447.D	26 Mar 2020 12:33	GHD1-1BC-IB-0-5DL	PCB	SAM	5	AR1254 hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
L2013-07DL	PO067448.D	26 Mar 2020 12:50	GHD1-BC-IB-0-5DL	PCB	SAM	5	AR1254 hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
L1754-01	PO067449.D	26 Mar 2020 13:09	NB-08-032420	PCB	SAM	1	--	OK	UPDATE STATUS
L1757-07	PO067450.D	26 Mar 2020 13:25	EO-01-032420	PCB	SAM	1	--	OK	UPDATE STATUS
PB127766BS	PO067451.D	26 Mar 2020 13:42	PB127766BS	PCB	LCS	1	--	OK	UPDATE STATUS
PB127766BSD	PO067452.D	26 Mar 2020 14:00	PB127766BSD	PCB	LCSD	1	--	OK	UPDATE STATUS
		26							

I.BLK	PO067453.D	Mar 2020 14:17	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067454.D	26 Mar 2020 16:43	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L1761-11	PO067455.D	26 Mar 2020 17:02	SU-02-032520	PCB	SAM	1	--	OK	UPDATE STATUS
L2036-01	PO067456.D	26 Mar 2020 17:19	FK-BPM-03-014-ABCD	PCB	SAM	1	--	OK	UPDATE STATUS
L2037-01	PO067457.D	26 Mar 2020 17:36	FK-BPM-01-C4-D4-C4A-D4A	PCB	SAM	1	--	OK	UPDATE STATUS
L2040-01	PO067458.D	26 Mar 2020 17:53	RO-350	PCB	SAM	1	--	OK	UPDATE STATUS
L2040-04	PO067459.D	26 Mar 2020 18:10	RO-06	PCB	SAM	1	--	OK	UPDATE STATUS
L2043-02	PO067460.D	26 Mar 2020 18:27	TP-2A	PCB	SAM	1	--	OK	UPDATE STATUS
L2043-06	PO067461.D	26 Mar 2020 18:44	TP-1A	PCB	SAM	1	DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L2040-07	PO067462.D	26 Mar 2020 19:01	RO-11986	PCB	SAM	1	--	OK	UPDATE STATUS
L2040-10	PO067463.D	26 Mar 2020 19:18	RO-346	PCB	SAM	1	--	OK	UPDATE STATUS
L2040-13	PO067464.D	26 Mar 2020 19:35	RO-209	PCB	SAM	1	--	OK	UPDATE STATUS
I.BLK	PO067465.D	26 Mar 2020 19:52	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067466.D	26 Mar 2020 20:10	AR1660CCC500	PCB	CCAL500	1	CCAL Failing high for TCMX & AR1016 in 1st column	OK	CCAL Fail UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)