



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 608.3 PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po040820 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
I.BLK	PO067733.D	08 Apr 2020 8:17	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067734.D	08 Apr 2020 8:34	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L2165-01	PO067735.D	08 Apr 2020 9:11	2ND-FLOOR	PCB	SAM	10	Already analyzed	NotOK	Surr Fail UPDATE STATUS
L2165-03	PO067736.D	08 Apr 2020 9:28	3RD-FLOOR	PCB	SAM	10	Already analyzed	NotOK	Surr Fail UPDATE STATUS
L2165-02	PO067737.D	08 Apr 2020 11:55	2ND-FLOOR	TCLP PCB	SAM	1	Already analyzed	NotOK	Surr Fail UPDATE STATUS
L2165-04	PO067738.D	08 Apr 2020 12:12	3RD-FLOOR	TCLP PCB	SAM	1	Already analyzed	NotOK	UPDATE STATUS
PB128086BL	PO067739.D	08 Apr 2020 13:06	PB128086BL	PCB Group1	MB	1	--	OK	Surr Fail UPDATE STATUS
PB128086BS	PO067740.D	08 Apr 2020 13:23	PB128086BS	PCB Group1	LCS	1	--	OK	UPDATE STATUS
L2079-06	PO067741.D	08 Apr 2020 13:40	S6-01-B	PCB Group1	SAM	1	AR1254 & AR1268 Hits	OK	UPDATE STATUS
L2079-07	PO067742.D	08 Apr 2020 13:57	S6-02-B	PCB Group1	SAM	1	AR1254 & AR1268 Hits	OK	UPDATE STATUS
		08							

L2079-11	PO067743.D	Apr 2020 14:14	S6-01-C	PCB Group1	SAM	1	AR1254 & AR1268 Hits	OK	UPDATE STATUS
L2079-12	PO067744.D	08 Apr 2020 14:31	S6-02-C	PCB Group1	SAM	1	AR1268 Hits	OK	UPDATE STATUS
L2079-14	PO067745.D	08 Apr 2020 14:49	S6-04-C	PCB Group1	SAM	1	AR1268 Hits, DCB high in both column	RERUN	Surr Fail UPDATE STATUS
L2079-17	PO067746.D	08 Apr 2020 15:06	DUP-8	PCB Group1	SAM	1	AR1268 Hits, Need 5x dilution	DILUTION	Surr, OR Fail UPDATE STATUS
PB128087BL	PO067747.D	08 Apr 2020 15:23	PB128087BL	PCB Group1	MB	1	DCB high in first column	OK	Surr Fail UPDATE STATUS
PB128087BS	PO067748.D	08 Apr 2020 15:40	PB128087BS	PCB Group1	LCS	1	--	OK	Surr Fail UPDATE STATUS
I.BLK	PO067749.D	08 Apr 2020 15:57	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067750.D	08 Apr 2020 16:14	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L2180-01	PO067751.D	08 Apr 2020 16:33	NEWPORT-TP-7FT	PCB	SAM	1	AR1254 & AR1260 Hits	OK	UPDATE STATUS
L2181-01	PO067752.D	08 Apr 2020 16:50	PL-02-04072020	PCB	SAM	1	AR1260 Hits	OK	UPDATE STATUS
L2081-21	PO067753.D	08 Apr 2020 17:07	S8-01-C	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2081-22	PO067754.D	08 Apr 2020 17:25	S8-02-C	PCB Group1	SAM	1	AR1254 Hits	OK	UPDATE STATUS
L2081-23	PO067755.D	08 Apr 2020 17:42	S8-03-C	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2081-24	PO067756.D	08 Apr 2020 17:59	S8-04-C	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2081-25	PO067757.D	08 Apr 2020 18:16	S8-05-C	PCB Group1	SAM	1	AR1254 & AR1268 Hits	OK	UPDATE STATUS
L2081-27	PO067758.D	08 Apr 2020 18:33	DUP-11	PCB Group1	SAM	1	AR1254 Hits	OK	UPDATE STATUS
L2081-27MS	PO067759.D	08 Apr 2020 18:50	DUP-11MS	PCB Group1	MS	1	Recovery Fail for AR1260	OK	Recovery Fail UPDATE STATUS
L2081-27MSD	PO067760.D	08 Apr 2020 19:07	DUP-11MSD	PCB Group1	MSD	1	Recovery Fail for AR1260	OK	Recovery Fail UPDATE STATUS

I.BLK	PO067761.D	08 Apr 2020 19:40	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO067762.D	08 Apr 2020 19:57	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved