



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po092120 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PO071480.D	21 Sep 2020 8:21	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
I.BLK	PO071481.D	21 Sep 2020 8:38	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO071482.D	21 Sep 2020 9:12	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB131718BL	PO071483.D	21 Sep 2020 9:31	PB131718BL	PCB	MB	1	--	OK	UPDATE STATUS
PB131718BS	PO071484.D	21 Sep 2020 9:48	PB131718BS	PCB	LCS	1	--	OK	UPDATE STATUS
L4062-02RE	PO071485.D	21 Sep 2020 10:05	EROC-CF-2RE	PCB	SAM	1	DCB failing high in both column	CONFIRMS	Surr Fail UPDATE STATUS
L4068-03	PO071486.D	21 Sep 2020 10:22	PE-3A-(1-1.5)	PCB	SAM	1	DCB failing high in 1st column	OK	Surr Fail UPDATE STATUS
L4068-05	PO071487.D	21 Sep 2020 10:39	PE-5-(5-5.5)	PCB	SAM	1	DCB failing high in 1st column,	OK	Surr Fail UPDATE STATUS
L4068-06	PO071488.D	21 Sep 2020 10:56	PE-1B-(4.5-5)	PCB	SAM	1	DCB failing high in 1st column	OK	Surr Fail UPDATE STATUS
L4068-08	PO071489.D	21 Sep 2020 11:13	PE-3B-(4.5-5)	PCB	SAM	1	DCB failing high in 1st column	OK	Surr Fail UPDATE STATUS
		21					DCB failing		

L4068-09	PO071490.D	Sep 2020 11:30	PE-4B-(5-5.5)	PCB	SAM	1	high in 1st column	OK	Surr Fail UPDATE STATUS
L4068-10	PO071491.D	21 Sep 2020 11:47	DUPLICATE	PCB	SAM	1	DCB failing high in 1st column	OK	Surr Fail UPDATE STATUS
L3981-05	PO071492.D	21 Sep 2020 12:04	B18-4-6	PCB	SAM	1	DCB failing high in 1st column	OK	Surr Fail UPDATE STATUS
L3981-02RE	PO071493.D	21 Sep 2020 12:21	B17-4-6RE	PCB	SAM	1	AR1254 & AR1260 Hits, DCB failing high in both column	CONFIRMS	Surr Fail UPDATE STATUS
L4071-05	PO071494.D	21 Sep 2020 12:38	MJLW47	PCB	SAM	1	TYPO , AR1260 Hit	NotOK	UPDATE STATUS
L3871-19	PO071495.D	21 Sep 2020 12:56	TR-08-091720	PCB	SAM	1	--	OK	UPDATE STATUS
L3871-13	PO071496.D	21 Sep 2020 13:13	TR-05-091720	PCB	SAM	1	DCB failing high in 1st column & TCMX failing high in 1st column	RERUN	Surr Fail UPDATE STATUS
L3870-06	PO071497.D	21 Sep 2020 13:30	SU-02-091720	PCB	SAM	5	AR1242 Hits	OK	UPDATE STATUS
I.BLK	PO071498.D	21 Sep 2020 13:47	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO071499.D	21 Sep 2020 14:04	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB131614BL	PO071500.D	21 Sep 2020 14:21	PB131614BL	PCB	MB	1	--	OK	UPDATE STATUS
I.BLK	PO071501.D	21 Sep 2020 14:38	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO071502.D	21 Sep 2020 14:55	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L4053-01	PO071503.D	21 Sep 2020 15:12	1813	PCB	SAM	1	AR1260 Hits, TCMX having F flag in 2nd column	NotOK	UPDATE STATUS
L4053-03	PO071504.D	21 Sep 2020 15:29	VNJ-231	PCB	SAM	1	--	OK	UPDATE STATUS
L4057-02	PO071505.D	21 Sep 2020 15:46	JA-DRUM-COMP	PCB	SAM	1	AR1254 Hits	OK	UPDATE STATUS
L4062-01	PO071506.D	21 Sep 2020 16:03	EROC-CF-1	PCB	SAM	1	DCB failing high in 2nd column	OK	Surr Fail UPDATE STATUS
		21							

L4062-03	PO071507.D	Sep 2020 16:20	EROC-NI4-1	PCB	SAM	1	--	OK	UPDATE STATUS
L4062-04	PO071508.D	21 Sep 2020 16:37	EROC-NI4-2	PCB	SAM	1	--	OK	UPDATE STATUS
L4059-03	PO071509.D	21 Sep 2020 16:54	PAV-B33-091720-0-10	PCB	SAM	1	DCB failing high in 1st column	OK	Surr Fail UPDATE STATUS
L4059-05	PO071510.D	21 Sep 2020 17:11	PAV-B33-091720-10-19	PCB	SAM	1	DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4073-01	PO071511.D	21 Sep 2020 17:28	H-1	PCB	SAM	1	All surrogate failing high	NotOK	Surr Fail UPDATE STATUS
PB131750BL	PO071512.D	21 Sep 2020 17:45	PB131750BL	PCB	MB	1	--	OK	UPDATE STATUS
PB131750BS	PO071513.D	21 Sep 2020 18:02	PB131750BS	PCB	LCS	1	--	OK	UPDATE STATUS
L3869-06	PO071514.D	21 Sep 2020 18:19	OR-02-091820	PCB	SAM	1	--	OK	UPDATE STATUS
L4048-01	PO071515.D	21 Sep 2020 18:36	WC-1	PCB	SAM	1	--	OK	UPDATE STATUS
L4048-03	PO071516.D	21 Sep 2020 18:53	WC-2	PCB	SAM	1	--	OK	UPDATE STATUS
L4048-03MS	PO071517.D	21 Sep 2020 19:10	WC-2MS	PCB	MS	1	Recovery Fail for AR1016 & 1260, DCB high in 1st column	OK	Surr, Recovery Fail UPDATE STATUS
L4048-03MSD	PO071518.D	21 Sep 2020 19:28	WC-2MSD	PCB	MSD	1	Recovery Fail for AR1016 & 1260	OK	Surr, Recovery Fail UPDATE STATUS
L4076-01	PO071519.D	21 Sep 2020 19:45	TS-ROC	PCB	SAM	1	DCB high in 1st column	OK	Surr Fail UPDATE STATUS
L4091-01	PO071520.D	21 Sep 2020 20:02	CARLSTADT-TOPSOIL-2020	PCB	SAM	1	--	OK	UPDATE STATUS
I.BLK	PO071521.D	21 Sep 2020 20:19	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO071522.D	21 Sep 2020 20:36	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L4052-01	PO071523.D	21 Sep 2020 20:53	HEF317G-TOP	PCB	SAM	10	AR1254 hit, End CCC failing low	NotOK	UPDATE STATUS
L4052-02	PO071524.D	21 Sep	HED160B-TOP	PCB	SAM	10	End CCC	NotOK	UPDATE

		2020 21:10					failing low		STATUS
L4052-03	PO071525.D	21 Sep 2020 21:27	HEF317G- BOTTOM	PCB	SAM	10	AR1260 hit, End CCC failing low	NotOK	UPDATE STATUS
L4052-04	PO071526.D	21 Sep 2020 21:44	HED160B- BOTTOM	PCB	SAM	10	End CCC failing low	NotOK	UPDATE STATUS
L4052-06	PO071527.D	21 Sep 2020 22:01	CO-76728	PCB	SAM	10	End CCC failing low, TCMX high in 1st column	NotOK	Surr Fail UPDATE STATUS
L4054-01	PO071528.D	21 Sep 2020 22:18	KZZ075N-TOP	PCB	SAM	10	End CCC failing low	NotOK	UPDATE STATUS
L4054-02	PO071529.D	21 Sep 2020 22:36	KZZ075N- BOTTOM	PCB	SAM	10	End CCC failing low	NotOK	UPDATE STATUS
I.BLK	PO071530.D	21 Sep 2020 22:53	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO071531.D	21 Sep 2020 23:10	AR1660CCC500	PCB	CCAL500	1	CCC failing low for AR1016 1st column, AR1260 & DCB both column	NotOK	CCAL Fail UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)