



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#) |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 608.3 PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pq033120 **CHEMTECH-NJ Lab Sequence**

Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
I.BLK	PQ047133.D	31 Mar 2020 09:58	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PQ047134.D	31 Mar 2020 10:15	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB12786BL	PQ047135.D	31 Mar 2020 10:31	PB12786BL	PCB	MB	1	TYPO, DCB failing high in first column	NotOK	Surr Fail UPDATE STATUS
PB12786BS	PQ047136.D	31 Mar 2020 10:47	PB12786BS	PCB	LCS	1	TYPO, DCB failing high in first column & Recovery fail for AR1016 & AR1260	NotOK	Surr, Recovery Fail UPDATE STATUS
PB12786BSD	PQ047137.D	31 Mar 2020 11:03	PB12786BSD	PCB	LCSD	1	TYPO, Recovery fail for AR1016 & AR1260	NotOK	Recovery Fail UPDATE STATUS
L2048-02	PQ047138.D	31 Mar 2020 11:20	GW-1- (DISCHARGE)	PCB	SAM	1	--	OK	UPDATE STATUS
L2031-22	PQ047139.D	31 Mar 2020 11:37	WATER-COMP	PCB	SAM	1	DCB failing low in second column	OK	Surr Fail UPDATE STATUS
L2031-18	PQ047140.D	31 Mar 2020 11:54	DEBRIS-COMP	PCB	SAM	1	--	OK	UPDATE STATUS
L2052-02	PQ047141.D	31 Mar 2020 12:10	SOIL-PILE	PCB	SAM	1	AR1254 Hits	OK	UPDATE STATUS
I.BLK	PQ047142.D	31 Mar 2020	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS

		12:26							
AR1660CCC500	PQ047143.D	31 Mar 2020 13:06	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB127885BL	PQ047144.D	31 Mar 2020 13:48	PB127885BL	PCB	MB	1	--	OK	UPDATE STATUS
PB127885BS	PQ047145.D	31 Mar 2020 14:04	PB127885BS	PCB	LCS	1	--	OK	UPDATE STATUS
L2049-02	PQ047146.D	31 Mar 2020 14:21	SB-3-(1-3)	PCB	SAM	1	--	OK	UPDATE STATUS
L2049-04	PQ047147.D	31 Mar 2020 14:37	SB-4-(1-3)	PCB	SAM	1	--	OK	UPDATE STATUS
L2051-02	PQ047148.D	31 Mar 2020 14:53	SB-2	PCB	SAM	1	--	OK	UPDATE STATUS
L2053-06	PQ047149.D	31 Mar 2020 15:10	TP-15-SA	PCB	SAM	1	--	OK	UPDATE STATUS
L2049-08	PQ047150.D	31 Mar 2020 15:26	SB-4-(10-12)	PCB	SAM	1	--	OK	UPDATE STATUS
L2051-01	PQ047151.D	31 Mar 2020 15:42	SB-1	PCB	SAM	1	AR1254 Hits, Need Dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L2055-02	PQ047152.D	31 Mar 2020 15:58	SB-2-(10-12)	PCB	SAM	1	--	OK	UPDATE STATUS
L2055-04	PQ047153.D	31 Mar 2020 16:15	SB-6-(10-12)	PCB	SAM	1	--	OK	UPDATE STATUS
L2055-04MS	PQ047154.D	31 Mar 2020 16:31	SB-6-(10-12) MS	PCB	MS	1	--	OK	UPDATE STATUS
L2055-04MSD	PQ047155.D	31 Mar 2020 16:47	SB-6-(10-12) MSD	PCB	MSD	1	--	OK	UPDATE STATUS
L2055-05	PQ047156.D	31 Mar 2020 17:04	SB-8-(1-3)	PCB	SAM	1	DCB high in 2nd column	OK	Surr Fail UPDATE STATUS
L2055-06	PQ047157.D	31 Mar 2020 17:20	SB-10-(1-3)	PCB	SAM	1	--	OK	UPDATE STATUS
I.BLK	PQ047158.D	31 Mar 2020 17:36	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PQ047159.D	31 Mar 2020 18:09	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
		31 Mar		PCB					

PB127906BS	PQ047160.D	2020 18:25	PB127906BS	Group1	LCS	1	--	OK	UPDATE STATUS
PB127906BL	PQ047161.D	31 Mar 2020 18:41	PB127906BL	PCB Group1	MB	1	--	OK	UPDATE STATUS
L2076-01	PQ047162.D	31 Mar 2020 18:58	S3-01-A	PCB Group1	SAM	1	DCB high in 2nd column	OK	Surr Fail UPDATE STATUS
L2076-02	PQ047163.D	31 Mar 2020 19:14	S3-02-A	PCB Group1	SAM	1	AR1260 hit, DCB high in 2nd column	OK	Surr Fail UPDATE STATUS
L2076-03	PQ047164.D	31 Mar 2020 19:30	S3-03-A	PCB Group1	SAM	1	AR1260 hit	OK	UPDATE STATUS
L2076-05	PQ047165.D	31 Mar 2020 19:46	S3-05-A	PCB Group1	SAM	1	AR1260 hit	OK	UPDATE STATUS
L2076-06	PQ047166.D	31 Mar 2020 20:03	S3-06-A	PCB Group1	SAM	1	AR1260 hit	OK	UPDATE STATUS
L2076-20	PQ047167.D	31 Mar 2020 20:19	DUP-4	PCB Group1	SAM	1	AR1260 hit	OK	UPDATE STATUS
L2077-01	PQ047168.D	31 Mar 2020 20:35	S4-01-A	PCB Group1	SAM	1	DCB high in 1st column, Check AR1254,1260	OK	Surr Fail UPDATE STATUS
L2077-02	PQ047169.D	31 Mar 2020 20:52	S4-02-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2077-03	PQ047170.D	31 Mar 2020 21:08	S4-05-A	PCB Group1	SAM	1	DCB low in both column	RERUN	Surr Fail UPDATE STATUS
L2077-04	PQ047171.D	31 Mar 2020 21:24	S4-06-A	PCB Group1	SAM	1	DCB low in both column	RERUN	Surr Fail UPDATE STATUS
L2079-01	PQ047172.D	31 Mar 2020 21:41	S6-01-A	PCB Group1	SAM	1	AR1254 hit, Check AR1268	OK	UPDATE STATUS
L2079-04	PQ047173.D	31 Mar 2020 21:57	S6-04-A	PCB Group1	SAM	1	AR1254,1268 hit, Need 5X, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
L2079-05	PQ047174.D	31 Mar 2020 22:13	S6-05-A	PCB Group1	SAM	1	AR1254,1268 hit, Need 5X, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS
L2079-16	PQ047175.D	31 Mar 2020 22:29	DUP-7	PCB Group1	SAM	1	AR1260 hit, confirm hit	OK	UPDATE STATUS
L2080-02	PQ047176.D	31 Mar 2020 22:46	S7-02-A	PCB Group1	SAM	1	AR1254,1260 hit, confirm hit	OK	UPDATE STATUS
L2080-03	PQ047177.D	31 Mar 2020 23:02	S7-03-A	PCB Group1	SAM	1	AR1254,1268 hit & DCB high in both column	RERUN	Surr Fail UPDATE STATUS

L2080-03MS	PQ047178.D	31 Mar 2020 23:18	S7-03-AMS	PCB Group1	MS	1	DCB high in both column, Recovery Fail for AR1260	OK	Surr, Recovery Fail UPDATE STATUS
L2080-03MSD	PQ047179.D	31 Mar 2020 23:35	S7-03-AMSD	PCB Group1	MSD	1	DCB high in both column, Recovery Fail for AR1260	OK	Surr, Recovery Fail UPDATE STATUS
I.BLK	PQ047180.D	31 Mar 2020 23:51	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PQ047181.D	01 Apr 2020 00:24	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved