



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

Dashboard | Edd | Efolder | Fax | Genchem | Projecttrack | Qaqc | Quanttrack | Report | Sequence | Utility |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 608.3 PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pq040220 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
I.BLK	PQ047225.D	02 Apr 2020 10:22	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PQ047226.D	02 Apr 2020 10:39	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L2076-04	PQ047227.D	02 Apr 2020 11:03	S3-04-A	PCB Group1	SAM	1	AR1260 Hits, DCB low in first column	OK	Surr Fail UPDATE STATUS
L2074-01	PQ047228.D	02 Apr 2020 11:20	S1-01-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2084-03	PQ047229.D	02 Apr 2020 11:36	S11-03-A	PCB Group1	SAM	1	--	OK	UPDATE STATUS
L2079-03DL	PQ047230.D	02 Apr 2020 11:52	S6-03-ADL	PCB Group1	SAM	15	AR1254 & AR1268 hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
L2081-09DL	PQ047231.D	02 Apr 2020 12:25	S8-09-ADL	PCB Group1	SAM	5	AR1254, AR1260 & AR1268 hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
L2081-06DL	PQ047232.D	02 Apr 2020 12:41	S8-06-ADL	PCB Group1	SAM	2	AR1254, AR1260 & AR1268 hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
L2051-01DL	PQ047233.D	02 Apr 2020 12:57	SB-1DL	PCB	SAM	2	AR1254 Hits, DCB high in both column & TCMX in first column	OK	Surr Fail UPDATE STATUS

L2097-15	PQ047234.D	02 Apr 2020 13:14	40788	PCB	SAM	1	--	OK	UPDATE STATUS
L2097-13	PQ047235.D	02 Apr 2020 13:30	317205	PCB	SAM	1	--	OK	UPDATE STATUS
L2085-09	PQ047236.D	02 Apr 2020 13:46	S12-09-A	PCB Group1	SAM	1	AR1260 hits, DCB low in 1st column	OK	Surr Fail UPDATE STATUS
L2085-10	PQ047237.D	02 Apr 2020 14:02	S12-10-A	PCB Group1	SAM	1	DCB low in both column	RERUN	Surr Fail UPDATE STATUS
L2085-20	PQ047238.D	02 Apr 2020 14:19	DUP-14	PCB Group1	SAM	1	AR1254 hits	OK	UPDATE STATUS
L2097-14	PQ047239.D	02 Apr 2020 14:35	40789	PCB	SAM	1	--	OK	UPDATE STATUS
L2097-12	PQ047240.D	02 Apr 2020 14:51	40772	PCB	SAM	1	--	OK	UPDATE STATUS
L2094-03	PQ047241.D	02 Apr 2020 15:08	95-63-64	PCB	SAM	1	--	OK	UPDATE STATUS
L2096-01	PQ047242.D	02 Apr 2020 15:24	RO-1-2-TP	PCB	SAM	1	--	OK	UPDATE STATUS
L2096-01MS	PQ047243.D	02 Apr 2020 15:40	RO-1-2-TPMS	PCB	MS	1	--	OK	UPDATE STATUS
L2096-01MSD	PQ047244.D	02 Apr 2020 15:57	RO-1-2-TPMSD	PCB	MSD	1	--	OK	UPDATE STATUS
I.BLK	PQ047245.D	02 Apr 2020 16:13	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PQ047246.D	02 Apr 2020 17:13	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L2097-20	PQ047247.D	02 Apr 2020 17:30	COMP-3	PCB	SAM	1	--	OK	UPDATE STATUS
L2097-16	PQ047248.D	02 Apr 2020 17:46	40851	PCB	SAM	1	--	OK	UPDATE STATUS
L2097-18	PQ047249.D	02 Apr 2020 18:02	COMP-1	PCB	SAM	1	--	OK	UPDATE STATUS
L2097-19	PQ047250.D	02 Apr 2020 18:19	COMP-2	PCB	SAM	1	--	OK	UPDATE STATUS
L2073-01	PQ047251.D	02 Apr 2020	32272-32273-21719-COMP	PCB	SAM	1	--	OK	UPDATE STATUS

		18:35							
L2094-01	PQ047252.D	02 Apr 2020 18:51	65-66-67	PCB	SAM	1	--	OK	UPDATE STATUS
L2133-04	PQ047253.D	02 Apr 2020 19:08	SMALL-HOUSE-WALLS	PCB	SAM	1	AR1254 hits, Need 2X	DILUTION	OR Fail UPDATE STATUS
L2133-03	PQ047254.D	02 Apr 2020 19:24	SMALL-HOUSE-FLOORS	PCB	SAM	1	AR1254 hits	OK	UPDATE STATUS
L2133-02	PQ047255.D	02 Apr 2020 19:40	BIG-HOUSE-WALLS	PCB	SAM	1	AR1254 hits, DCB high in both column	RERUN	Surr Fail UPDATE STATUS
L2133-01	PQ047256.D	02 Apr 2020 19:57	BIG-HOUSE-FLOORS	PCB	SAM	1	AR1254 hits, DCB high in 2nd column	OK	Surr Fail UPDATE STATUS
L2129-41	PQ047257.D	02 Apr 2020 20:13	TP-3	PCB	SAM	1	AR1268 hits	OK	UPDATE STATUS
L2129-36	PQ047258.D	02 Apr 2020 20:29	TP-6	PCB	SAM	1	DCB high in 2nd column	OK	Surr Fail UPDATE STATUS
L2129-31	PQ047259.D	02 Apr 2020 20:45	TP-5	PCB	SAM	1	AR1254,1260 hits	OK	UPDATE STATUS
L2129-26	PQ047260.D	02 Apr 2020 21:02	TP-2	PCB	SAM	1	--	OK	UPDATE STATUS
I.BLK	PQ047261.D	02 Apr 2020 21:34	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PQ047262.D	02 Apr 2020 21:51	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved