



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence po101920 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PO072476.D	19 Oct 2020 8:41	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
I.BLK	PO072477.D	19 Oct 2020 8:58	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO072478.D	19 Oct 2020 9:36	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
L4413-01	PO072479.D	19 Oct 2020 9:53	30688	PCB	SAM	1	--	OK	UPDATE STATUS
L4432-01DL	PO072480.D	19 Oct 2020 10:10	WCS-DD-G-01DL	PCB	SAM	20	AR1248,1254 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4432-01DL2	PO072481.D	19 Oct 2020 10:28	WCS-DD-G-01DL2	PCB	SAM	200	AR1248,1254 hits, Need more dilution	NotOK	Surr, OR Fail UPDATE STATUS
L4442-09DL	PO072482.D	19 Oct 2020 10:45	COAL0DL	PCB	SAM	40	AR1260 Hits	OK	Surr Fail UPDATE STATUS
L4442-10DL	PO072483.D	19 Oct 2020 11:02	COAL1DL	PCB	SAM	50	AR1242 &1260 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4442-10DL2	PO072484.D	19 Oct 2020 11:19	COAL1DL2	PCB	SAM	100	AR1242 &1260 hits, Need more dilution	NotOK	Surr, OR Fail UPDATE STATUS
L4442-11DL	PO072485.D	19 Oct 2020 11:36	COAL2DL	PCB	SAM	50	AR1260 Hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
		19					AR1260 Hits,		

L4442-11DL2	PO072486.D	Oct 2020 11:53	C0AL2DL2	PCB	SAM	200	Need more dilution	NotOK	Surr, OR Fail STATUS UPDATE
L4442-12DL	PO072487.D	19 Oct 2020 12:10	C0AL3DL	PCB	SAM	2	wrong sample	NotOK	STATUS UPDATE
L4442-12DL2	PO072488.D	19 Oct 2020 12:27	C0AL3DL2	PCB	SAM	20	wrong sample	NotOK	Surr Fail STATUS UPDATE
L4442-14DL	PO072489.D	19 Oct 2020 12:44	C0AL5DL	PCB	SAM	5	AR1248 & 1254, 1260 hits	OK	STATUS UPDATE
L4442-15DL	PO072490.D	19 Oct 2020 13:01	C0AL6DL	PCB	SAM	2	AR1260 hits	OK	STATUS UPDATE
L4442-16DL	PO072491.D	19 Oct 2020 13:18	C0AL7DL	PCB	SAM	20	AR1260 hits	OK	STATUS UPDATE
L4442-17DL	PO072492.D	19 Oct 2020 13:36	C0AL8DL	PCB	SAM	20	AR1260 hits	OK	STATUS UPDATE
L4442-19DL	PO072493.D	19 Oct 2020 13:53	C0AM0DL	PCB	SAM	5	AR1248 & 1254, 1260 hits	OK	STATUS UPDATE
I.BLK	PO072494.D	19 Oct 2020 14:11	I.BLK	PCB	IBLK	1	--	OK	STATUS UPDATE
AR1660CCC500	PO072495.D	19 Oct 2020 14:46	AR1660CCC500	PCB	CCAL500	1	--	OK	STATUS UPDATE
L4442-12DL	PO072496.D	19 Oct 2020 15:03	C0AL3DL	PCB	SAM	10	AR1248, AR1260 hits, DCB low in both column- add DL2 suffix and correct typo As 20x	OK	Surr Fail STATUS UPDATE
L4442-12DL	PO072497.D	19 Oct 2020 15:25	C0AL3DL	PCB	SAM	2	AR1248, AR1260 hits, Need more dilution	DILUTION	OR Fail STATUS UPDATE
PB132445BL	PO072498.D	19 Oct 2020 15:42	PB132445BL	PCB	MB	1	--	OK	STATUS UPDATE
PB132445BS	PO072499.D	19 Oct 2020 15:59	PB132445BS	PCB	LCS	1	--	OK	STATUS UPDATE
PB132445BSD	PO072500.D	19 Oct 2020 16:16	PB132445BSD	PCB	LCSD	1	--	OK	STATUS UPDATE
L4434-03	PO072501.D	19 Oct 2020 16:33	40978-A	PCB	SAM	1	AR1242 Hits, Need 5X, DCB low in both column- ar1242ccc missing	NotOK	Surr, OR Fail STATUS UPDATE
L4434-04	PO072502.D	19 Oct 2020 16:50	16757-A	PCB	SAM	1	AR1242 Hits, All surrogate failing low	NotOK	Surr Fail STATUS UPDATE

L4434-05	PO072503.D	19 Oct 2020 17:07	16743	PCB	SAM	1	--	OK	UPDATE STATUS
L4434-06	PO072504.D	19 Oct 2020 17:24	16804	PCB	SAM	1	--	OK	UPDATE STATUS
I.BLK	PO072505.D	19 Oct 2020 17:41	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO072506.D	19 Oct 2020 17:59	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
PB132443BL	PO072507.D	19 Oct 2020 18:16	PB132443BL	PCB	MB	1	--	OK	UPDATE STATUS
PB132443BS	PO072508.D	19 Oct 2020 18:33	PB132443BS	PCB	LCS	1	--	OK	UPDATE STATUS
L4434-01	PO072509.D	19 Oct 2020 18:50	40978-S	PCB	SAM	1	AR1242 Hits, Need 10X,100X, TCMX high in 1st column- AR1242CCC MISSING	NotOK	Surr, OR Fail UPDATE STATUS
L4434-02	PO072510.D	19 Oct 2020 19:07	16757-S	PCB	SAM	1	AR1242 Hits, Need 20X- AR1242CCC MISSING	NotOK	OR Fail UPDATE STATUS
L4435-02	PO072511.D	19 Oct 2020 19:24	5412	PCB	SAM	1	AR1248 & 1254 hits, Need 5X, NEED CLEAN UP	NotOK	OR Fail UPDATE STATUS
L4454-01	PO072512.D	19 Oct 2020 19:41	TEST-PIT	PCB	SAM	1	--	OK	UPDATE STATUS
L4454-01MS	PO072513.D	19 Oct 2020 19:58	TEST-PITMS	PCB	MS	1	--	OK	UPDATE STATUS
L4454-01MSD	PO072514.D	19 Oct 2020 20:15	TEST-PITMSD	PCB	MSD	1	RPD Fail for AR1260	OK	RPD Fail UPDATE STATUS
I.BLK	PO072515.D	19 Oct 2020 20:32	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
AR1660CCC500	PO072516.D	19 Oct 2020 20:49	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
Read Files			Update			All Manual Integration Report			

Read QUANT File

EPH Sequence Transfer

Update ClientInfo

Trasfer PH