



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome **Sakhvala**
| Logout

Search : **Go**

Dashboard | Edd | Efolder | Fax | Genchem | Projecttrack | Qaqc | Quanttrack | Report | Sequence | Utility |

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : SOM02.4_PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pr102220 **CHEMTECH-NJ Lab Sequence** Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
AIBLK77	PR047971.D	22 Oct 2020 00:10	AIBLK77	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PR047972.D	22 Oct 2020 00:25	AR1660352	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1242CCC400	PR047973.D	22 Oct 2020 00:39	AR1242324	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PR047974.D	22 Oct 2020 00:53	AR1248357	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC500	PR047975.D	22 Oct 2020 01:08	AR1254369	PCB	CCAL500	1	--	OK	UPDATE STATUS
L4451-01	PR047976.D	22 Oct 2020 01:22	C0AD9	PCB	SAM	1	AR1248 & 1254, 1260 hits, Need dilution 50X,500X, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
L4451-02	PR047977.D	22 Oct 2020 01:37	C0AE0	PCB	SAM	1	AR1248,AR1260 Hit, Need dilution 10X,100X	DILUTION	OR Fail UPDATE STATUS
L4451-03	PR047978.D	22 Oct 2020 01:51	C0AE1	PCB	SAM	1	AR1248 & 1254, 1260 hits, Need dilution 10X,100X, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
L4451-04	PR047979.D	22 Oct 2020 02:06	C0AE2	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS

L4451-06	PR047980.D	22 Oct 2020 02:20	C0AG0	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4451-07	PR047981.D	22 Oct 2020 02:35	C0AG1	PCB	SAM	1	AR1248 & 1260 hits, Need dilution, Need to check AR1260 2nd column 4th & 5th peak in coming Fflag, pls Fix it if possible	DILUTION	Surr, OR Fail UPDATE STATUS
L4451-08	PR047982.D	22 Oct 2020 02:49	C0AG2	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4451-17	PR047983.D	22 Oct 2020 03:03	C0AH9	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	Surr, OR Fail UPDATE STATUS
PB132444BL	PR047984.D	22 Oct 2020 03:18	ABLK44	PCB	MB	1	--	OK	Surr Fail UPDATE STATUS
PB132444BS	PR047985.D	22 Oct 2020 03:32	ALCS44	PCB	LCS	1	--	OK	Surr Fail UPDATE STATUS
L4449-01	PR047986.D	22 Oct 2020 03:47	C0AD4	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4449-02	PR047987.D	22 Oct 2020 04:01	C0AD5	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4449-03	PR047988.D	22 Oct 2020 04:16	C0AD6	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4449-04	PR047989.D	22 Oct 2020 04:30	C0AD7	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4449-05	PR047990.D	22 Oct 2020 04:45	C0AD8	PCB	SAM	1	AR1248 & 1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4449-06	PR047991.D	22 Oct 2020 04:59	C0AE4	PCB	SAM	1	AR1260 hits, Need dilution	DILUTION	OR Fail UPDATE STATUS
L4449-07	PR047992.D	22 Oct 2020 05:14	C0AE5	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
L4449-08	PR047993.D	22 Oct 2020 05:28	C0AE6	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
L4449-09	PR047994.D	22 Oct 2020 05:42	C0AE7	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
							AR1248 &		

L4449-10	PR047995.D	22 Oct 2020 05:57	C0AE8	PCB	SAM	1	AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
L4449-11	PR047996.D	22 Oct 2020 06:11	C0AE9	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	Surr, OR Fail UPDATE STATUS
L4449-12	PR047997.D	22 Oct 2020 06:26	C0AF0	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Confirm AR1254	OK	UPDATE STATUS
L4449-13	PR047998.D	22 Oct 2020 06:40	C0AF1	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
L4449-14	PR047999.D	22 Oct 2020 06:55	C0AF2	PCB	SAM	1	AR1248 & AR1254, 1260 hits, Need dilution, Confirm AR1254	DILUTION	OR Fail UPDATE STATUS
AIBLK78	PR048000.D	22 Oct 2020 08:32	AIBLK78	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PR048001.D	22 Oct 2020 09:03	AR1660353	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1242CCC400	PR048002.D	22 Oct 2020 09:19	AR1242325	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1248CCC400	PR048003.D	22 Oct 2020 09:34	AR1248358	PCB	CCAL400	1	--	OK	UPDATE STATUS
AR1254CCC400	PR048004.D	22 Oct 2020 09:49	AR1254370	PCB	CCAL400	1	--	OK	UPDATE STATUS
L4449-15MS	PR048005.D	22 Oct 2020 10:03	C0AF2MS	PCB	MS	1	Recovery Fail for AR1016 & 1260	OK	Surr, Recovery Fail UPDATE STATUS
L4449-16MSD	PR048006.D	22 Oct 2020 10:18	C0AF2MSD	PCB	MSD	1	Recovery Fail for AR1016 & 1260	OK	Surr, Recovery Fail UPDATE STATUS
L4365-06DL	PR048007.D	22 Oct 2020 10:46	BEQD2DL	PCB	SAM	5	AR1248 & 1254 hits	OK	UPDATE STATUS
L4365-07DL	PR048008.D	22 Oct 2020 11:15	BEQD3DL	PCB	SAM	10	AR1248 & 1254 hits	OK	UPDATE STATUS
L4365-11DL	PR048009.D	22 Oct 2020 11:59	BEQD5DL	PCB	SAM	5	AR1248 & 1254 hits	OK	UPDATE STATUS
L4402-06	PR048010.D	22 Oct 2020 12:28	C0AB7	PCB	SAM	50	AR1248 & 1260 hits, Need dilution, AR1248 1st column 1st peak	DILUTION	Surr, OR Fail UPDATE STATUS

							overdilute, pls check			
L4402-06DL	PR048011.D	22 Oct 2020 12:57	C0AB7DL	PCB	SAM	500	AR1248 & 1260 hits	OK	Surr Fail UPDATE STATUS	
L4449-17	PR048012.D	22 Oct 2020 13:40	C0AF3	PCB	SAM	10	Need to straight run	NotOK	UPDATE STATUS	
L4449-18	PR048013.D	22 Oct 2020 13:54	C0AF4	PCB	SAM	10	AR1260 hits, Need to straight run	NotOK	UPDATE STATUS	
L4449-19	PR048014.D	22 Oct 2020 14:09	C0AF5	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS	
L4449-20	PR048015.D	22 Oct 2020 14:23	C0AF6	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS	
L4449-21	PR048016.D	22 Oct 2020 14:38	C0AF7	PCB	SAM	10	AR1248 & 1260 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS	
L4449-22	PR048017.D	22 Oct 2020 14:52	C0AF8	PCB	SAM	10	AR1248 & 1260 hits, Need more dilution, DCB high in both column	DILUTION	Surr, OR Fail UPDATE STATUS	
L4452-13	PR048018.D	22 Oct 2020 15:07	C0AK3	PCB	SAM	10	AR1248 & 1260 hits, Need more dilution, DCB high in both column, Pls check already run	NotOK	Surr, OR Fail UPDATE STATUS	
AIBLK79	PR048019.D	22 Oct 2020 15:35	AIBLK79	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS	
AR1660CCC400	PR048020.D	22 Oct 2020 16:05	AR1660354	PCB	CCAL400	1	--	OK	UPDATE STATUS	
AR1242CCC400	PR048021.D	22 Oct 2020 16:20	AR1242326	PCB	CCAL400	1	--	OK	UPDATE STATUS	
AR1248CCC400	PR048022.D	22 Oct 2020 16:35	AR1248359	PCB	CCAL400	1	--	OK	UPDATE STATUS	
AR1254CCC400	PR048023.D	22 Oct 2020 16:50	AR1254371	PCB	CCAL400	1	--	OK	UPDATE STATUS	
PB132450BL	PR048024.D	22 Oct 2020 17:05	ABLK50	PCB	MB	1	--	OK	Surr Fail UPDATE STATUS	
PB132450BS	PR048025.D	22 Oct 2020 17:20	ALCS50	PCB	LCS	1	--	OK	Surr Fail UPDATE STATUS	
L4451-05	PR048026.D	22 Oct 2020 17:34	C0AE3	PCB	SAM	1	AR1260 hits, Need 5X	DILUTION	OR Fail UPDATE STATUS	

L4451-10	PR048027.D	22 Oct 2020 17:48	C0AG4	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-11	PR048028.D	22 Oct 2020 18:03	C0AG5	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-12	PR048029.D	22 Oct 2020 18:17	C0AG6	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-13	PR048030.D	22 Oct 2020 18:32	C0AG7	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-14	PR048031.D	22 Oct 2020 18:46	C0AG9	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-15	PR048032.D	22 Oct 2020 19:01	C0AH2	PCB	SAM	1	AR1260 hits, Low concentration	OK	UPDATE STATUS
L4451-16	PR048033.D	22 Oct 2020 19:15	C0AH6	PCB	SAM	1	AR1248, AR1260 Hit, Need 2X	DILUTION	OR Fail UPDATE STATUS
L4449-17	PR048034.D	22 Oct 2020 19:29	C0AF3	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4449-18	PR048035.D	22 Oct 2020 19:44	C0AF4	PCB	SAM	1	AR1248 & 1260 hits, Need 2X	DILUTION	OR Fail UPDATE STATUS
L4451-09	PR048036.D	22 Oct 2020 19:58	C0AG3	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-18	PR048037.D	22 Oct 2020 20:13	C0AJ6	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-19	PR048038.D	22 Oct 2020 20:27	C0AJ7	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-20MS	PR048039.D	22 Oct 2020 20:42	C0AJ7MS	PCB	MS	1	--	OK	Surr Fail UPDATE STATUS
L4451-21MSD	PR048040.D	22 Oct 2020 20:56	C0AJ7MSD	PCB	MSD	1	--	OK	Surr Fail UPDATE STATUS
L4451-22	PR048041.D	22 Oct 2020 21:11	C0AJ8	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L4451-01DL	PR048042.D	22 Oct 2020 21:25	C0AD9DL	PCB	SAM	50	AR1248 & 1254, 1260 hits, Need more dilution	DILUTION	Surr, OR Fail UPDATE STATUS
L4451-01DL2	PR048043.D	22 Oct 2020 21:40	C0AD9DL2	PCB	SAM	500	AR1248 & 1254, 1260 hits	OK	Surr Fail UPDATE STATUS
L4451-02DL	PR048044.D	22 Oct 2020	C0AE0DL	PCB	SAM	10	AR1248, AR1260 Hit, Need More dilution	DILUTION	OR Fail UPDATE STATUS

		21:54								
L4451-02DL2	PR048045.D	22 Oct 2020 22:08	C0AE0DL2	PCB	SAM	100	AR1248,AR1260 Hit	OK	Surr Fail STATUS	UPDATE
L4451-03DL	PR048046.D	22 Oct 2020 22:23	C0AE1DL	PCB	SAM	10	AR1248 & 1254, 1260 hits, Need more dilution	DILUTION	OR Fail STATUS	UPDATE
L4451-03DL2	PR048047.D	22 Oct 2020 22:37	C0AE1DL2	PCB	SAM	100	AR1248 & 1254, 1260 hits	OK	Surr Fail STATUS	UPDATE
L4451-04DL	PR048048.D	22 Oct 2020 22:52	C0AE2DL	PCB	SAM	4	AR1248 & 1260 hits, Need more dilution	DILUTION	OR Fail STATUS	UPDATE
L4451-04DL2	PR048049.D	22 Oct 2020 23:06	C0AE2DL2	PCB	SAM	400	AR1248 & 1260 hits, Need to confirm dilution suffix	OK	Surr Fail STATUS	UPDATE
L4451-06DL	PR048050.D	22 Oct 2020 23:21	C0AG0DL	PCB	SAM	50	AR1248 & 1260 hits, Need more dilution	DILUTION	Surr, OR Fail STATUS	UPDATE
L4451-06DL2	PR048051.D	22 Oct 2020 23:35	C0AG0DL2	PCB	SAM	500	AR1248 & 1260 hits	OK	Surr Fail STATUS	UPDATE
L4451-07DL	PR048052.D	22 Oct 2020 23:50	C0AG1DL	PCB	SAM	100	AR1248 & 1260 hits, Need more dilution	DILUTION	Surr, OR Fail STATUS	UPDATE
L4451-07DL2	PR048053.D	23 Oct 2020 00:04	C0AG1DL2	PCB	SAM	1000	AR1248 & 1260 hits, Need more dilution	NotOK	Surr, OR Fail STATUS	UPDATE
L4451-08DL	PR048054.D	23 Oct 2020 00:18	C0AG2DL	PCB	SAM	50	AR1248 & 1260 hits, Need more dilution	DILUTION	Surr, OR Fail STATUS	UPDATE
L4451-08DL2	PR048055.D	23 Oct 2020 00:33	C0AG2DL2	PCB	SAM	500	AR1248 & 1260 hits	OK	Surr Fail STATUS	UPDATE
L4451-17DL	PR048056.D	23 Oct 2020 00:47	C0AH9DL	PCB	SAM	40	AR1248 & 1260 hits, Need more dilution	DILUTION	Surr, OR Fail STATUS	UPDATE
L4451-17DL2	PR048057.D	23 Oct 2020 01:02	C0AH9DL2	PCB	SAM	400	AR1248 & 1260 hits	OK	Surr Fail STATUS	UPDATE
AIBLK81	PR048058.D	23 Oct 2020 01:16	AIBLK81	PCB	IBLK	1	--	OK	Surr Fail STATUS	UPDATE
AR1660CCC400	PR048059.D	23 Oct 2020 01:31	AR1660355	PCB	CCAL400	1	--	OK	STATUS	UPDATE
AR1242CCC400	PR048060.D	23 Oct 2020 01:45	AR1242327	PCB	CCAL400	1	--	OK	STATUS	UPDATE
AR1248CCC400	PR048061.D	23 Oct 2020 01:59	AR1248360	PCB	CCAL400	1	--	OK	STATUS	UPDATE
		23 Oct								

AR1254CCC400	PR048062.D	2020 02:14	AR1254372	PCB	CCAL400	1	--	OK	UPDATE STATUS
Read Files		Update		All Manual Integration Report					

Read QUANT File

EPH Sequence Transfer

Update ClientInfo

Trasfer PH

Copyright © 2020 CHEMTECH. All rights reserved