



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : SOM02.4_PCB

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pr060620 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
AIBLK09	PR045614.D	06 Jun 2020 00:00	AIBLK09	PCB	IBLK	1	--	OK	Surr Fail UPDATE STATUS
AR1660CCC400	PR045615.D	06 Jun 2020 01:16	AR1660398	PCB	CCAL400	1	--	OK	UPDATE STATUS
PB129356BL	PR045616.D	06 Jun 2020 01:44	ABLK56	PCB	MB	1	--	OK	Surr Fail UPDATE STATUS
PB129356BS	PR045617.D	06 Jun 2020 01:59	ALCS56	PCB	LCS	1	--	OK	Surr Fail UPDATE STATUS
L2898-01	PR045618.D	06 Jun 2020 02:13	ETX49	PCB	SAM	1	AR1260 hits, Need 2X	DILUTION	OR Fail UPDATE STATUS
L2898-02MS	PR045619.D	06 Jun 2020 02:28	ETX49MS	PCB	MS	1	Recovery Fail for AR1260	OK	Surr, Recovery Fail UPDATE STATUS
L2898-03MSD	PR045620.D	06 Jun 2020 02:42	ETX49MSD	PCB	MSD	1	Recovery Fail for AR1260	OK	Surr, Recovery Fail UPDATE STATUS
L2898-04	PR045621.D	06 Jun 2020 02:57	ETX53	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L2898-05	PR045622.D	06 Jun 2020 03:11	ETX54	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L2898-06	PR045623.D	06 Jun 2020 03:26	ETX55	PCB	SAM	1	AR1254 hits	OK	UPDATE STATUS
		06							

L2898-07	PR045624.D	Jun 2020 03:40	ETX56	PCB	SAM	1	AR1254 hits, Confirm hit	OK	UPDATE STATUS
L2898-08	PR045625.D	06 Jun 2020 03:55	ETX57	PCB	SAM	1	--	OK	UPDATE STATUS
L2898-09	PR045626.D	06 Jun 2020 04:09	ETX58	PCB	SAM	1	--	OK	UPDATE STATUS
L2898-10	PR045627.D	06 Jun 2020 04:23	ETX61	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L2898-11	PR045628.D	06 Jun 2020 04:38	ETX62	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L2898-12	PR045629.D	06 Jun 2020 04:52	ETX63	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L2898-13	PR045630.D	06 Jun 2020 05:07	ETX64	PCB	SAM	1	AR1260 hits	OK	UPDATE STATUS
L2898-14	PR045631.D	06 Jun 2020 05:21	ETX65	PCB	SAM	1	--	OK	UPDATE STATUS
L2898-15	PR045632.D	06 Jun 2020 05:36	ETX66	PCB	SAM	1	--	OK	UPDATE STATUS
L2898-16	PR045633.D	06 Jun 2020 05:50	ETX67	PCB	SAM	1	AR1248 & 1254 HITS, Need 5X	DILUTION	OR Fail UPDATE STATUS
L2898-17	PR045634.D	06 Jun 2020 06:05	ETX68	PCB	SAM	1	AR1248 & 1254 HITS, Need 5X	DILUTION	OR Fail UPDATE STATUS
L2898-18	PR045635.D	06 Jun 2020 06:19	ETX69	PCB	SAM	1	AR1248,1254 & 1260 hits, Confirm AR1260	OK	UPDATE STATUS
L2898-19	PR045636.D	06 Jun 2020 06:33	ETX70	PCB	SAM	1	AR1248,1254 & 1260 hits, Confirm AR1260	OK	UPDATE STATUS
L2898-20	PR045637.D	06 Jun 2020 06:48	ETX71	PCB	SAM	1	AR1248,1254 & 1260 hits, Confirm AR1260	OK	UPDATE STATUS
L2898-21	PR045638.D	06 Jun 2020 07:02	ETX72	PCB	SAM	1	AR1248 & 1254 HITS, Need 5X	DILUTION	OR Fail UPDATE STATUS
L2898-22	PR045639.D	06 Jun 2020 07:17	ETX73	PCB	SAM	1	AR1242 & 1254 HITS, Need 200X	DILUTION	Surr, OR Fail UPDATE STATUS
PB129357BL	PR045640.D	06 Jun 2020 07:31	ABLK57	PCB	MB	1	AR1248 & 1254 HITS, TYPO	NotOK	Surr, OR, Contaminant UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)

Copyright © 2020 CHEMTECH. All rights reserved