



Suggestion Box MSDS RICCA MSDS J.T.Baker
MSDS emdmillipore MSDS restek MSDS CHEMTECH

Welcome Sakhvala
| Logout

Search :

[Dashboard](#) | [Edd](#) | [Efolder](#) | [Fax](#) | [Genchem](#) | [Projecttrack](#) | [Qaqc](#) | [Quanttrack](#) | [Report](#) | [Sequence](#) | [Utility](#)

[Home](#) >> [Sequence Module](#) >> [File Info](#)

Sequence Module :: File Info

Navigation Bar

Method : 8082A

[FileInfo Form](#) [Get Test Info](#) [Analysis RunLog](#) [Sequence Info](#) [Maintenance](#) [Audit Summary Report](#) [Sequence Process](#)

Data For Sequence pp031521 **CHEMTECH-NJ Lab Sequence**
Rule For Ms/Msd of EPH

[Sequence Transfer](#)

[Review Raw Data](#)

[Non Conformance Summary](#)

No Review & No Supervised

Reviewed & No Supervised

Reviewed & Supervised

SampleID	Data File	Date & Time	ClientId	Test	QCType	Dilution.	Comments	Status	System Comments
HEXANE	PP033986.D	15 Mar 2021 9:01	HEXANE	PCB	HEXANE	1	--	OK	UPDATE STATUS
AR1660CCC500	PP033987.D	15 Mar 2021 9:35	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PP033988.D	15 Mar 2021 9:54	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP033989.D	15 Mar 2021 10:11	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
M1624-01RE	PP033990.D	15 Mar 2021 10:28	WALLS-1RE	PCB	SAM	1	AR1254 Hits, DCB failing high in both column	CONFIRMS	Surr Fail UPDATE STATUS
M1624-03RE	PP033991.D	15 Mar 2021 10:45	WALLS-2RE	PCB	SAM	1	AR1254 Hits, DCB failing high in both column	CONFIRMS	Surr Fail UPDATE STATUS
M1624-05RE	PP033992.D	15 Mar 2021 11:01	WALLS-3RE	PCB	SAM	1	AR1254 Hits, DCB failing high in both column	CONFIRMS	Surr Fail UPDATE STATUS
M1660-01DL	PP033993.D	15 Mar 2021 11:18	X127-1ADL	PCB Group1	SAM	5	AR1254 Hits	OK	UPDATE STATUS
M1660-02DL	PP033994.D	15 Mar 2021 11:35	X127-DUP1DL	PCB Group1	SAM	5	AR1254 Hits	OK	UPDATE STATUS
M1660-05DL	PP033995.D	15 Mar 2021 11:52	X127-2ADL	PCB Group1	SAM	5	AR1254 Hits	OK	UPDATE STATUS
		15							

M1660-08DL	PP033996.D	Mar 2021 12:09	X127-3ADL	PCB Group1	SAM	2	AR1254 Hits	OK	UPDATE STATUS
M1660-11DL	PP033997.D	15 Mar 2021 12:26	X127-4ADL	PCB Group1	SAM	5	AR1254 Hits	OK	UPDATE STATUS
M1660-17DL	PP033998.D	15 Mar 2021 12:42	X127-6ADL	PCB Group1	SAM	2	AR1254 Hits	OK	UPDATE STATUS
AR1660CCC500	PP033999.D	15 Mar 2021 12:59	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
AR1254CCC500	PP034000.D	15 Mar 2021 13:16	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP034001.D	15 Mar 2021 13:33	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
PB136152BL	PP034002.D	15 Mar 2021 13:50	PB136152BL	PCB	MB	1	TYPO	NotOK	UPDATE STATUS
PB136152BS	PP034003.D	15 Mar 2021 14:06	PB136152BS	PCB	LCS	1	TYPO	NotOK	UPDATE STATUS
M1661-01	PP034004.D	15 Mar 2021 14:23	X127-7A	PCB Group1	SAM	5	AR1254 Hits, DCB failing high in both column	OK	Surr Fail UPDATE STATUS
M1661-04	PP034005.D	15 Mar 2021 14:40	X127-8A	PCB Group1	SAM	5	AR1254 Hits, Need more Dilution	DILUTION	OR Fail UPDATE STATUS
M1661-07	PP034006.D	15 Mar 2021 14:57	X127-9A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS
M1661-10	PP034007.D	15 Mar 2021 15:13	X127-10A	PCB Group1	SAM	5	Looks like Hexane	NotOK	Surr Fail UPDATE STATUS
M1661-14	PP034008.D	15 Mar 2021 15:30	X127-11A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS
M1661-18	PP034009.D	15 Mar 2021 15:47	X127-12A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS
M1662-01	PP034010.D	15 Mar 2021 16:04	X127-13A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS
M1662-01MS	PP034011.D	15 Mar 2021 16:21	X127-13AMS	PCB Group1	MS	5	Recovery Fail for AR1016	OK	Surr, Recovery Fail UPDATE STATUS
M1662-01MSD	PP034012.D	15 Mar 2021 16:38	X127-13AMSD	PCB Group1	MSD	5	Recovery Fail for AR1016	OK	Surr, Recovery Fail UPDATE STATUS
M1662-04	PP034013.D	15 Mar 2021 16:54	X127-14A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS

M1662-07	PP034014.D	15 Mar 2021 17:11	X127-15A	PCB Group1	SAM	5	--	OK	UPDATE STATUS
M1662-08	PP034015.D	15 Mar 2021 17:28	X127-DUP4	PCB Group1	SAM	5	--	OK	UPDATE STATUS
M1662-11	PP034016.D	15 Mar 2021 17:45	X127-16A	PCB Group1	SAM	5	AR1254 hits, Confirm hit	OK	UPDATE STATUS
M1662-14	PP034017.D	15 Mar 2021 18:02	X127-17A	PCB Group1	SAM	5	AR1254 hits, Confirm hit	OK	UPDATE STATUS
M1662-17	PP034018.D	15 Mar 2021 18:19	X127-18A	PCB Group1	SAM	5	AR1254 hits, Confirm hit	OK	UPDATE STATUS
AR1660CCC500	PP034019.D	15 Mar 2021 18:52	AR1660CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP034020.D	15 Mar 2021 19:09	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
M1663-01	PP034021.D	15 Mar 2021 19:26	X127-19A	PCB Group1	SAM	5	AR1254 hits, Confirm hit	OK	UPDATE STATUS
M1663-05	PP034022.D	15 Mar 2021 19:43	X127-20A	PCB Group1	SAM	5	AR1254 hits, Confirm hit	OK	UPDATE STATUS
M1663-08	PP034023.D	15 Mar 2021 20:00	X127-21A	PCB Group1	SAM	5	AR1254 hits, Confirm hit	OK	UPDATE STATUS
M1663-12	PP034024.D	15 Mar 2021 20:17	X127-22A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS
M1663-15	PP034025.D	15 Mar 2021 20:33	X127-23A	PCB Group1	SAM	5	AR1254 hits	OK	UPDATE STATUS
M1663-18	PP034026.D	15 Mar 2021 20:50	X127-24A	PCB Group1	SAM	5	--	OK	UPDATE STATUS
M1663-19	PP034027.D	15 Mar 2021 21:07	X127-DUP7	PCB Group1	SAM	5	--	OK	UPDATE STATUS
AR1660CCC500	PP034028.D	15 Mar 2021 21:41	AR1660CCC500	PCB	CCAL500	1	DCB has a F flag, Please fix it	OK	UPDATE STATUS
AR1254CCC500	PP034029.D	15 Mar 2021 21:58	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP034030.D	15 Mar 2021 22:14	I.BLK	PCB	IBLK	1	--	OK	UPDATE STATUS
PB135155BL	PP034031.D	15 Mar 2021	PB135155BL	PCB	MB	1	--	OK	UPDATE STATUS

		22:31							
PB135155BS	PP034032.D	15 Mar 2021 22:48	PB135155BS	PCB	LCS	1	--	OK	UPDATE STATUS
M1664-02	PP034033.D	15 Mar 2021 23:05	VNJ-230	PCB	SAM	1	DCB has a F flag	NotOK	UPDATE STATUS
M1665-01	PP034034.D	15 Mar 2021 23:22	41701	PCB	SAM	1	AR1248,AR1260 Hit, Need cleanup	NotOK	Surr, OR Fail UPDATE STATUS
M1666-01	PP034035.D	15 Mar 2021 23:39	1875-1	PCB	SAM	10	AR1260 hits	OK	UPDATE STATUS
M1668-01	PP034036.D	15 Mar 2021 23:55	CL-02-031221	PCB	SAM	1	--	OK	UPDATE STATUS
M1669-01	PP034037.D	16 Mar 2021 00:12	RBR-607	PCB	SAM	1	--	OK	OR Fail UPDATE STATUS
M1678-01	PP034038.D	16 Mar 2021 00:29	D2470-D2800 (SOIL)-A	PCB	SAM	1	AR1260 hits, DCB having F flag	NotOK	UPDATE STATUS
M1678-01MS	PP034039.D	16 Mar 2021 00:46	D2470-D2800 (SOIL)-AMS	PCB	MS	1	MSD is notok	NotOK	UPDATE STATUS
M1678-01MSD	PP034040.D	16 Mar 2021 1:03	D2470-D2800 (SOIL)-AMSD	PCB	MSD	1	DCB has a F flag	NotOK	UPDATE STATUS
AR1660CCC500	PP034041.D	16 Mar 2021 1:36	AR1660CCC500	PCB	CCAL500	1	DCB has a F flag	OK	UPDATE STATUS
AR1254CCC500	PP034042.D	16 Mar 2021 1:53	AR1254CCC500	PCB	CCAL500	1	--	OK	UPDATE STATUS
I.BLK	PP034043.D	16 Mar 2021 2:10	I.BLK	PCB	IBLK	1	DCB has a F flag	OK	UPDATE STATUS
Read Files		Update		All Manual Integration Report					

[Read QUANT File](#)[EPH Sequence Transfer](#)[Update ClientInfo](#)[Trasfer PH](#)