



PERCENT SOLID

Supervisor: apatel
Analyst: JIGNESH
Date: 7/17/2019

OVENTEMP IN Celsius(°C): 107
Time IN: 16:00
In Date: 07/15/2019
Weight Check 1.0g: 1.00
Weight Check 10g: 10.00
OvenID: M OVEN-1

OVENTEMP OUT Celsius(°C): 103
Time OUT: 08:00
Out Date: 07/16/2019
Weight Check 1.0g: 1.00
Weight Check 10g: 10.00
BalanceID: M SC-4
Thermometer ID: % SOLIDS-Oven

QC:LB103972

Lab ID	Client Sample ID	Dish#	Dish Wt(g) (A)	Dish + Sample Wt(g) (B)	Dish + Dry Sample Wt(g) (C)	% Solid
K3770-06	X2H36	1	1.00	2.00	2.00	100.0
K3770-07	X2H37	2	1.00	2.00	2.00	100.0
K3770-08	X2H38	3	1.00	2.00	2.00	100.0
K3770-09	X2H39	4	1.00	2.00	2.00	100.0
K3770-10	X2H40	5	1.00	2.00	2.00	100.0

$$\% \text{ Solid} = \frac{(C-A) * 100}{(B-A)}$$

103942

WORKLIST(Hardcopy Internal Chain)

WorkList Name : %1-K3770 WorkList ID : 128567 Department : Wet-Chemistry Date : 07-15-2019 15:45:50

Due Date	Matrix	Sample	Test	Preservative	Customer	Storage Location	Customer Sample	Collect Date	Method
07/20/2019	Solid	K3770-06	Percent Solids	Cool 4 deg C	USEP04	QA Office	X2H36	07/10/2019	Chemtech -SO
07/20/2019	Solid	K3770-07	Percent Solids	Cool 4 deg C	USEP04	QA Office	X2H37	07/10/2019	Chemtech -SO
07/20/2019	Solid	K3770-08	Percent Solids	Cool 4 deg C	USEP04	QA Office	X2H38	07/10/2019	Chemtech -SO
07/20/2019	Solid	K3770-09	Percent Solids	Cool 4 deg C	USEP04	QA Office	X2H39	07/10/2019	Chemtech -SO
07/20/2019	Solid	K3770-10	Percent Solids	Cool 4 deg C	USEP04	QA Office	X2H40	07/10/2019	Chemtech -SO

Date/Time 07-15-19 16:00
 Received by: JN
 Relinquished by: [Signature]

Date/Time 07-15-19 17:00
 Received by: [Signature]
 Relinquished by: JD