



PERCENT SOLID

Supervisor: Iwona
Analyst: jignesh
Date: 1/4/2024

OVENTEMP IN Celsius(°C): 107
Time IN: 16:30
In Date: 01/03/2024
Weight Check 1.0g: 1.00
Weight Check 10g: 10.00
OvenID: M OVEN-1

OVENTEMP OUT Celsius(°C): 103
Time OUT: 08:00
Out Date: 01/04/2024
Weight Check 1.0g: 1.00
Weight Check 10g: 10.00
BalanceID: M SC-4
Thermometer ID: %SOLIDS-OVEN

QC:LB129011

Lab ID	Client SampleID	Dish #	Dish Wt(g) (A)	Sample Wt(g)	Dish + Sample Wt(g) (B)	Dish+Dry Sample Wt(g) (C)	% Solid	Comments
P1005-01	RBR200030	1	1.15	8.81	9.96	8.75	86.3	
P1005-02	RBR200030	2	1.15	8.53	9.68	8.5	86.2	
P1006-01	NB-7-010324	3	1.14	8.43	9.57	8.91	92.2	
P1006-02	NB-7-010324-E2	4	1.13	8.45	9.58	8.76	90.3	

$$\% \text{ Solid} = \frac{(C-A) * 100}{(B-A)}$$

129011

WORKLIST(Hardcopy Internal Chain)

WorkList Name : %1-010324

WorkList ID : 176906

Department : Wet-Chemistry

Date : 01-03-2024 07:50:52

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P1005-01	RBR200030	Solid	Percent Solids	Cool 4 deg C	PSEG03	O21	01/03/2024	Chemtech -SO
P1005-02	RBR200030	Solid	Percent Solids	Cool 4 deg C	PSEG03	O21	01/03/2024	Chemtech -SO
P1006-01	NB-7-010324	Solid	Percent Solids	Cool 4 deg C	PSEG05	O11	01/03/2024	Chemtech -SO
P1006-02	NB-7-010324-E2	Solid	Percent Solids	Cool 4 deg C	PSEG05	O11	01/03/2024	Chemtech -SO

Date/Time 01/03/24 16:00

Raw Sample Received by: [Signature]

Raw Sample Relinquished by: [Signature]

Date/Time 01/03/24 17:00

Raw Sample Received by: [Signature]

Raw Sample Relinquished by: [Signature]