

LB132606

WORKLIST(Hardcopy Internal Chain)

WorkList Name : TOC W PT -09262024

WorkList ID : 183912

Department : Wet-Chemistry

Date : 09-26-2024 11:53:16

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P3848-04	PT-DEM-WP	Water	TOC	Conc H2SO4 to pH < 2	CHEM02	QA Of	09/03/2024	9060A

Date/Time 09.26.2024 , 12:00

Raw Sample Received by: NF(WC)

Raw Sample Relinquished by: SJ(QAO)

Date/Time

Raw Sample Received by:

Raw Sample Relinquished by:

LB132606

WORKLIST(Hardcopy Internal Chain)

WorkList Name : TOC W-09262024

WorkList ID : 183854

Department : Wet-Chemistry

Date : 09-26-2024 14:28:25

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
P4180-02	5602-75-001-NEUTRALIZATION	Water	TOC	Conc H2SO4 to pH < 2	SCIE01	J41	09/24/2024	9060A
P4194-01	MANHOLE-119-KEARNY	Water	TOC	Conc H2SO4 to pH < 2	PSEG03	J51	09/25/2024	9060A
P4209-02	DRUM-2	Water	TOC	Conc H2SO4 to pH < 2	PSEG03	J41	09/26/2024	9060A

Date/Time 09.26.2024, 15:06

Raw Sample Received by: NF(wc)

Raw Sample Relinquished by: L.C. (sm)

Date/Time 09.26.2024, 17:00

Raw Sample Received by: L.C. (sm)

Raw Sample Relinquished by: NF(wc)