



PERCENT SOLID

Supervisor: Iwona
Analyst: jignesh
Date: 10/14/2025

OVENTEMP IN Celsius(°C): 107
Time IN: 17:10
In Date: 10/13/2025
Weight Check 1.0g: 1.00
Weight Check 10g: 10.00
OvenID: M OVEN#1

OVENTEMP OUT Celsius(°C): 104
Time OUT: 08:15
Out Date: 10/14/2025
Weight Check 1.0g: 1.00
Weight Check 10g: 10.00
BalanceID: M SC-4
Thermometer ID: % SOLID-OVEN

QC:LB137511

Lab ID	Client SampleID	Dish #	Dish Wt (g) (A)	Sample Wt (g)	Dish + Sample Wt (g) (B)	Dish+Dry Sample Wt (g) (C)	% Solid	Comments
Q3337-01	LAYDOWN-YARD-1	1	1.14	10.28	11.42	10.07	86.9	
Q3337-03	LAYDOWN-YARD-2	2	1.13	10.61	11.74	10.33	86.7	
Q3338-01	50696	3	1.00	1.00	2.00	2.00	100.0	WIPE SAMPLE
Q3338-02	50697	4	1.00	1.00	2.00	2.00	100.0	WIPE SAMPLE
Q3338-03	50698-WIPE	5	1.00	1.00	2.00	2.00	100.0	WIPE SAMPLE
Q3338-04	50699	6	1.00	1.00	2.00	2.00	100.0	WIPE SAMPLE
Q3338-05	50698-CT	7	1.00	1.00	2.00	2.00	100.0	TAR SAMPLE

$$\% \text{ Solid} = \frac{(C-A) * 100}{(B-A)}$$

WORKLIST(Hardcopy Internal Chain)

137511

WorkList Name : %1-101325 WorkList ID : 192412 Department : Wet-Chemistry Date : 10-13-2025 09:20:22

Sample	Customer Sample	Matrix	Test	Preservative	Customer	Raw Sample Storage Location	Collect Date	Method
Q3337-01	LAYDOWN-YARD-1	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO
Q3337-03	LAYDOWN-YARD-2	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO
Q3338-01	50696	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO
Q3338-02	50697	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO
Q3338-03	50698-WIPE	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO
Q3338-04	50699	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO
Q3338-05	50698-CT	Solid	Percent Solids	Cool 4 deg C	PSEG03	D31	10/13/2025	Chemtech -SO

Date/Time 10/13/25 15:00
 Raw Sample Received by: [Signature]
 Raw Sample Relinquished by: [Signature]

Date/Time 10/13/25 17:20
 Raw Sample Received by: [Signature]
 Raw Sample Relinquished by: [Signature]